

ION BLOCK ROCKER MAX



CAUTION
RISK OF ELECTRIC SHOCK
DO NOT OPEN



WARNING: SHOCK HAZARD - DO NOT OPEN
AVIS: RISQUE DE CHOC ELECTRIQUE - NE PAS OUVRIR
WARNING: TO REDUCE THE RISK OF FIRE OR ELECTRIC SHOCK
DO NOT EXPOSE THIS EQUIPMENT TO RAIN OR MOISTURE
AVIS: NE PAS EXPOSER CE MATERIEL A LA PLUIE OU L'HUMIDITE
AFIN DE REDUIRE LE RISQUE D'INFLAMMATION OU DE CHOC ELÉCTRIQUE

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES, OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION.

- a. Denmark: Apparatets stikprop skal tilsluttes en stikkontakt med jord, som giver forbindelse til stikproppens jord
- b. Finland (Suomi): Laitte on liitettävä suojamaadoituskoskettimilla varustettuun pistorasiaan
- c. Norway (Norge): Apparatet må tilkoples jordet stikkontakt
- d. Sweden (Sverige): Apparatet skall anslutas till jordat uttag

MADE IN CHINA



Intertek
3043205

CONFORMS TO ANSI/UL
STD. 60065
CERTIFIED TO CAN/CSA
STD. C22.2 NO.60065

iPA76C2



CAN ICES-3 (B)/NMB-3(B)

FCC ID: 2AB3E-IPA76C2

IC: 10541A-IPA76C2

