

Long Range Solutions, LLC

Add: 9525 Forrest View Street, Dallas, Texas 75243 United States

Tel: 9722350670 Fax: 9722350890

Email: [rpinell2015@yahoo.com](mailto:rpinell2015@yahoo.com)

## **Justification Letter**

Date: 2022-04-26

FEDERAL COMMUNICATIONS COMMISSION

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

FCC ID: 2AB6OTX9561

Model number: TX-9561EZ, TX-9561MT

Dear Sir/Madam,

We, Long Range Solutions, LLC, acknowledge that this device will not be marketed to USA users with the frequency band which is not allowed by rule part 90 and it is a violation of FCC rules if this device is operated on unauthorized frequencies inside the U.S.A.

This equipment meets the requirements of the FCC Rules, Parts 90.203(e) and (g), as applicable. Programming of this products transmit frequencies can be performed ONLY by the manufacturer or by service or by maintenance personal.

The operator can't program transmit frequencies using the equipment's external operation controls. This is to certify that the requirements of 47 CFR Part 90.203(j)(4) and (5) spectrum efficiency are met by the Long Range Solutions, LLC as demonstrated by the tests conducted on the sample radio provided.

The tests show that the 4FSK data rate is in accordance with ETSI TS 102 361-1, that is 9600 bits per second in a 12.5 kHz bandwidth to satisfy the data rate requirement of 4800 bits per second per 6.25 kHz of channel bandwidth (7K60F1D emissions).

Sincerely Yours,



Robert Pinell

Chief Officer