



Band2-15MHz-QPSK-18675-1RB#0-Range1:30~1000MHz




18:00:10 13.01.2022

Band2-15MHz-QPSK-18675-1RB#0-Range2:1000~2000MHz




18:00:21 13.01.2022

Band2-15MHz-QPSK-18675-1RB#0-Range3:2000~20000MHz




18:00:32 13.01.2022

Band2-15MHz-QPSK-18900-1RB#0-Range1:30~100MHz




18:01:19 13.01.2022


Band2-15MHz-QPSK-18900-1RB#0-Range2:1000~2000MHz




Band2-15MHz-QPSK-18900-1RB#0-Range3:2000~20000MHz




Band2-15MHz-QPSK-19125-1RB#0-Range1:30~1000MHz



Band2-15MHz-QPSK-19125-1RB#0-Range2:1000~2000MHz




### Band2-15MHz-QPSK-19125-1RB#0-Range3:2000~20000MHz




18:02:50 13.01.2022

### Band2-15MHz-16QAM-18675-1RB#0-Range1:30~1000MHz




18:00:44 13.01.2022

Band2-15MHz-16QAM-18675-1RB#0-Range2:1000~2000MHz




Band2-15MHz-16QAM-18675-1RB#0-Range3:2000~20000MHz







Band2-15MHz-16QAM-18900-1RB#0-Range1:30~1000MHz



Band2-15MHz-16QAM-18900-1RB#0-Range2:1000~2000MHz




Band2-15MHz-16QAM-18900-1RB#0-Range3:2000~20000MHz



18:02:14 13.01.2022


Band2-15MHz-16QAM-19125-1RB#0-Range1:30~1000MHz




18:03:02 13.01.2022




Band2-15MHz-16QAM-19125-1RB#0-Range2:1000~2000MHz



Band2-15MHz-16QAM-19125-1RB#0-Range3:2000~20000MHz




Band2-20MHz-QPSK-18700-1RB#0-Range1:30~1000MHz




18:10:40 13.01.2022

Band2-20MHz-QPSK-18700-1RB#0-Range2:1000~2000MHz




18:10:50 13.01.2022

Band2-20MHz-QPSK-18700-1RB#0-Range3:2000~20000MHz




18:11:01 13.01.2022

Band2-20MHz-QPSK-18900-1RB#0-Range1:30~100MHz




18:11:48 13.01.2022

Band2-20MHz-QPSK-18900-1RB#0-Range2:1000~2000MHz




18:11:59 13.01.2022

Band2-20MHz-QPSK-18900-1RB#0-Range3:2000~20000MHz




18:12:09 13.01.2022

Band2-20MHz-QPSK-19100-1RB#0-Range1:30~1000MHz




18:12:57 13.01.2022

Band2-20MHz-QPSK-19100-1RB#0-Range2:1000~2000MHz




18:13:08 13.01.2022

Band2-20MHz-QPSK-19100-1RB#0-Range3:2000~20000MHz



18:13:18 13.01.2022


Band2-20MHz-16QAM-18700-1RB#0-Range1:30~1000MHz




18:11:13 13.01.2022




Band2-20MHz-16QAM-18700-1RB#0-Range2:1000~2000MHz




Band2-20MHz-16QAM-18700-1RB#0-Range3:2000~20000MHz




Band2-20MHz-16QAM-18900-1RB#0-Range1:30~1000MHz



Band2-20MHz-16QAM-18900-1RB#0-Range2:1000~2000MHz




Band2-20MHz-16QAM-18900-1RB#0-Range3:2000~20000MHz




18:12:43 13.01.2022

Band2-20MHz-16QAM-19100-1RB#0-Range1:30~1000MHz




18:13:31 13.01.2022

Band2-20MHz-16QAM-19100-1RB#0-Range2:1000~2000MHz




18:13:41 13.01.2022

Band2-20MHz-16QAM-19100-1RB#0-Range3:2000~20000MHz




18:13:52 13.01.2022

Band4-1.4MHz-QPSK-19957-1RB#0-Range1:30~1000MHz




11:57:31 24.08.2021

Band4-1.4MHz-QPSK-19957-1RB#0-Range2:1000~2000MHz




11:57:40 24.08.2021

Band4-1.4MHz-QPSK-19957-1RB#0-Range3:2000~20000MHz



11:57:48 24.08.2021


Band4-1.4MHz-QPSK-20175-1RB#0-Range1:30~1000MHz



11:58:57 24.08.2021




Band4-1.4MHz-QPSK-20175-1RB#0-Range2:1000~2000MHz




11:59:06 24.08.2021

Band4-1.4MHz-QPSK-20175-1RB#0-Range3:2000~20000MHz




11:59:14 24.08.2021


Band4-1.4MHz-QPSK-20393-1RB#0-Range1:30~1000MHz



Band4-1.4MHz-QPSK-20393-1RB#0-Range2:1000~2000MHz




Band4-1.4MHz-QPSK-20393-1RB#0-Range3:2000~20000MHz




12:00:40 24.08.2021

Band4-1.4MHz-16QAM-19957-1RB#0-Range1:30~1000MHz




11:58:00 24.08.2021

Band4-1.4MHz-16QAM-19957-1RB#0-Range2:1000~2000MHz




11:58:09 24.08.2021

Band4-1.4MHz-16QAM-19957-1RB#0-Range3:2000~20000MHz




11:58:17 24.08.2021


Band4-1.4MHz-16QAM-20175-1RB#0-Range1:30~1000MHz



Band4-1.4MHz-16QAM-20175-1RB#0-Range2:1000~2000MHz




Band4-1.4MHz-16QAM-20175-1RB#0-Range3:2000~20000MHz



11:59:43 24.08.2021


Band4-1.4MHz-16QAM-20393-1RB#0-Range1:30~1000MHz




12:00:52 24.08.2021




Band4-1.4MHz-16QAM-20393-1RB#0-Range2:1000~2000MHz



Band4-1.4MHz-16QAM-20393-1RB#0-Range3:2000~20000MHz




Band4-3MHz-QPSK-19965-1RB#0-Range1:30~1000MHz




12:26:55 24.08.2021

Band4-3MHz-QPSK-19965-1RB#0-Range2:1000~2000MHz




12:27:04 24.08.2021

### Band4-3MHz-QPSK-19965-1RB#0-Range3:2000~20000MHz




12:27:13 24.08.2021

### Band4-3MHz-QPSK-20175-1RB#0-Range1:30~1000MHz




12:27:55 24.08.2021

Band4-3MHz-QPSK-20175-1RB#0-Range2:1000~2000MHz




12:28:04 24.08.2021

Band4-3MHz-QPSK-20175-1RB#0-Range3:2000~20000MHz




12:28:12 24.08.2021

Band4-3MHz-QPSK-20385-1RB#0-Range1:30~1000MHz




12:28:55 24.08.2021

Band4-3MHz-QPSK-20385-1RB#0-Range2:1000~2000MHz




12:29:04 24.08.2021

Band4-3MHz-QPSK-20385-1RB#0-Range3:2000~20000MHz



12:29:12 24.08.2021


Band4-3MHz-16QAM-19965-1RB#0-Range1:30~100MHz



12:27:25 24.08.2021




Band4-3MHz-16QAM-19965-1RB#0-Range2:1000~2000MHz




12:27:33 24.08.2021

Band4-3MHz-16QAM-19965-1RB#0-Range3:2000~20000MHz




12:27:42 24.08.2021

Band4-3MHz-16QAM-20175-1RB#0-Range1:30~1000MHz




12:28:24 24.08.2021

Band4-3MHz-16QAM-20175-1RB#0-Range2:1000~2000MHz




12:28:33 24.08.2021

Band4-3MHz-16QAM-20175-1RB#0-Range3:2000~20000MHz




12:28:41 24.08.2021

Band4-3MHz-16QAM-20385-1RB#0-Range1:30~100MHz




12:29:24 24.08.2021

Band4-3MHz-16QAM-20385-1RB#0-Range2:1000~2000MHz




12:29:33 24.08.2021

Band4-3MHz-16QAM-20385-1RB#0-Range3:2000~20000MHz




12:29:41 24.08.2021

Band4-5MHz-QPSK-19975-1RB#0-Range1:30~1000MHz




12:54:53 24.08.2021

Band4-5MHz-QPSK-19975-1RB#0-Range2:1000~2000MHz




12:55:02 24.08.2021

Band4-5MHz-QPSK-19975-1RB#0-Range3:2000~20000MHz



12:55:10 24.08.2021


Band4-5MHz-QPSK-20175-1RB#0-Range1:30~1000MHz




12:55:53 24.08.2021




Band4-5MHz-QPSK-20175-1RB#0-Range2:1000~2000MHz



Band4-5MHz-QPSK-20175-1RB#0-Range3:2000~20000MHz




Band4-5MHz-QPSK-20375-1RB#0-Range1:30~1000MHz




12:56:53 24.08.2021

Band4-5MHz-QPSK-20375-1RB#0-Range2:1000~2000MHz




12:57:01 24.08.2021

Band4-5MHz-QPSK-20375-1RB#0-Range3:2000~20000MHz




12:57:10 24.08.2021

Band4-5MHz-16QAM-19975-1RB#0-Range1:30~100MHz




12:55:23 24.08.2021

### Band4-5MHz-16QAM-19975-1RB#0-Range2:1000~2000MHz




12:55:31 24.08.2021

### Band4-5MHz-16QAM-19975-1RB#0-Range3:2000~20000MHz




12:55:40 24.08.2021

Band4-5MHz-16QAM-20175-1RB#0-Range1:30~1000MHz




12:56:22 24.08.2021

Band4-5MHz-16QAM-20175-1RB#0-Range2:1000~2000MHz




12:56:31 24.08.2021

Band4-5MHz-16QAM-20175-1RB#0-Range3:2000~20000MHz



12:56:39 24.08.2021


Band4-5MHz-16QAM-20375-1RB#0-Range1:30~100MHz




12:57:22 24.08.2021




Band4-5MHz-16QAM-20375-1RB#0-Range2:1000~2000MHz




Band4-5MHz-16QAM-20375-1RB#0-Range3:2000~20000MHz




Band4-10MHz-QPSK-20000-1RB#0-Range1:30~1000MHz



Band4-10MHz-QPSK-20000-1RB#0-Range2:1000~2000MHz




Band4-10MHz-QPSK-20000-1RB#0-Range3:2000~20000MHz




13:22:40 24.08.2021

Band4-10MHz-QPSK-20175-1RB#0-Range1:30~1000MHz




13:23:22 24.08.2021

Band4-10MHz-QPSK-20175-1RB#0-Range2:1000~2000MHz




13:23:31 24.08.2021

Band4-10MHz-QPSK-20175-1RB#0-Range3:2000~20000MHz




13:23:39 24.08.2021

Band4-10MHz-QPSK-20350-1RB#0-Range1:30~1000MHz




13:24:22 24.08.2021

Band4-10MHz-QPSK-20350-1RB#0-Range2:1000~2000MHz




13:24:31 24.08.2021

Band4-10MHz-QPSK-20350-1RB#0-Range3:2000~20000MHz



13:24:39 24.08.2021


Band4-10MHz-16QAM-20000-1RB#0-Range1:30~1000MHz



13:22:52 24.08.2021




Band4-10MHz-16QAM-20000-1RB#0-Range2:1000~2000MHz




13:23:01 24.08.2021

Band4-10MHz-16QAM-20000-1RB#0-Range3:2000~20000MHz




13:23:09 24.08.2021

Band4-10MHz-16QAM-20175-1RB#0-Range1:30~1000MHz




13:23:51 24.08.2021

Band4-10MHz-16QAM-20175-1RB#0-Range2:1000~2000MHz




13:24:00 24.08.2021

Band4-10MHz-16QAM-20175-1RB#0-Range3:2000~20000MHz




13:24:08 24.08.2021

Band4-10MHz-16QAM-20350-1RB#0-Range1:30~1000MHz




13:24:51 24.08.2021

Band4-10MHz-16QAM-20350-1RB#0-Range2:1000~2000MHz




13:25:00 24.08.2021

Band4-10MHz-16QAM-20350-1RB#0-Range3:2000~20000MHz




13:25:08 24.08.2021

Band4-15MHz-QPSK-20025-1RB#0-Range1:30~1000MHz




13:50:11 24.08.2021

Band4-15MHz-QPSK-20025-1RB#0-Range2:1000~2000MHz




13:50:20 24.08.2021

### Band4-15MHz-QPSK-20025-1RB#0-Range3:2000~20000MHz



13:50:28 24.08.2021


### Band4-15MHz-QPSK-20175-1RB#0-Range1:30~1000MHz



13:51:11 24.08.2021




Band4-15MHz-QPSK-20175-1RB#0-Range2:1000~2000MHz




13:51:20 24.08.2021

Band4-15MHz-QPSK-20175-1RB#0-Range3:2000~20000MHz




13:51:28 24.08.2021

Band4-15MHz-QPSK-20325-1RB#0-Range1:30~1000MHz




13:52:12 24.08.2021

Band4-15MHz-QPSK-20325-1RB#0-Range2:1000~2000MHz




13:52:20 24.08.2021

Band4-15MHz-QPSK-20325-1RB#0-Range3:2000~20000MHz




13:52:29 24.08.2021

Band4-15MHz-16QAM-20025-1RB#0-Range1:30~1000MHz




13:50:41 24.08.2021


### Band4-15MHz-16QAM-20025-1RB#0-Range2:1000~2000MHz



### Band4-15MHz-16QAM-20025-1RB#0-Range3:2000~20000MHz




Band4-15MHz-16QAM-20175-1RB#0-Range1:30~1000MHz




13:51:41 24.08.2021

Band4-15MHz-16QAM-20175-1RB#0-Range2:1000~2000MHz




13:51:50 24.08.2021

### Band4-15MHz-16QAM-20175-1RB#0-Range3:2000~20000MHz



13:51:58 24.08.2021


### Band4-15MHz-16QAM-20325-1RB#0-Range1:30~1000MHz



13:52:41 24.08.2021




Band4-15MHz-16QAM-20325-1RB#0-Range2:1000~2000MHz




13:52:50 24.08.2021

Band4-15MHz-16QAM-20325-1RB#0-Range3:2000~20000MHz




13:52:58 24.08.2021


Band4-20MHz-QPSK-20050-1RB#0-Range1:30~1000MHz



Band4-20MHz-QPSK-20050-1RB#0-Range2:1000~2000MHz




Band4-20MHz-QPSK-20050-1RB#0-Range3:2000~20000MHz




14:18:36 24.08.2021

Band4-20MHz-QPSK-20175-1RB#0-Range1:30~1000MHz




14:19:19 24.08.2021

Band4-20MHz-QPSK-20175-1RB#0-Range2:1000~2000MHz




14:19:28 24.08.2021

Band4-20MHz-QPSK-20175-1RB#0-Range3:2000~20000MHz




14:19:36 24.08.2021

Band4-20MHz-QPSK-20300-1RB#0-Range1:30~1000MHz




14:20:19 24.08.2021

Band4-20MHz-QPSK-20300-1RB#0-Range2:1000~2000MHz




14:20:28 24.08.2021

Band4-20MHz-QPSK-20300-1RB#0-Range3:2000~20000MHz



14:20:36 24.08.2021


Band4-20MHz-16QAM-20050-1RB#0-Range1:30~1000MHz



14:18:48 24.08.2021




Band4-20MHz-16QAM-20050-1RB#0-Range2: 1000~2000MHz




14:18:57 24.08.2021

Band4-20MHz-16QAM-20050-1RB#0-Range3: 2000~20000MHz




14:19:05 24.08.2021


Band4-20MHz-16QAM-20175-1RB#0-Range1:30~1000MHz



Band4-20MHz-16QAM-20175-1RB#0-Range2:1000~2000MHz




Band4-20MHz-16QAM-20175-1RB#0-Range3:2000~20000MHz




14:20:05 24.08.2021

Band4-20MHz-16QAM-20300-1RB#0-Range1:30~1000MHz




14:20:48 24.08.2021


Band4-20MHz-16QAM-20300-1RB#0-Range2: 1000~2000MHz



Band4-20MHz-16QAM-20300-1RB#0-Range3: 2000~20000MHz




Band5-1.4MHz-QPSK-20407-1RB#0-Range1:30~1000MHz




15:09:18 24.08.2021

Band5-1.4MHz-QPSK-20407-1RB#0-Range2:1000~10000MHz




15:09:27 24.08.2021

Band5-1.4MHz-QPSK-20525-1RB#0-Range1:30~1000MHz



15:10:01 24.08.2021


Band5-1.4MHz-QPSK-20525-1RB#0-Range2:1000~10000MHz




15:10:10 24.08.2021




Band5-1.4MHz-QPSK-20643-1RB#0-Range1:30~1000MHz



Band5-1.4MHz-QPSK-20643-1RB#0-Range2:1000~10000MHz




Band5-1.4MHz-16QAM-20407-1RB#0-Range1:30~1000MHz




15:09:39 24.08.2021

Band5-1.4MHz-16QAM-20407-1RB#0-Range2:1000~10000MHz




15:09:48 24.08.2021

Band5-1.4MHz-16QAM-20525-1RB#0-Range1:30~1000MHz




15:10:22 24.08.2021

Band5-1.4MHz-16QAM-20525-1RB#0-Range2:1000~10000MHz




15:10:30 24.08.2021

Band5-1.4MHz-16QAM-20643-1RB#0-Range1:30~1000MHz




15:11:05 24.08.2021

Band5-1.4MHz-16QAM-20643-1RB#0-Range2:1000~10000MHz




15:11:13 24.08.2021

Band5-3MHz-QPSK-20415-1RB#0-Range1:30~1000MHz




15:36:02 24.08.2021

Band5-3MHz-QPSK-20415-1RB#0-Range2:1000~10000MHz




15:36:11 24.08.2021

Band5-3MHz-QPSK-20525-1RB#0-Range1:30~1000MHz



15:36:45 24.08.2021


Band5-3MHz-QPSK-20525-1RB#0-Range2:1000~10000MHz



15:36:54 24.08.2021




Band5-3MHz-QPSK-20635-1RB#0-Range1:30~1000MHz




15:37:28 24.08.2021

Band5-3MHz-QPSK-20635-1RB#0-Range2:1000~10000MHz




15:37:37 24.08.2021

Band5-3MHz-16QAM-20415-1RB#0-Range1:30~1000MHz




15:36:23 24.08.2021

Band5-3MHz-16QAM-20415-1RB#0-Range2:1000~10000MHz




15:36:32 24.08.2021

Band5-3MHz-16QAM-20525-1RB#0-Range1:30~1000MHz




15:37:06 24.08.2021

Band5-3MHz-16QAM-20525-1RB#0-Range2:1000~10000MHz




15:37:14 24.08.2021

Band5-3MHz-16QAM-20635-1RB#0-Range1:30~1000MHz




15:37:49 24.08.2021

Band5-3MHz-16QAM-20635-1RB#0-Range2:1000~10000MHz




15:37:58 24.08.2021

Band5-5MHz-QPSK-20425-1RB#0-Range1:30~1000MHz




16:03:37 24.08.2021

Band5-5MHz-QPSK-20425-1RB#0-Range2:1000~10000MHz




16:03:45 24.08.2021

Band5-5MHz-QPSK-20525-1RB#0-Range1:30~1000MHz



16:04:20 24.08.2021


Band5-5MHz-QPSK-20525-1RB#0-Range2:1000~10000MHz



16:04:28 24.08.2021




Band5-5MHz-QPSK-20625-1RB#0-Range1:30~1000MHz




16:05:03 24.08.2021

Band5-5MHz-QPSK-20625-1RB#0-Range2:1000~10000MHz




16:05:11 24.08.2021


Band5-5MHz-16QAM-20425-1RB#0-Range1:30~1000MHz



Band5-5MHz-16QAM-20425-1RB#0-Range2:1000~10000MHz




Band5-5MHz-16QAM-20525-1RB#0-Range1:30~1000MHz




16:04:41 24.08.2021

Band5-5MHz-16QAM-20525-1RB#0-Range2:1000~10000MHz




16:04:49 24.08.2021

Band5-5MHz-16QAM-20625-1RB#0-Range1:30~1000MHz




16:05:24 24.08.2021

Band5-5MHz-16QAM-20625-1RB#0-Range2:1000~10000MHz




16:05:32 24.08.2021


Band5-10MHz-QPSK-20450-1RB#0-Range1:30~1000MHz



Band5-10MHz-QPSK-20450-1RB#0-Range2:1000~10000MHz




Band5-10MHz-QPSK-20525-1RB#0-Range1:30~1000MHz



16:31:23 24.08.2021


Band5-10MHz-QPSK-20525-1RB#0-Range2:1000~10000MHz



16:31:31 24.08.2021




Band5-10MHz-QPSK-20600-1RB#0-Range1:30~1000MHz




16:32:06 24.08.2021

Band5-10MHz-QPSK-20600-1RB#0-Range2:1000~10000MHz




16:32:14 24.08.2021

Band5-10MHz-16QAM-20450-1RB#0-Range1:30~1000MHz




16:31:01 24.08.2021

Band5-10MHz-16QAM-20450-1RB#0-Range2:1000~10000MHz




16:31:09 24.08.2021

Band5-10MHz-16QAM-20525-1RB#0-Range1:30~1000MHz




16:31:44 24.08.2021

Band5-10MHz-16QAM-20525-1RB#0-Range2:1000~10000MHz




16:31:52 24.08.2021

Band5-10MHz-16QAM-20600-1RB#0-Range1:30~1000MHz




16:32:27 24.08.2021

Band5-10MHz-16QAM-20600-1RB#0-Range2:1000~10000MHz




16:32:35 24.08.2021

Band7-5MHz-QPSK-20775-1RB#0-Range1:30~1000MHz




08:24:02 25.08.2021

Band7-5MHz-QPSK-20775-1RB#0-Range2:1000~3000MHz




08:24:11 25.08.2021

Band7-5MHz-QPSK-20775-1RB#0-Range3:3000~26500MHz



08:24:19 25.08.2021


Band7-5MHz-QPSK-21100-1RB#0-Range1:30~1000MHz




08:25:02 25.08.2021




Band7-5MHz-QPSK-21100-1RB#0-Range2:1000~3000MHz



Band7-5MHz-QPSK-21100-1RB#0-Range3:3000~26500MHz




Band7-5MHz-QPSK-21425-1RB#0-Range1:30~1000MHz




08:26:02 25.08.2021

Band7-5MHz-QPSK-21425-1RB#0-Range2:1000~3000MHz




08:26:10 25.08.2021

Band7-5MHz-QPSK-21425-1RB#0-Range3:3000~26500MHz




08:26:19 25.08.2021

Band7-5MHz-16QAM-20775-1RB#0-Range1:30~100MHz




08:24:31 25.08.2021


Band7-5MHz-16QAM-20775-1RB#0-Range2:1000~3000MHz




Band7-5MHz-16QAM-20775-1RB#0-Range3:3000~26500MHz




Band7-5MHz-16QAM-21100-1RB#0-Range1:30~1000MHz



Band7-5MHz-16QAM-21100-1RB#0-Range2:1000~3000MHz




Band7-5MHz-16QAM-21100-1RB#0-Range3:3000~26500MHz



08:25:48 25.08.2021

Band7-5MHz-16QAM-21425-1RB#0-Range1:30~100MHz




08:26:31 25.08.2021




Band7-5MHz-16QAM-21425-1RB#0-Range2:1000~3000MHz



Band7-5MHz-16QAM-21425-1RB#0-Range3:3000~26500MHz




Band7-10MHz-QPSK-20800-1RB#0-Range1:30~1000MHz




08:52:03 25.08.2021

Band7-10MHz-QPSK-20800-1RB#0-Range2:1000~3000MHz




08:52:12 25.08.2021

### Band7-10MHz-QPSK-20800-1RB#0-Range3:3000~26500MHz




08:52:20 25.08.2021

### Band7-10MHz-QPSK-21100-1RB#0-Range1:30~1000MHz




08:53:03 25.08.2021


Band7-10MHz-QPSK-21100-1RB#0-Range2:1000~3000MHz



Band7-10MHz-QPSK-21100-1RB#0-Range3:3000~26500MHz




Band7-10MHz-QPSK-21400-1RB#0-Range1:30~1000MHz




08:54:03 25.08.2021

Band7-10MHz-QPSK-21400-1RB#0-Range2:1000~3000MHz




08:54:12 25.08.2021

Band7-10MHz-QPSK-21400-1RB#0-Range3:3000~26500MHz



08:54:20 25.08.2021


Band7-10MHz-16QAM-20800-1RB#0-Range1:30~1000MHz




08:52:32 25.08.2021




Band7-10MHz-16QAM-20800-1RB#0-Range2:1000~3000MHz



Band7-10MHz-16QAM-20800-1RB#0-Range3:3000~26500MHz




Band7-10MHz-16QAM-21100-1RB#0-Range1:30~1000MHz



08:53:32 25.08.2021

Band7-10MHz-16QAM-21100-1RB#0-Range2:1000~3000MHz



08:53:41 25.08.2021