

Appendix II

Internal Photographs

Open View of EUT



Internal View of EUT-1



Internal View of EUT-2



Page 3 of 26 UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

.




Detail View of EUT-2



Page 4 of 26




Detail View of EUT-4




UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Page 5 of 26




Detail View of EUT-6



Detail View of EUT-7

Page 6 of 26




Detail View of EUT-8



Page 7 of 26




Detail View of EUT-10






Detail View of EUT-12



Detail View of EUT-13



Detail View of EUT-14






Detail View of EUT-16





UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Page 11 of 26




Detail View of EUT-18







Detail View of EUT-20



Page 13 of 26




Detail View of EUT-22






Detail View of EUT-24



Page 15 of 26




Detail View of EUT-26





Page 16 of 26

Detail View of EUT-27




Detail View of EUT-28







Detail View of EUT-30



Page 18 of 26




Detail View of EUT-32






Detail View of EUT-34






Detail View of EUT-36





UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Page 21 of 26




Detail View of EUT-38






Detail View of EUT-40




UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Page 23 of 26


Detail View of EUT-41




Detail View of EUT-42




Page 24 of 26



Detail View of EUT-44



Page 25 of 26



Detail View of EUT-46



Page 26 of 26