









Band12-10MHz-QPSK-23130-50RB#0-PASS

Band12-10MHz-QPSK-23130-1RB#49-PASS





Band12-10MHz-16QAM-23060-1RB#0-PASS

Band12-10MHz-16QAM-23060-50RB#0-PASS





Band12-10MHz-16QAM-23060-1RB#49-PASS

Band12-10MHz-16QAM-23130-1RB#0-PASS





Band12-10MHz-16QAM-23130-50RB#0-PASS

Band12-10MHz-16QAM-23130-1RB#49-PASS





Band17-5MHz-QPSK-23755-1RB#0-PASS

Band17-5MHz-QPSK-23755-25RB#0-PASS




Band17-5MHz-QPSK-23755-1RB#24-PASS


Band17-5MHz-QPSK-23825-1RB#0-PASS




Band17-5MHz-QPSK-23825-25RB#0-PASS




Band17-5MHz-QPSK-23825-1RB#24-PASS



Band17-5MHz-16QAM-23755-1RB#0-PASS





Band17-5MHz-16QAM-23755-25RB#0-PASS




Band17-5MHz-16QAM-23755-1RB#24-PASS


Band17-5MHz-16QAM-23825-1RB#0-PASS




Band17-5MHz-16QAM-23825-25RB#0-PASS



Band17-5MHz-16QAM-23825-1RB#24-PASS



Band17-10MHz-QPSK-23780-1RB#0-PASS





Band17-10MHz-QPSK-23780-50RB#0-PASS




Band17-10MHz-QPSK-23780-1RB#49-PASS


Band17-10MHz-QPSK-23800-1RB#0-PASS




Band17-10MHz-QPSK-23800-50RB#0-PASS



Band17-10MHz-QPSK-23800-1RB#49-PASS



Band17-10MHz-16QAM-23780-1RB#0-PASS





Band17-10MHz-16QAM-23780-50RB#0-PASS




Band17-10MHz-16QAM-23780-1RB#49-PASS


Band17-10MHz-16QAM-23800-1RB#0-PASS




Band17-10MHz-16QAM-23800-50RB#0-PASS




Band17-10MHz-16QAM-23800-1RB#49-PASS




Band38-5MHz-QPSK-37775-1RB#0-PASS



Band38-5MHz-QPSK-37775-25RB#0-PASS




Band38-5MHz-QPSK-37775-1RB#0-PASS




13:15:17 17.09.2024

Band38-5MHz-QPSK-37775-25RB#0-PASS




13:31:28 17.09.2024

Band38-5MHz-QPSK-37775-1RB#24-PASS




13:38:22 17.09.2024

Band38-5MHz-QPSK-38225-1RB#0-PASS




13:34:36 17.09.2024

Band38-5MHz-QPSK-38225-25RB#0-PASS



13:40:47 17.09.2024


Band38-5MHz-QPSK-38225-1RB#24-PASS




13:37:41 17.09.2024

Band38-5MHz-16QAM-37775-1RB#0-PASS

Band38-5MHz-16QAM-37775-25RB#0-PASS




13:26:49 17.09.2024




13:33:00 17.09.2024

Band38-5MHz-16QAM-37775-1RB#24-PASS




13:29:55 17.09.2024

Band38-5MHz-16QAM-38225-1RB#0-PASS




13:36:08 17.09.2024

Band38-5MHz-16QAM-38225-25RB#0-PASS



13:42:19 17.09.2024



Band38-5MHz-16QAM-38225-1RB#24-PASS




13:39:14 17.09.2024

Band38-10MHz-QPSK-37800-1RB#0-PASS


Band38-10MHz-QPSK-37800-50RB#0-PASS




Band38-10MHz-QPSK-37800-1RB#49-PASS




Band38-10MHz-QPSK-38200-1RB#0-PASS



Band38-10MHz-QPSK-38200-50RB#0-PASS





Band38-10MHz-QPSK-38200-1RB#49-PASS




Band38-10MHz-16QAM-37800-1RB#0-PASS

Band38-10MHz-16QAM-37800-50RB#0-PASS



Band38-10MHz-16QAM-37800-1RB#49-PASS




Band38-10MHz-16QAM-38200-1RB#0-PASS



Band38-10MHz-16QAM-38200-50RB#0-PASS




Band38-10MHz-16QAM-38200-1RB#49-PASS




Band38-15MHz-QPSK-37825-1RB#0-PASS

Band38-15MHz-QPSK-37825-75RB#0-PASS




14:25:41 17.09.2024




14:31:55 17.09.2024

Band38-15MHz-QPSK-37825-1RB#74-PASS




14:28:48 17.09.2024

Band38-15MHz-QPSK-38175-1RB#0-PASS




14:35:04 17.09.2024

Band38-15MHz-QPSK-38175-75RB#0-PASS



14:41:18 17.09.2024


Band38-15MHz-QPSK-38175-1RB#74-PASS




14:38:11 17.09.2024

Band38-15MHz-16QAM-37825-1RB#0-PASS

Band38-15MHz-16QAM-37825-75RB#0-PASS




14:27:15 17.09.2024




14:33:29 17.09.2024

Band38-15MHz-16QAM-37825-1RB#74-PASS




14:30:22 17.09.2024

Band38-15MHz-16QAM-38175-1RB#0-PASS




14:36:38 17.09.2024

Band38-15MHz-16QAM-38175-75RB#0-PASS



14:42:52 17.09.2024


Band38-15MHz-16QAM-38175-1RB#74-PASS




14:39:45 17.09.2024

Band38-20MHz-QPSK-37850-1RB#0-PASS

Band38-20MHz-QPSK-37850-100RB#0-PASS




14:54:57 17.09.2024




15:01:11 17.09.2024

Band38-20MHz-QPSK-37850-1RB#99-PASS




14:58:04 17.09.2024

Band38-20MHz-QPSK-38150-1RB#0-PASS




15:04:20 17.09.2024

Band38-20MHz-QPSK-38150-100RB#0-PASS



15:10:34 17.09.2024


Band38-20MHz-QPSK-38150-1RB#99-PASS




15:07:27 17.09.2024

Band38-20MHz-16QAM-37850-1RB#0-PASS

Band38-20MHz-16QAM-37850-100RB#0-PASS




14:56:31 17.09.2024




15:02:45 17.09.2024

Band38-20MHz-16QAM-37850-1RB#99-PASS




14:59:38 17.09.2024

Band38-20MHz-16QAM-38150-1RB#0-PASS




15:05:54 17.09.2024

Band38-20MHz-16QAM-38150-100RB#0-PASS




15:12:09 17.09.2024

Band38-20MHz-16QAM-38150-1RB#99-PASS




15:09:01 17.09.2024

40(2305-2315)-5MHz-QPSK-38725-1RB#0-PASS




40(2305-2315)-5MHz-QPSK-38725-25RB#0-PASS

40(2305-2315)-5MHz-QPSK-38725-1RB#24-PASS




16:43:59 17.09.2024




16:35:52 17.09.2024

40(2305-2315)-5MHz-QPSK-38775-1RB#0-PASS

40(2305-2315)-5MHz-QPSK-38775-25RB#0-PASS




16:51:09 17.09.2024




17:08:23 17.09.2024

40(2305-2315)-5MHz-QPSK-38775-1RB#24-PASS

40(2305-2315)-5MHz-16QAM-38725-1RB#0-PASS




17:00:16 17.09.2024




16:31:48 17.09.2024

40(2305-2315)-5MHz-16QAM-38725-25RB#0-PASS

40(2305-2315)-5MHz-16QAM-38725-1RB#24-PASS




16:48:03 17.09.2024




16:39:56 17.09.2024

40(2305-2315)-5MHz-16QAM-38775-1RB#0-PASS

40(2305-2315)-5MHz-16QAM-38775-25RB#0-PASS




16:56:12 17.09.2024




17:12:27 17.09.2024

40(2305-2315)-5MHz-16QAM-38775-1RB#24-PASS

40(2305-2315)-10MHz-QPSK-38750-1RB#0-PASS




17:04:20 17.09.2024




17:27:27 17.09.2024

40(2305-2315)-10MHz-QPSK-38750-50RB#0-PASS




23:39:05 17.09.2024

40(2305-2315)-10MHz-QPSK-38750-1RB#49-PASS




17:35:34 17.09.2024

40(2305-2315)-10MHz-16QAM-38750-1RB#0-PASS



17:31:30 17.09.2024

40(2305-2315)-10MHz-16QAM-38750-50RB#0-PASS



23:43:09 17.09.2024

40(2305-2315)-10MHz-16QAM-38750-1RB#49-PASS

40(2350-2360)-5MHz-QPSK-39175-1RB#0-PASS