
9. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)



Page 52 of 58




RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)




Page 53 of 58




RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION





Page 54 of 58






Page 55 of 58






Page 56 of 58



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB AND LAPTOP



Page 57 of 58



END OF REPORT

UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.

Page 58 of 58