


# 11. SETUP PHOTOS

### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




# RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)







Page 55 of 62


### RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz) - WITH METAL WRISTBAND







# **RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)**






### RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz) - WITH METAL WRISTBAND






## RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION








Page 59 of 62



# $\frac{\text{RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION - WITH METAL}{\text{WRISTBAND}}$







**END OF REPORT**