

## 10.4 Setup Photographs:




Intertek

30-1000MHz



Intertek

## Report Number: 102172761BOX-001



Intertek

18-25GHz Hand scans