

# AFC DUT Compliance Test Report

## DUT Information

---

<b>AFC DUT System</b>	Standard Power AP with Proxy
<b>DUT Vendor Name</b>	Tarana
<b>DUT Product Model</b>	BN

## Test Result

---

<b>FCC Requirements</b>	<b>TestCaseName</b>	<b>Test Result</b>
15.407(k)(8)(i), 15.407(k)(8)(ii), 15.407(k)(9)(i)	<a href="#">CT_AFC_SP_AP_AFCDU34_Channel_10624_1(Unsuccessful spectrum access update)</a>	PASS

## Test Measurements

---

**TestCaseName:** CT\_AFC\_SP\_AP\_AFCDU34\_Channel\_10624\_1 (Unsuccessful spectrum access update)  
**TestResult:** PASS  
**Band:** 6GHz

Measurements Name	Description	Value	Validation Result
AFC_DUT_SP_OPERATION	AFC DUT transmit with standard power in the band before the Spectrum Inquiry Response	false	PASS
AFC_DUT_SEND_SPECTRUM_INQUIRYREQUEST	AFC DUT sends an Available Spectrum Inquiry Request	true	PASS
AFC_DUT_SPECTRUM_INQUIRYREQUEST_VALID_1	Valid mandatory registration information	true	PASS
AFC_DUT_CONFORM_SPECTRUM_INQUIRYRESPONSE_1	AFC DUT conforms to the conditions in Spectrum Response (36.0 dBm EIRP) on channel 67 bandwidth 20.	true	PASS
AFC_DUT_SPECTRUM_INQUIRYREQUEST_VALID_2	Valid mandatory registration information	true	PASS
AFC_DUT_CONFORM_SPECTRUM_INQUIRYRESPONSE_2	AFC DUT conforms to the conditions in the Spectrum Inquiry Response	true	PASS