
## 1. External Photograph of EUT

Brand Name: SOUNDHAWK / Model Name: SHK001 / Marketing Name: Smart Listening System




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3-WM1 Page Number : 1 of 22

Report No.: EP442473-01




Brand Name: SOUNDHAWK / Model Name: SHK001 / Marketing Name: Smart Listening System



Page Number : 2 of 22

Report No.: EP442473-01







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3-WM1

: 3 of 22 Page Number

Report No.: EP442473-01





Remark: There have several color case for EUT, and the test result is not affected thus all of those are identical on electrically.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3-WM1 Page Number : 4 of 22

Report Issued Date : Sep. 22, 2014 : Rev. 01 Report Version

## 2. Photograph of Accessory

Brand Name: SOUNDHAWK / Model Name: SHK001 / Marketing Name: Smart Listening System

Specification of Accessory		
AC Adapter	Brand Name	soundhawk
	Model Name	C5010-A08N
Battery	Brand Name	McNair
	Model Name	MLP371030
USB Cable	Brand Name	NWING
	Model Name	CUND004B-T336W-EH
BT HeadSet	Brand Name	SOUNDHAWK
	Model Name	SHK001
Charging Case	<b>Brand Name</b>	SOUNDHAWK
	<b>Model Name</b>	SHK001

## Remark:

- 1. For accessories equipped with this EUT, please refer to the following photos.
- 2. There have several color case for BT HeadSet, and the test result is not affected thus all of those are identical on electrically.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3-WM1 Page Number : 5 of 22
Report Issued Date : Sep. 22, 2014

Report No.: EP442473-01

Report Version : Rev. 01



Brand Name: SOUNDHAWK / Model Name: SHK001 / Marketing Name: Smart Listening System



Page Number : 6 of 22

Report No.: EP442473-01

Report Issued Date : Sep. 22, 2014 : Rev. 01 Report Version







Page Number : 7 of 22

Report No.: EP442473-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3-WM1 Page Number : 8 of 22


Report No.: EP442473-01

Report Issued Date : Sep. 22, 2014

: Rev. 01 Report Version




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3-WM1 Page Number : 9 of 22



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3-WM1 Page Number : 10 of 22 Report Issued Date : Sep. 22, 2014

Report Version : Rev. 01



Page Number : 11 of 22







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3-WM1 Page Number : 12 of 22 Report Issued Date : Sep. 22, 2014

Report No.: EP442473-01

Report Version : Rev. 01




Page Number : 13 of 22
Report Issued Date : Sep. 22, 2014
Report Version : Rev. 01



Page Number : 14 of 22 Report Issued Date : Sep. 22, 2014 Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ABW3-WM1 Page Number : 15 of 22 Report Issued Date : Sep. 22, 2014

Report No.: EP442473-01

Report Version : Rev. 01