





























































Band Edge

Condition	Mode	Frequency (MHz)	Antenna	Max Value (dBc)	Limit (dBc)	Verdict
NVNT	ac20	5500	Ant1	-38.18	-27	Pass
NVNT	ac20	5700	Ant1	-36.92	-27	Pass
NVNT	ac20	5500	Ant2	-38.26	-27	Pass
NVNT	ac20	5700	Ant2	-36.82	-27	Pass
NVNT	ac20	5500	Ant3	-38.98	-27	Pass
NVNT	ac20	5700	Ant3	-37.2	-27	Pass
NVNT	ac20	5500	Ant4	-38.35	-27	Pass
NVNT	ac20	5700	Ant4	-38.19	-27	Pass
NVNT	ac40	5510	Ant1	-37.87	-27	Pass
NVNT	ac40	5670	Ant1	-37.18	-27	Pass
NVNT	ac40	5510	Ant2	-37.48	-27	Pass
NVNT	ac40	5670	Ant2	-38.07	-27	Pass
NVNT	ac40	5510	Ant3	-39.27	-27	Pass
NVNT	ac40	5670	Ant3	-38.17	-27	Pass
NVNT	ac40	5510	Ant4	-39.72	-27	Pass
NVNT	ac40	5670	Ant4	-37.98	-27	Pass
NVNT	ac80	5530	Ant1	-37.94	-27	Pass
NVNT	ac80	5610	Ant1	-36.58	-27	Pass
NVNT	ac80	5530	Ant2	-37.19	-27	Pass
NVNT	ac80	5610	Ant2	-38.9	-27	Pass
NVNT	ac80	5530	Ant3	-39.16	-27	Pass
NVNT	ac80	5610	Ant3	-38.12	-27	Pass
NVNT	ac80	5530	Ant4	-40.27	-27	Pass
NVNT	ac80	5610	Ant4	-39.06	-27	Pass
NVNT	ac160	5570	Ant1	-37.6	-27	Pass
NVNT	ac160	5570	Ant2	-37.4	-27	Pass
NVNT	ac160	5570	Ant3	-39.28	-27	Pass
NVNT	ac160	5570	Ant4	-38.73	-27	Pass
NVNT	ax160	5570	Ant1	-37.91	-27	Pass
NVNT	ax160	5570	Ant2	-37.04	-27	Pass
NVNT	ax160	5570	Ant3	-37.66	-27	Pass
NVNT	ax160	5570	Ant4	-38.11	-27	Pass
NVNT	ax20	5500	Ant1	-37.85	-27	Pass
NVNT	ax20	5700	Ant1	-36.74	-27	Pass
NVNT	ax20	5500	Ant2	-37.78	-27	Pass
NVNT	ax20	5700	Ant2	-37.32	-27	Pass
NVNT	ax20	5500	Ant3	-38.19	-27	Pass
NVNT	ax20	5700	Ant3	-37.53	-27	Pass
NVNT	ax20	5500	Ant4	-39.36	-27	Pass
NVNT	ax20	5700	Ant4	-38.55	-27	Pass

NVNT	ax40	5510	Ant1	-37.19	-27	Pass
NVNT	ax40	5670	Ant1	-35.99	-27	Pass
NVNT	ax40	5510	Ant2	-36.83	-27	Pass
NVNT	ax40	5670	Ant2	-31.29	-27	Pass
NVNT	ax40	5510	Ant3	-38.23	-27	Pass
NVNT	ax40	5670	Ant3	-37.48	-27	Pass
NVNT	ax40	5510	Ant4	-39.79	-27	Pass
NVNT	ax40	5670	Ant4	-38.53	-27	Pass
NVNT	ax80	5530	Ant1	-38.01	-27	Pass
NVNT	ax80	5610	Ant1	-39.17	-27	Pass
NVNT	ax80	5530	Ant2	-37.91	-27	Pass
NVNT	ax80	5610	Ant2	-38.83	-27	Pass
NVNT	ax80	5530	Ant3	-38.42	-27	Pass
NVNT	ax80	5610	Ant3	-38.46	-27	Pass
NVNT	ax80	5530	Ant4	-40.04	-27	Pass
NVNT	ax80	5610	Ant4	-39.87	-27	Pass
NVNT	ac20	5500	Ant5	-36.83	-27	Pass
NVNT	ac20	5700	Ant5	-35.77	-27	Pass
NVNT	ac20	5500	Ant6	-36.4	-27	Pass
NVNT	ac20	5700	Ant6	-36.49	-27	Pass
NVNT	ac20	5500	Ant7	-36.67	-27	Pass
NVNT	ac20	5700	Ant7	-37.78	-27	Pass
NVNT	ac20	5500	Ant8	-39.94	-27	Pass
NVNT	ac20	5700	Ant8	-38.11	-27	Pass
NVNT	ac40	5510	Ant5	-36.39	-27	Pass
NVNT	ac40	5670	Ant5	-35.72	-27	Pass
NVNT	ac40	5510	Ant6	-35.36	-27	Pass
NVNT	ac40	5670	Ant6	-35.82	-27	Pass
NVNT	ac40	5510	Ant7	-36.99	-27	Pass
NVNT	ac40	5670	Ant7	-37	-27	Pass
NVNT	ac40	5510	Ant8	-39.96	-27	Pass
NVNT	ac40	5670	Ant8	-38.43	-27	Pass
NVNT	ac80	5530	Ant5	-36.56	-27	Pass
NVNT	ac80	5610	Ant5	-37.31	-27	Pass
NVNT	ac80	5530	Ant6	-36.01	-27	Pass
NVNT	ac80	5610	Ant6	-37.91	-27	Pass
NVNT	ac80	5530	Ant7	-37.12	-27	Pass
NVNT	ac80	5610	Ant7	-38.81	-27	Pass
NVNT	ac80	5530	Ant8	-39.45	-27	Pass
NVNT	ac80	5610	Ant8	-40.24	-27	Pass
NVNT	ac160	5570	Ant5	-32.14	-27	Pass
NVNT	ac160	5570	Ant6	-35.84	-27	Pass
NVNT	ac160	5570	Ant7	-35.68	-27	Pass
NVNT	ac160	5570	Ant8	-38.62	-27	Pass

NVNT	ax160	5570	Ant5	-34.98	-27	Pass
NVNT	ax160	5570	Ant6	-35.01	-27	Pass
NVNT	ax160	5570	Ant7	-38.61	-27	Pass
NVNT	ax160	5570	Ant8	-38.94	-27	Pass
NVNT	ax20	5500	Ant5	-36.37	-27	Pass
NVNT	ax20	5700	Ant5	-35.52	-27	Pass
NVNT	ax20	5500	Ant6	-36.48	-27	Pass
NVNT	ax20	5700	Ant6	-34.58	-27	Pass
NVNT	ax20	5500	Ant7	-37.07	-27	Pass
NVNT	ax20	5700	Ant7	-36.08	-27	Pass
NVNT	ax20	5500	Ant8	-38.73	-27	Pass
NVNT	ax20	5700	Ant8	-38.25	-27	Pass
NVNT	ax40	5510	Ant5	-35.83	-27	Pass
NVNT	ax40	5670	Ant5	-29.83	-27	Pass
NVNT	ax40	5510	Ant6	-35.36	-27	Pass
NVNT	ax40	5670	Ant6	-27.53	-27	Pass
NVNT	ax40	5510	Ant7	-36.46	-27	Pass
NVNT	ax40	5670	Ant7	-32.1	-27	Pass
NVNT	ax40	5510	Ant8	-38.32	-27	Pass
NVNT	ax40	5670	Ant8	-34.61	-27	Pass
NVNT	ax80	5530	Ant5	-36.91	-27	Pass
NVNT	ax80	5610	Ant5	-37.61	-27	Pass
NVNT	ax80	5530	Ant6	-35.51	-27	Pass
NVNT	ax80	5610	Ant6	-36.13	-27	Pass
NVNT	ax80	5530	Ant7	-37.9	-27	Pass
NVNT	ax80	5610	Ant7	-39.48	-27	Pass
NVNT	ax80	5530	Ant8	-39.74	-27	Pass
NVNT	ax80	5610	Ant8	-39.45	-27	Pass













