

## KATHREIN Automotive GmbH & Co. KG, Roemerring 1, 31137 Hildesheim

December 21, 2015

To whom it may concern:

Subject: <u>Label and Location for FCC ID: 2ACC7LTECOMPB0</u>

Product Name: Compensator US
Brand: KATHREIN Automotive
Model Number: LTECOMPB0

## **Product Label (Top Side):**





## Warning Label (Bottom Side):



## ASUMER DEVICE

rovider and have your principle moviders may not consent their network. If you are THIS

e this device with app ectified by the manufac d at least 20 cm (8 in

iperating this device

or may be inaccurate for using this device.

BMW 04-01-16

6803145 - 01

Kathrein Automotive

218898-10

50110260

LTE Kompensator US


SN: 000111


Compensator US BU001

FCC ID: 2ACC7LTECOMPB0

IC: 11980A-LTECOMPB0

Portugal





B/M/M// 04-01-16

6803145 - 01

Kathrein Automotive

218898-10

50110260

LTE Kompensator US

SN: 000110

Compensator US BU001

FCC ID: 2ACC7LTECOMPB0

IC: 11980A-LTECOMPBO

Portugal



