

Federal Communications Commission 7345 Oakland Mills Road Columbia MD 21046

SUBJECT: Request for Class II Permissive Change for FCC ID: 2ACCJB172

The product, MK40, has been granted by FCC dated 04/14/2022, FCC ID: 2ACCJB172.

Pursuant to §2.1043, we, 2ACCJB172, would like to modify the authorized equipment for below changes:

- 1. P sensor from SX93101CSTRT change to SX9311ICSTRTi
- 2. RF switch from HS8775C-15 change to OM8775C-25
- 3. RF switch from AW13412DNR change to AW13412HDNR
- 4. Antenna switch from AW13418QNR change to AW13418RQNR
- 5. ESIM chipset from EMBLTECONN (Dynacard) change to SLI97CF1MOOPE (INFINEON).

Except for the changes above, no other modification is performed. There is no hardware or electrical modification made to the applying transmitter itself. We would like to certify the additional of certified FCC ID: 2ACCJB172 as a Class II Permissive Change in this device.

Thank you for your attention in this matter.

Sincerely,

Signatory

Annie Jiang

(FCC original Grantee CONTACT DETAILS)

Name: Annie Jiang

Position: Product certification Manager Company: TCL Communication Ltd.

Address: 5/F, Building 22E, 22 Science Park East Avenue, Hong Kong Science Park, Shatin, NT,

Hong Kong

Tel.: +86 755 36611621

Fax.: +86 755 3661 2000-81722 E-Mail: nianxiang.jiang@tcl.com