

仅供内部使用
Internal Use Only

5F, C building, TBD. 232, Liang Jing Road
ZhangJiang High-Tech Park, Pudong Area
Shanghai, P.R. China. 201203
TEL: +86(0)21 61460666
FAX: +86(0)21 61460602

Declaration of changes from Initial 8492A to Variant 8493A

General: 8493A is a variant product of 8492A:

● SOFTWARE MODIFICATIONS:

- OS update (e.g. from Android 12 to 13) / change (e.g. from Android to other OS) : no
- Protocol Stack changes: no
- MMS/STK/USAT/USIM changes: no
- DM/SUPL/VT/FUMO/SWP/HCI: no
- Other changes detail: no

● HARDWARE MODIFICATIONS:

- CPU change: Yes, pin to pin change, MTK 8766 changes to MTK 8768.
 - 1) The new chip component is pin-for-pin compatible.
 - 2) The new chip has the same basic function as the old chip, from an external perspective (internal circuitry may differ).
 - 3) No change in radio parameters has occurred.
 - 4) The same conditions apply when a small area (approximately the same area as the chip) of the PCB is replaced with an equivalent chip.
- Baseband changes: No
- Band changes: No Main bands for conformance testing changes (Yes/No): No
- PCB layout/material changes: No
- Main components changes: NO
- FM changes: No
- GPS changes: No (e.g. Saw is different)
- Memory/TP/LCD/ Camera/SIM changes: no
- Other changes detailed: no

● MECHANICAL MODIFICATIONS:

- Use new metal front/back cover or keypad: no
- Mechanical shell changes: no
 - Whole size of EUT: no
 - Distance of Ear reference point to bottom of handset: no
 - Other trinkets to change the surface of handset: no
- Other changes detailed: no

● Accessory changes:

- Use new charger/battery/headset/USB cable: add a USB cable

● Update of standards: no

APPROVED BY:

Project Manager: Yafang.Xi

Signature:

Date: 2024/01/22

Yafang.Xi