

Date: Oct. 20, 21

To: Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Attn: OET Dept.

Ref: FCC Class II Permissive change for FCC ID: 2ACCJH120 Original Grant Date: 03/11/2020 Applicant: TCL Communication Ltd.

Dear Examiner,

This is to request a Class II permissive change for FCC ID: 2ACCJH120 , originally granted on 03/11/2020

The major change filed under this application is:

• SOFTWARE MODIFICATIONS:

- Protocol Stack changes: No
- > MMS/STK/USAT/USIM changes: No
- > DM/SUPL/VT/FUMO/SWP/HCI: No
- > Other changes detailed: No

• HARDWARE MODIFICATIONS:

Band changes: No

| Code Name | Frequency Band | CA |
|-----------|--|----|
| 5002S | 2G-GSM:850/900/1800/1900 | |
| | 3G-WCDMA:B1/B2/B4/B5/B8 | |
| | 4G-FDD LTE:B2/B4/B5/B7/B12/B13/B17/B66 | |
| 5002W | 2G-GSM:850/900/1800/1900 | |
| | 3G-WCDMA:B1/B2/B4/B5/B8 | |
| | 4G-FDD LTE:B2/B4/B5/B7/B12/B13/B17/B66 | |

- PCB Layout changes: No
- > RF components changes: No



| | Antenn | Base | Transceiv | ASM | Power | Тх | Rx | Duplex |
|-----------|--------|------|-----------|-----|-----------|--------|--------|--------|
| | а | Band | er | | Amplifier | SAW | SAW | er |
| | | | | | - | Filter | Filter | |
| GSM850 | NO | NO | NO | NO | NO | NO | NO | NO |
| GSM900 | NO | NO | NO | NO | NO | NO | NO | NO |
| GSM1800 | NO | NO | NO | NO | NO | NO | NO | NO |
| GSM1900 | NO | NO | NO | NO | NO | NO | NO | NO |
| UMTS2100 | NO | NO | NO | NO | NO | NO | NO | NO |
| UMTS1900 | NO | NO | NO | NO | NO | NO | NO | NO |
| UMTS1700 | NO | NO | NO | NO | NO | NO | NO | NO |
| UMTS900 | NO | NO | NO | NO | NO | NO | NO | NO |
| UMTS850 | NO | NO | NO | NO | NO | NO | NO | NO |
| LTE 2 | NO | NO | NO | NO | NO | NO | NO | NO |
| LTE 4 | NO | NO | NO | NO | NO | NO | NO | NO |
| LTE 5 | NO | NO | NO | NO | NO | NO | NO | NO |
| LTE 7 | NO | NO | NO | NO | NO | NO | NO | NO |
| LTE 12 | NO | NO | NO | NO | NO | NO | NO | NO |
| LTE 13 | NO | NO | NO | NO | NO | NO | NO | NO |
| LTE 17 | NO | NO | NO | NO | NO | NO | NO | NO |
| LTE 66 | NO | NO | NO | NO | NO | NO | NO | NO |
| Bluetooth | NO | NO | NO | NO | NO | NO | NO | NO |
| WiFi | NO | NO | NO | NO | NO | NO | NO | NO |
| GPS | NO | NO | NO | NO | NO | NO | NO | NO |

FM changes: No

- > LCD/ Speaker/ Camera/ Vibrator changes: Yes, change memory/camera
- > Other changes detailed:

add 2nd battery and add a USB cable. For more detail refer to the follower list.

| Code Name | 5002S | 5002W |
|------------|-----------------------------|-------------------------------|
| Battery | CAB2880001C1,3000mAh, BYD | CAB2880015C7, 3000mAh, VEKEN, |
| | | TLi028C7 |
| Charger | CBA0058AGAC5, MOU,PUAN | CBA0058AGAC5, MOU, PUAN, UC11 |
| | CBA0058AGAC7, MOU, CHENYANG | |
| Data cable | CDA3122005C8, PUAN | CDA3122005C8, PUAN |
| | CDA3122005C1, JUWEI | CDA0000143C8, PUAN (same with |
| | | CDA3122005C8) |

• MECHANICAL MODIFICATIONS:

- > Use new metal front/back cover or keypad: No
- Mechanical shell changes:
 - Whole size of EUT: No
 - Distance of Ear reference point to bottom of handset: No
 - Other trinkets to change the surface of handset: No
- > Other changes detailed: N/A

Based on the change, we performed test for SAR/Part15B as below table. Details refer to the relevant test reports.



| | Items | Band | Comment |
|-------|--|---|--|
| 1.1 | GSM part | | |
| 1.1.1 | GSM mobile phone FCC certification SAR testing | 850,1900 | 850、1900: 2 points spot check |
| 1.2 | UMTS part | | |
| 1.2.1 | UMTS mobile phone FCC certification SAR testing | 850,1900,1700 | 850、1900、1700: 2 points spot check |
| 1.3 | LTE part | | |
| 1.3.1 | LTE mobile phone FCC certification SAR testing acc to Oet65 | Band66,Band1 7,Band12,Ban d4,Band7,Ban d2,Band5,Ban d13 | Band66、Band12、Band7、 Band2、Band5、Band13: 2 points spot check, Band17、Band4: No test |
| 1.4 | USB part | | |
| 1.4.1 | FCC certification part15B testing | | RE TCs |

Sincerely yours,

Zi Xiaogang