

LTE 71	No	No	No	No	No	No	No	No	No
5G SA N2(remove)	NA	NA	NA	NA	NA	NA	NA	NA	NA
5G SA N5(add)	No	No	No	No	No	No	No	No	No
5G SA N25	No	No	No	No	No	No	No	No	No
5G SA N41	No	No	No	No	No	No	No	No	No
5G SA N66	No	No	No	No	No	No	No	No	No
5G SA N70(remove)	NA	NA	NA	NA	NA	NA	NA	NA	NA
5G SA N71	No	No	No	No	No	No	No	No	No
5G SA N77	No	No	No	No	No	No	No	No	No
5G SA N78(add)	No	No	No	No	No	No	No	No	No
Bluetooth	No	No	No	No	No	No	No	No	No
WiFi	No	No	No	No	No	No	No	No	No

- FM changes: No
- Other components changes:
LCD/ Speaker/ Vibrator changes: No
- Other changes detailed:

● **MECHANICAL MODIFICATIONS:**

- Use new metal front/back cover or keypad: No
- Mechanical shell changes:
Whole size of EUT: No
Distance of Ear reference point to bottom of handset: No
Other trinkets to change the surface of handset: No
- Other changes detailed:

For the above, we performed SAR/HAC/T-coil/Part22/24/27 tests (partially re-used the test results of initial). Other test result coming from the initial model. And please refer to the relevant test reports.

Thank you.

Sincerely,

Name:

Title:

Company Name: TCL Communication Ltd.

Company address: 5/F, Building 22E, 22 Science Park East Avenue, Hong Kong Science Park, Shatin, NT, Hong Kong