



Declaration of changes between 5031G and 5131G

● SOFTWARE MODIFICATIONS:

- Protocol Stack changes: No
- MMS/STK/USAT/USIM changes: No
- DM/SUPL/VT/FUMO/SWP/HCI: No
- Other changes detailed: [Brand logo changes](#)

● HARDWARE MODIFICATIONS:

- Band changes: No
- PCB Layout changes: No
- Main RF components changes: No

	Antenna	Baseband (AP)	Baseband (BP)	Transceiver	Power Amplifier	Tx SAW Filter	Rx SAW Filter	Duplexer	ASM
GSM850	No	No	No	No	No	No	No	No	No
GSM900	No	No	No	No	No	No	No	No	No
GSM1800	No	No	No	No	No	No	No	No	No
GSM1900	No	No	No	No	No	No	No	No	No
UMTS B1	No	No	No	No	No	No	No	No	No
UMTS B2	No	No	No	No	No	No	No	No	No
UMTS B5	No	No	No	No	No	No	No	No	No
UMTS B8	No	No	No	No	No	No	No	No	No
LTE Band 1	No	No	No	No	No	No	No	No	No
LTE Band 3	No	No	No	No	No	No	No	No	No
LTE Band 5	No	No	No	No	No	No	No	No	No
LTE Band 7	No	No	No	No	No	No	No	No	No
LTE Band 8	No	No	No	No	No	No	No	No	No
LTE Band 20	No	No	No	No	No	No	No	No	No
LTE Band 28full	No	No	No	No	No	No	No	No	No
LTE Band 38	No	No	No	No	No	No	No	No	No
LTE Band 40	No	No	No	No	No	No	No	No	No
LTE Band 41	No	No	No	No	No	No	No	No	No
Bluetooth	No	No	No	No	No	No	No	No	No
Wi-Fi	No	No	No	No	No	No	No	No	No

- CA bands

5031G	NA
5131G	NA

- FM changes: No
- LCD/ Speaker/ Camera/ Vibrator changes: No
- Other changes detailed: [Brand logo changes](#)
- [5031G & 5131G is totally consistent except brand, so testing could be performed on 5031G](#)

● **MECHANICAL MODIFICATIONS:**


- Use new metal front/back cover or keypad: No
- Mechanical shell changes:
 - Whole size of EUT: No
 - Distance of Ear reference point to bottom of handset: No
 - Other trinkets to change the surface of handset: No
- Other changes detailed:

[The silkscreen of the battery cover is different](#)

APPROVED BY:

Project Manager: 陈淑云

Signature:



Date: 2022-01-29