

Date: Dec. 7, 21

To: Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Attn: OET Dept.

Ref: FCC Class II Permissive change for FCC ID: 2ACCJN056

Original Grant Date: 11/16/2021 Applicant: TCL Communication Ltd.

Dear Examiner,

This is to request a Class II permissive change for FCC ID: 2ACCJN056 , originally granted on 11/16/2021

The major change filed under this application is:

• SOFTWARE MODIFICATIONS:

- Protocol Stack changes: NO
- > MMS/STK/USAT/USIM changes: NO
- > DM/SUPL/VT/FUMO/SWP/HCI: NO (indicated the changed items if yes)
- > Other changes detailed: yes , add 2CC mmW and SW version change to 3D5G
- Supported carrier bandwidth for 2CC: 100MHz, and Total aggregated mmWave BW: 200MHz

5G-NR	Sub-Category	Number	DL-Combo	4G UL	5G NR UL
		of			
		mmWave			
		cc			
	1DL+ FR2	2	DC_13A_n261G	13A	n261A, n261G
	2DL+ FR2	2	DC_13A-66A_n261G	13A , 66A	n261A, n261G
	1DL+ FR2	2	DC_13A_n260G	13A	n260A, n260G
	2DL+ FR2	2	DC_13A-66A_n260G	13A , 66A	n260A, n260G
	1DL+ FR2	2	DC_2A_n261G	2A	n261A, n261G
mmW	2DL+ FR2	2	DC_2A-13A_n261G	2A , 13A	n261A, n261G
	2DL+ FR2	2	DC_2A-66A_n261G	2A , 66A	n261A, n261G
	1DL+ FR2	2	DC_2A_n260G	2A	n260A, n260G
	2DL+ FR2	2	DC_2A-2A_n260G	2A	n260A, n260G
	2DL+ FR2	2	DC_2A-5A_n260G	2A , 5A	n260A, n260G
	2DL+ FR2	2	DC_2A-13A_n260G	2A , 13A	n260A, n260G



	1			1
2DL+ FR2	2	DC_2A-66A_n260G	2A , 66A	n260A, n260G
1DL+ FR2	2	DC_48A_n261G	48A	n261A, n261G
1DL+ FR2	2	DC_48A_n260G	48A	n260A, n260G
1DL+ FR2	2	DC_5A_n261G	5A	n261A, n261G
1DL+ FR2	2	DC_66A_n261G	66A	n261A, n261G
2DL+ FR2	2	DC_66A-66A_n261G	66A	n261A, n261G
1DL+ FR2	2	DC_5A_n260G	5A	n260A, n260G
1DL+ FR2	2	DC_66A_n260G	66A	n260A, n260G
2DL+ FR2	2	DC_66A-66A_n260G	66A	n260A, n260G
2DL+ FR2	2	DC_2A-5A_n261G	2A , 5A	n261A, n261G
2DL+ FR2	2	DC_5A-66A_n261G	5A , 66A	n261A, n261G
2DL+ FR2	2	DC_5A-66A_n260G	5A , 66A	n260A, n260G

• HARDWARE MODIFICATIONS:

- Band changes: NO
- PCB Layout changes: NO
- Main RF components changes: NO
- FM changes: No
- LCD/ Speaker/ Camera/ Vibrator changes: (indicated the changed items if yes) No
- > Other changes detailed:

We request permission to use all the test results from model T781S,T781SPP (FCC ID: 2ACCJN056) in our applications for model T781S,T781SPP (FCC ID: 2ACCJN056). Because we add bands on this product only by software.

In addition, we performed full test for the 2CC mmW(EMC). For details, please refer to the relevant test reports.

Sincerely yours, Regards,

Jong shishon

Zhizhou GONG Product Certification Manager TCL Communication Ltd.