

Sentry Industries Limited

July 10, 2020

Office of Engineering Technology  
Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046  
USA

**Subject: Explanation of differences between product types**

FCC ID : 2ACP4LBT251

Model Number: BT237, BT116, BT120, BT135, BT140, BT150, BT175 ,  
BT231, BT234, BT115, BT239, BT250, BT251, BT315, BT320, BT350, BT450, BT550,  
BT650, BT651, BT652, BT750, BT751, BT752, BT850, BT875, BT885, BT895, BT876,  
BT877, BT878, BT879, BT886, BT887, BT888, BT889, BX150, BX250


**To Whom It May Concern:**

We, The Sentry Industries Limited hereby declare that the model : BT116, BT120, BT135, BT140, BT150, BT175 , BT231, BT234, BT115, BT239, BT250, BT251, BT315, BT320, BT350, BT450, BT550, BT650, BT651, BT652, BT750, BT751, BT752, BT850, BT875, BT885, BT895, BT876, BT877, BT878, BT879, BT886, BT887, BT888, BT889, BX150, BX250 is identical with the model : BT237, except the model name.

Except for the different above, no other modification is performed.

Sincerely,

Signature:



Sentry Industries Limited  
Contact person: Peetu Melwani