



Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6D21707-17252-FCC

FCC ID: 2AD37JWR2100

External Photos

Model no.: AMS117-1202000F2





Worldwide Testing Services(Taiwan) Co., Ltd.

Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100
Model no.: DSA-24PFM-12 FCA 120200







Worldwide Testing Services(Taiwan) Co., Ltd.


Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100
Model no.: DSA-24PFM-12 FUS 120200






Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100






Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100





Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100





Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100






Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100






Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100






Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100






Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100






Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100






Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100





Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100





Registration number: W6D21707-17252-FCC
FCC ID: 2AD37JWR2100



Registration number: W6D21707-17252-FCC

FCC ID: 2AD37JWR2100

Adaptor 1:



Adaptor 2:



Registration number: W6D21707-17252-FCC

FCC ID: 2AD37JWR2100

Adaptor 3:

