

Dentsply Sirona  
SIRONA Dental Systems GmbH  
Fabrikstraße 31  
64625 Bensheim - Germany



TUV SUD America Inc.  
10 Centennial Drive  
Peabody, MA 01960, USA

Date 08/11/2023

REF: C2PC for FCC ID:, 2AD7W-6802040 and IC: 12730A-6802040 C4PC/ for IC: 12730A-6802040,  
Model/HVIN: Primescan 2

Dear Sir or Madam,

Pursuant to FCC Rule Part 2.1043, and ISED RSP-100 Sec. 7, we hereby submit a request for FCC C2PC/ IC  
C4PC for FCC ID:, 2AD7W-6802040 and to Existing Certification IC: 12730A-6802040, Model/HVIN: Primescan 2

Description of the change:

The differences between model/HVIN: Primescan 2 and previously approved model(s) shown below:

- The module can be use in Portable / mobile hosts.

The Radio module remains unchanged.

Sincerely,

Signature:

Ralf Burkhardt / Chapter Lead Electronics Research and Development

Telephone Number: 06251/16-2157

Email: [ralf.burkhardt@dentsplysirona.com](mailto:ralf.burkhardt@dentsplysirona.com)