



Please refer to following plots:




Date: 31.JUL.2022 13:19:10




Date: 31.JUL.2022 13:19:28

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 31.JUL.2022 13:19:47

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 31.JUL.2022 13:20:02

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 31.JUL.2022 13:20:23

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 31.JUL.2022 13:20:37

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 31.JUL.2022 13:21:17

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 31.JUL.2022 13:21:32

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 31.JUL.2022 13:21:48

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 31.JUL.2022 13:22:06

Band 2_3 MHz_High_QPSK_RB15#0




Date: 31.JUL.2022 13:22:25

Band 2_3 MHz_High_16QAM_RB15#0




Date: 31.JUL.2022 13:22:40

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 31.JUL.2022 13:24:15

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 31.JUL.2022 13:24:31

Band 2_5 MHz_High_QPSK_RB25#0




Date: 31.JUL.2022 13:24:50

Band 2_5 MHz_High_16QAM_RB25#0




Date: 31.JUL.2022 13:25:10

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 31.JUL.2022 13:25:56

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 31.JUL.2022 13:26:15

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 31.JUL.2022 13:26:35

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 31.JUL.2022 13:26:52

Band 2_10 MHz_High_QPSK_RB50#0




Date: 31.JUL.2022 13:27:12

Band 2_10 MHz_High_16QAM_RB50#0




Date: 31.JUL.2022 13:27:31

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 31.JUL.2022 13:28:43

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 31.JUL.2022 13:29:02

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 31.JUL.2022 13:29:24

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 31.JUL.2022 13:29:48

Band 2_15 MHz_High_QPSK_RB75#0




Date: 31.JUL.2022 13:30:07

Band 2_15 MHz_High_16QAM_RB75#0




Date: 31.JUL.2022 13:30:26

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 31.JUL.2022 13:31:13

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 31.JUL.2022 13:31:33

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 31.JUL.2022 13:31:56

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 31.JUL.2022 13:32:18

Band 2_20 MHz_High_QPSK_RB100#0




Date: 31.JUL.2022 13:32:42

Band 2_20 MHz_High_16QAM_RB100#0




Date: 31.JUL.2022 13:33:01

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 31.JUL.2022 13:33:24

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 31.JUL.2022 13:33:43

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 31.JUL.2022 13:34:01

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 31.JUL.2022 13:34:16

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 31.JUL.2022 13:34:35

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 31.JUL.2022 13:34:50

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 31.JUL.2022 13:35:41

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 31.JUL.2022 13:35:56

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 31.JUL.2022 13:36:12

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 31.JUL.2022 13:36:30

Band 4_3 MHz_High_QPSK_RB15#0




Date: 31.JUL.2022 13:36:46

Band 4_3 MHz_High_16QAM_RB15#0




Date: 31.JUL.2022 13:37:04

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 31.JUL.2022 13:37:44

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 31.JUL.2022 13:38:03

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 31.JUL.2022 13:38:22

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 31.JUL.2022 13:38:41

Band 4_5 MHz_High_QPSK_RB25#0




Date: 31.JUL.2022 13:39:00

Band 4_5 MHz_High_16QAM_RB25#0




Date: 31.JUL.2022 13:39:19

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 31.JUL.2022 13:40:03

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 31.JUL.2022 13:40:22

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 31.JUL.2022 13:40:43

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 31.JUL.2022 13:40:59

Band 4_10 MHz_High_QPSK_RB50#0




Date: 31.JUL.2022 13:41:19

Band 4_10 MHz_High_16QAM_RB50#0




Date: 31.JUL.2022 13:41:38

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 31.JUL.2022 13:42:56

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 31.JUL.2022 13:43:18

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 31.JUL.2022 13:43:41

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 31.JUL.2022 13:43:59

Band 4_15 MHz_High_QPSK_RB75#0




Date: 31.JUL.2022 13:44:22

Band 4_15 MHz_High_16QAM_RB75#0




Date: 31.JUL.2022 13:44:44

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 31.JUL.2022 13:45:31

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 31.JUL.2022 13:45:53

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 31.JUL.2022 13:46:16

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 31.JUL.2022 13:46:38

Band 4_20 MHz_High_QPSK_RB100#0




Date: 31.JUL.2022 13:46:58

Band 4_20 MHz_High_16QAM_RB100#0




Date: 31.JUL.2022 13:47:21

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 28.JUL.2022 10:24:43

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 28.JUL.2022 10:25:02

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 28.JUL.2022 10:25:24

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 28.JUL.2022 10:25:48

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 28.JUL.2022 10:26:07

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 28.JUL.2022 10:26:25

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 28.JUL.2022 10:28:53

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 28.JUL.2022 10:29:12

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 28.JUL.2022 10:29:31

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 28.JUL.2022 10:29:52

Band 5_3 MHz_High_QPSK_RB15#0




Date: 28.JUL.2022 10:30:11

Band 5_3 MHz_High_16QAM_RB15#0




Date: 28.JUL.2022 10:30:26

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 28.JUL.2022 10:31:42

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 28.JUL.2022 10:32:03

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 28.JUL.2022 10:32:26

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 28.JUL.2022 10:32:51

Band 5_5 MHz_High_QPSK_RB25#0




Date: 28.JUL.2022 10:33:10

Band 5_5 MHz_High_16QAM_RB25#0




Date: 28.JUL.2022 10:33:32

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 28.JUL.2022 10:34:40

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 28.JUL.2022 10:34:59

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 28.JUL.2022 10:35:20

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 28.JUL.2022 10:35:39

Band 5_10 MHz_High_QPSK_RB50#0




Date: 28.JUL.2022 10:35:59

Band 5_10 MHz_High_16QAM_RB50#0




Date: 28.JUL.2022 10:36:18

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 31.JUL.2022 13:47:46

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 31.JUL.2022 13:48:08

Band 7_5 MHz_High_QPSK_RB25#0




Date: 31.JUL.2022 13:49:08

Band 7_5 MHz_High_16QAM_RB25#0




Date: 31.JUL.2022 13:49:27

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 31.JUL.2022 13:50:37

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 31.JUL.2022 13:50:56

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 31.JUL.2022 13:51:16

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 31.JUL.2022 13:51:36

Band 7_10 MHz_High_QPSK_RB50#0




Date: 31.JUL.2022 13:51:59

Band 7_10 MHz_High_16QAM_RB50#0




Date: 31.JUL.2022 13:52:15

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 31.JUL.2022 13:53:01

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 31.JUL.2022 13:53:20

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 31.JUL.2022 13:53:43

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 31.JUL.2022 13:54:05

Band 7_15 MHz_High_QPSK_RB75#0




Date: 31.JUL.2022 13:54:31

Band 7_15 MHz_High_16QAM_RB75#0




Date: 31.JUL.2022 13:54:52

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 31.JUL.2022 13:55:39

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 31.JUL.2022 13:56:02

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 31.JUL.2022 13:56:25

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 31.JUL.2022 13:56:47

Band 7_20 MHz_High_QPSK_RB100#0




Date: 31.JUL.2022 13:57:10

Band 7_20 MHz_High_16QAM_RB100#0




Date: 31.JUL.2022 13:57:33

Band 12_1.4 MHz_Middle_QPSK_RB6#0




Date: 28.JUL.2022 12:41:15

Band 12_1.4 MHz_Middle_16QAM_RB6#0




Date: 28.JUL.2022 12:41:32

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 28.JUL.2022 12:41:48

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 28.JUL.2022 12:42:06

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 28.JUL.2022 12:42:48

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 28.JUL.2022 12:43:06

Band 12_3 MHz_Middle_QPSK_RB15#0




Date: 28.JUL.2022 12:43:22

Band 12_3 MHz_Middle_16QAM_RB15#0




Date: 28.JUL.2022 12:43:40

Band 12_3 MHz_High_QPSK_RB15#0




Date: 28.JUL.2022 12:43:56

Band 12_3 MHz_High_16QAM_RB15#0




Date: 28.JUL.2022 12:44:17

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 28.JUL.2022 13:05:23

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 28.JUL.2022 13:05:46

Band 12_5 MHz_Middle_QPSK_RB25#0




Date: 28.JUL.2022 13:06:02

Band 12_5 MHz_Middle_16QAM_RB25#0




Date: 28.JUL.2022 13:06:24

Band 12_5 MHz_High_QPSK_RB25#0




Date: 28.JUL.2022 13:06:43

Band 12_5 MHz_High_16QAM_RB25#0




Date: 28.JUL.2022 13:07:02

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 28.JUL.2022 13:08:12

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 28.JUL.2022 13:08:34

Band 12_10 MHz_Middle_QPSK_RB50#0




Date: 28.JUL.2022 13:08:54

Band 12_10 MHz_Middle_16QAM_RB50#0




Date: 28.JUL.2022 13:09:17

Band 12_10 MHz_High_QPSK_RB50#0




Date: 28.JUL.2022 13:09:37

Band 12_10 MHz_High_16QAM_RB50#0




Date: 28.JUL.2022 13:09:59

Band 13_5 MHz_Low_QPSK_RB25#0




Date: 28.JUL.2022 10:36:46

Band 13_5 MHz_Low_16QAM_RB25#0




Date: 28.JUL.2022 10:37:08

Band 13_5 MHz_Middle_QPSK_RB25#0




Date: 28.JUL.2022 10:37:28

Band 13_5 MHz_Middle_16QAM_RB25#0




Date: 28.JUL.2022 10:37:49

Band 13_5 MHz_High_QPSK_RB25#0




Date: 28.JUL.2022 10:38:12

Band 13_5 MHz_High_16QAM_RB25#0




Date: 28.JUL.2022 10:38:31

Band 13_10 MHz_Middle_QPSK_RB50#0




Date: 28.JUL.2022 10:39:31

Band 13_10 MHz_Middle_16QAM_RB50#0




Date: 28.JUL.2022 10:39:51

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 29.JUL.2022 18:41:34

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 29.JUL.2022 18:41:53

Band 17_5 MHz_Middle_QPSK_RB25#0




Date: 29.JUL.2022 18:42:12

Band 17_5 MHz_Middle_16QAM_RB25#0




Date: 29.JUL.2022 18:42:31

Band 17_5 MHz_High_QPSK_RB25#0




Date: 29.JUL.2022 18:42:50

Band 17_5 MHz_High_16QAM_RB25#0




Date: 29.JUL.2022 18:43:12

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 29.JUL.2022 18:43:59

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 29.JUL.2022 18:44:18

Band 17_10 MHz_Middle_QPSK_RB50#0




Date: 29.JUL.2022 18:44:38

Band 17_10 MHz_Middle_16QAM_RB50#0




Date: 29.JUL.2022 18:44:57

Band 17_10 MHz_High_QPSK_RB50#0




Date: 29.JUL.2022 18:45:17

Band 17_10 MHz_High_16QAM_RB50#0




Date: 29.JUL.2022 18:45:36

Band 25_1.4 MHz_Low_QPSK_RB6#0




Date: 31.JUL.2022 13:57:54

Band 25_1.4 MHz_Low_16QAM_RB6#0




Date: 31.JUL.2022 13:58:12

Band 25_1.4 MHz_Middle_QPSK_RB6#0




Date: 31.JUL.2022 13:58:28

Band 25_1.4 MHz_Middle_16QAM_RB6#0




Date: 31.JUL.2022 13:58:43

Band 25_1.4 MHz_High_QPSK_RB6#0




Date: 31.JUL.2022 13:59:01

Band 25_1.4 MHz_High_16QAM_RB6#0




Date: 31.JUL.2022 13:59:19

Band 25_3 MHz_Low_QPSK_RB15#0




Date: 31.JUL.2022 14:00:28

Band 25_3 MHz_Low_16QAM_RB15#0




Date: 31.JUL.2022 14:00:46

Band 25_3 MHz_High_QPSK_RB15#0




Date: 31.JUL.2022 14:01:35

Band 25_3 MHz_High_16QAM_RB15#0




Date: 31.JUL.2022 14:01:53

Band 25_5 MHz_Low_QPSK_RB25#0




Date: 31.JUL.2022 14:02:37

Band 25_5 MHz_Low_16QAM_RB25#0




Date: 31.JUL.2022 14:02:56

Band 25_5 MHz_Middle_QPSK_RB25#0




Date: 31.JUL.2022 14:03:12

Band 25_5 MHz_Middle_16QAM_RB25#0




Date: 31.JUL.2022 14:03:28

Band 25_5 MHz_High_QPSK_RB25#0




Date: 31.JUL.2022 14:03:50

Band 25_5 MHz_High_16QAM_RB25#0




Date: 31.JUL.2022 14:04:09

Band 25_10 MHz_Low_QPSK_RB50#0




Date: 31.JUL.2022 14:04:54

Band 25_10 MHz_Low_16QAM_RB50#0




Date: 31.JUL.2022 14:05:13

Band 25_10 MHz_Middle_QPSK_RB50#0




Date: 31.JUL.2022 14:05:33

Band 25_10 MHz_Middle_16QAM_RB50#0




Date: 31.JUL.2022 14:05:53

Band 25_10 MHz_High_QPSK_RB50#0




Date: 31.JUL.2022 14:06:13

Band 25_10 MHz_High_16QAM_RB50#0




Date: 31.JUL.2022 14:06:32

Band 25_15 MHz_Low_QPSK_RB75#0




Date: 31.JUL.2022 14:07:17

Band 25_15 MHz_Low_16QAM_RB75#0




Date: 31.JUL.2022 14:07:35

Band 25_15 MHz_Middle_QPSK_RB75#0




Date: 31.JUL.2022 14:07:58

Band 25_15 MHz_Middle_16QAM_RB75#0




Date: 31.JUL.2022 14:08:20

Band 25_15 MHz_High_QPSK_RB75#0




Date: 31.JUL.2022 14:08:42

Band 25_15 MHz_High_16QAM_RB75#0




Date: 31.JUL.2022 14:09:01

Band 25_20 MHz_Low_QPSK_RB100#0




Date: 31.JUL.2022 14:09:55

Band 25_20 MHz_Low_16QAM_RB100#0




Date: 31.JUL.2022 14:10:14

Band 25_20 MHz_Middle_QPSK_RB100#0




Date: 31.JUL.2022 14:10:37

Band 25_20 MHz_Middle_16QAM_RB100#0




Date: 31.JUL.2022 14:10:59

Band 25_20 MHz_High_QPSK_RB100#0




Date: 31.JUL.2022 14:11:23

Band 25_20 MHz_High_16QAM_RB100#0




Date: 31.JUL.2022 14:11:45

Band 26_1.4 MHz_Low_QPSK_RB6#0




Date: 30.JUL.2022 16:26:09

Band 26_1.4 MHz_Low_16QAM_RB6#0




Date: 30.JUL.2022 16:26:31

Band 26_1.4 MHz_Middle_QPSK_RB6#0




Date: 30.JUL.2022 16:26:50

Band 26_1.4 MHz_Middle_16QAM_RB6#0




Date: 30.JUL.2022 16:27:05

Band 26_1.4 MHz_High_QPSK_RB6#0




Date: 30.JUL.2022 16:27:24

Band 26_1.4 MHz_High_16QAM_RB6#0




Date: 30.JUL.2022 16:27:42

Band 26_3 MHz_Low_QPSK_RB15#0




Date: 30.JUL.2022 16:28:04

Band 26_3 MHz_Low_16QAM_RB15#0




Date: 30.JUL.2022 16:28:22

Band 26_3 MHz_Middle_QPSK_RB15#0




Date: 30.JUL.2022 16:28:38

Band 26_3 MHz_Middle_16QAM_RB15#0




Date: 30.JUL.2022 16:28:53

Band 26_3 MHz_High_QPSK_RB15#0




Date: 30.JUL.2022 16:29:12

Band 26_3 MHz_High_16QAM_RB15#0




Date: 30.JUL.2022 16:29:30

Band 26_5 MHz_Low_QPSK_RB25#0




Date: 30.JUL.2022 16:29:59

Band 26_5 MHz_Low_16QAM_RB25#0




Date: 30.JUL.2022 16:30:21

Band 26_5 MHz_Middle_QPSK_RB25#0




Date: 30.JUL.2022 16:30:44

Band 26_5 MHz_Middle_16QAM_RB25#0




Date: 30.JUL.2022 16:31:02

Band 26_5 MHz_High_QPSK_RB25#0




Date: 30.JUL.2022 16:31:21

Band 26_5 MHz_High_16QAM_RB25#0




Date: 30.JUL.2022 16:31:43

Band 26_10 MHz_Middle_QPSK_RB50#0




Date: 30.JUL.2022 16:32:03

Band 26_10 MHz_Middle_16QAM_RB50#0




Date: 30.JUL.2022 16:32:26

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 28.JUL.2022 16:04:29

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 28.JUL.2022 16:04:51

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 28.JUL.2022 16:06:32

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 28.JUL.2022 16:07:19

Band 41_5 MHz_High_QPSK_RB25#0




Date: 28.JUL.2022 16:08:57

Band 41_5 MHz_High_16QAM_RB25#0




Date: 28.JUL.2022 16:10:16

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 28.JUL.2022 16:12:02

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 28.JUL.2022 16:12:28

Band 41_10 MHz_Middle_QPSK_RB50#0




Date: 28.JUL.2022 16:12:53

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 28.JUL.2022 16:13:12

Band 41_10 MHz_High_QPSK_RB50#0




Date: 28.JUL.2022 16:13:38

Band 41_10 MHz_High_16QAM_RB50#0




Date: 28.JUL.2022 16:14:01

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 28.JUL.2022 16:15:28

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 28.JUL.2022 16:16:00

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 28.JUL.2022 16:17:35

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 28.JUL.2022 16:18:00

Band 41_15 MHz_High_QPSK_RB75#0




Date: 28.JUL.2022 16:18:50

Band 41_15 MHz_High_16QAM_RB75#0




Date: 28.JUL.2022 16:20:14

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 28.JUL.2022 16:22:45

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 28.JUL.2022 16:23:10

Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 28.JUL.2022 16:23:36

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 28.JUL.2022 16:24:21

Band 41_20 MHz_High_QPSK_RB100#0




Date: 28.JUL.2022 16:25:53

Band 41_20 MHz_High_16QAM_RB100#0




Date: 28.JUL.2022 16:28:25

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 31.JUL.2022 14:12:10

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 31.JUL.2022 14:12:28

Band 66_1.4 MHz_Middle_QPSK_RB6#0




Date: 31.JUL.2022 14:12:46

Band 66_1.4 MHz_Middle_16QAM_RB6#0




Date: 31.JUL.2022 14:13:01

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 31.JUL.2022 14:13:20

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 31.JUL.2022 14:13:38

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 31.JUL.2022 14:14:18

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 31.JUL.2022 14:14:32

Band 66_3 MHz_Middle_QPSK_RB15#0




Date: 31.JUL.2022 14:14:48

Band 66_3 MHz_Middle_16QAM_RB15#0




Date: 31.JUL.2022 14:15:06

Band 66_3 MHz_High_QPSK_RB15#0




Date: 31.JUL.2022 14:15:22

Band 66_3 MHz_High_16QAM_RB15#0




Date: 31.JUL.2022 14:15:37

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 31.JUL.2022 14:16:27

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 31.JUL.2022 14:16:46

Band 66_5 MHz_Middle_QPSK_RB25#0




Date: 31.JUL.2022 14:17:02

Band 66_5 MHz_Middle_16QAM_RB25#0




Date: 31.JUL.2022 14:17:21

Band 66_5 MHz_High_QPSK_RB25#0




Date: 31.JUL.2022 14:17:40

Band 66_5 MHz_High_16QAM_RB25#0




Date: 31.JUL.2022 14:17:59

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 31.JUL.2022 14:19:11

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 31.JUL.2022 14:19:30

Band 66_10 MHz_High_QPSK_RB50#0




Date: 31.JUL.2022 14:20:23

Band 66_10 MHz_High_16QAM_RB50#0




Date: 31.JUL.2022 14:20:39

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 31.JUL.2022 14:21:25

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 31.JUL.2022 14:21:47

Band 66_15 MHz_Middle_QPSK_RB75#0




Date: 31.JUL.2022 14:22:09

Band 66_15 MHz_Middle_16QAM_RB75#0




Date: 31.JUL.2022 14:22:31

Band 66_15 MHz_High_QPSK_RB75#0




Date: 31.JUL.2022 14:22:51

Band 66_15 MHz_High_16QAM_RB75#0




Date: 31.JUL.2022 14:23:09

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 31.JUL.2022 14:24:23

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 31.JUL.2022 14:24:45

Band 66_20 MHz_Middle_QPSK_RB100#0




Date: 31.JUL.2022 14:25:05

Band 66_20 MHz_Middle_16QAM_RB100#0




Date: 31.JUL.2022 14:25:28

Band 66_20 MHz_High_QPSK_RB100#0




Date: 31.JUL.2022 14:25:48

Band 66_20 MHz_High_16QAM_RB100#0




Date: 31.JUL.2022 14:26:10

Band 71_5 MHz_Low_QPSK_RB25#0




Date: 29.JUL.2022 18:45:59

Band 71_5 MHz_Low_16QAM_RB25#0




Date: 29.JUL.2022 18:46:17

Band 71_5 MHz_Middle_QPSK_RB25#0




Date: 29.JUL.2022 18:46:40

Band 71_5 MHz_Middle_16QAM_RB25#0




Date: 29.JUL.2022 18:47:01

Band 71_5 MHz_High_QPSK_RB25#0




Date: 29.JUL.2022 18:47:24

Band 71_5 MHz_High_16QAM_RB25#0




Date: 29.JUL.2022 18:47:45

Band 71_10 MHz_Low_QPSK_RB50#0




Date: 29.JUL.2022 18:48:47

Band 71_10 MHz_Low_16QAM_RB50#0




Date: 29.JUL.2022 18:49:09

Band 71_10 MHz_Middle_QPSK_RB50#0




Date: 29.JUL.2022 18:49:29

Band 71_10 MHz_Middle_16QAM_RB50#0




Date: 29.JUL.2022 18:49:45

Band 71_10 MHz_High_QPSK_RB50#0




Date: 29.JUL.2022 18:50:05

Band 71_10 MHz_High_16QAM_RB50#0




Date: 29.JUL.2022 18:50:24

Band 71_15 MHz_Middle_QPSK_RB75#0




Date: 29.JUL.2022 18:52:02

Band 71_15 MHz_Middle_16QAM_RB75#0




Date: 29.JUL.2022 18:52:23

Band 71_15 MHz_High_QPSK_RB75#0




Date: 29.JUL.2022 18:52:43

Band 71_15 MHz_High_16QAM_RB75#0




Date: 29.JUL.2022 18:53:05

Band 71_20 MHz_Low_QPSK_RB100#0




Date: 29.JUL.2022 18:54:12

Band 71_20 MHz_Low_16QAM_RB100#0




Date: 29.JUL.2022 18:54:35

Band 71_20 MHz_Middle_QPSK_RB100#0




Date: 29.JUL.2022 18:54:58

Band 71_20 MHz_Middle_16QAM_RB100#0




Date: 29.JUL.2022 18:55:20

Band 71_20 MHz_High_QPSK_RB100#0



Date: 29.JUL.2022 18:55:43

Band 71_20 MHz_High_16QAM_RB100#0



Date: 29.JUL.2022 18:56:05