



n5 , Normal

n5_5MHz_15kHz_826.5MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 21:10:02

n5_5MHz_15kHz_826.5MHz_DFT-s-OFDM QPSK_RB25@0




Date: 22.AUG.2022 21:10:15

n5_5MHz_15kHz_846.5MHz_DFT-s-OFDM QPSK_RB1@24




Date: 22.AUG.2022 21:17:57

n5_5MHz_15kHz_846.5MHz_DFT-s-OFDM QPSK_RB25@0




Date: 22.AUG.2022 21:18:10

n5_10MHz_15kHz_829MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 21:23:25

n5_10MHz_15kHz_829MHz_DFT-s-OFDM QPSK_RB50@0




Date: 22.AUG.2022 21:23:38

n5_15MHz_15kHz_831.5MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 21:53:01

n5_15MHz_15kHz_831.5MHz_DFT-s-OFDM QPSK_RB75@0




Date: 22.AUG.2022 21:53:14

n5_15MHz_15kHz_841.5MHz_DFT-s-OFDM QPSK_RB75@0




Date: 22.AUG.2022 21:56:51

n5_20MHz_15kHz_834MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 21:57:26

n5_20MHz_15kHz_834MHz_DFT-s-OFDM QPSK_RB100@0




Date: 22.AUG.2022 21:57:39

n5_10MHz_15kHz_844MHz_DFT-s-OFDM QPSK_RB1@51




Date: 23.AUG.2022 08:49:36

n5_10MHz_15kHz_844MHz_DFT-s-OFDM QPSK_RB50@0




Date: 23.AUG.2022 08:49:49

n5_15MHz_15kHz_841.5MHz_DFT-s-OFDM QPSK_RB1@78




Date: 23.AUG.2022 08:50:46

n5_20MHz_15kHz_839MHz_DFT-s-OFDM QPSK_RB1@105



Date: 23.AUG.2022 08:52:26


n5_20MHz_15kHz_839MHz_DFT-s-OFDM QPSK_RB100@0



Date: 23.AUG.2022 08:52:39


n41 , Normal

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 19:20:58

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM QPSK_RB24@0




Date: 22.AUG.2022 19:21:11

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@23




Date: 22.AUG.2022 19:22:06

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB24@0




Date: 22.AUG.2022 19:22:19

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 19:22:55

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB36@0




Date: 22.AUG.2022 19:23:08

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB1@37




Date: 22.AUG.2022 19:24:02

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB36@0




Date: 22.AUG.2022 19:24:16

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB1@0




Date: 22.AUG.2022 19:24:52

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB50@0




Date: 22.AUG.2022 19:25:05

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB1@50




Date: 22.AUG.2022 19:26:00

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB50@0




Date: 22.AUG.2022 19:26:15

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB1@0




Date: 22.AUG.2022 19:26:51

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB100@0




Date: 22.AUG.2022 19:27:04

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB1@105




Date: 22.AUG.2022 19:28:00

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB100@0




Date: 22.AUG.2022 19:28:15

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB1@0




Date: 22.AUG.2022 19:28:51

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB128@0




Date: 22.AUG.2022 19:29:05

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB1@132




Date: 22.AUG.2022 19:30:00

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB128@0




Date: 22.AUG.2022 19:30:14

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 19:30:50

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB162@0




Date: 22.AUG.2022 19:31:04

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB1@161




Date: 22.AUG.2022 19:31:59

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB162@0




Date: 22.AUG.2022 19:32:14

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB1@0




Date: 22.AUG.2022 19:32:50

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB216@0




Date: 22.AUG.2022 19:33:04

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB1@216




Date: 22.AUG.2022 19:33:59

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB216@0




Date: 22.AUG.2022 19:34:14

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 19:34:51

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB243@0




Date: 22.AUG.2022 19:35:04

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB1@244




Date: 22.AUG.2022 19:35:59

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB243@0




Date: 22.AUG.2022 19:36:14

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB1@0




Date: 22.AUG.2022 19:36:51

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB270@0




Date: 22.AUG.2022 19:37:05

n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB1@272



Date: 22.AUG.2022 19:38:00


n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB270@0



Date: 22.AUG.2022 19:38:15


n66 , Normal

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 19:39:04

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM QPSK_RB25@0




Date: 22.AUG.2022 19:39:17

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM QPSK_RB1@24




Date: 22.AUG.2022 19:40:12

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM QPSK_RB25@0




Date: 22.AUG.2022 19:40:26

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 19:41:22

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM QPSK_RB50@0




Date: 22.AUG.2022 19:41:35

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM QPSK_RB1@51




Date: 22.AUG.2022 20:19:58

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM QPSK_RB50@0




Date: 22.AUG.2022 19:44:12

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 19:45:07

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM QPSK_RB75@0




Date: 22.AUG.2022 19:45:21

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM QPSK_RB1@78




Date: 22.AUG.2022 19:46:17

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM QPSK_RB75@0




Date: 22.AUG.2022 19:46:31

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 19:47:27

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM QPSK_RB100@0




Date: 22.AUG.2022 19:47:43

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM QPSK_RB1@105




Date: 22.AUG.2022 20:55:01

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM QPSK_RB100@0




Date: 22.AUG.2022 20:30:32

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 19:52:43

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM QPSK_RB128@0




Date: 22.AUG.2022 19:53:40

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB1@132




Date: 22.AUG.2022 19:56:02

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB128@0




Date: 22.AUG.2022 19:56:22

n66_30MHz_15kHz_1725MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 19:58:02

n66_30MHz_15kHz_1725MHz_DFT-s-OFDM
QPSK_RB160@0




Date: 22.AUG.2022 19:58:17

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM
QPSK_RB1@159




Date: 22.AUG.2022 20:55:55

n66_30MHz_15kHz_1765MHz_DFT-s-OFDM
QPSK_RB160@0




Date: 22.AUG.2022 20:56:10

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 20:35:28

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM QPSK_RB216@0




Date: 22.AUG.2022 20:35:44

n66_40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB1@215



Date: 22.AUG.2022 20:36:21


n66_40MHz_15kHz_1760MHz_DFT-s-OFDM QPSK_RB216@0



Date: 22.AUG.2022 20:09:44


n71 , Normal

n71_5MHz_15kHz_665.5MHz_DFT-s-OFDM QPSK_RB1@0




Date: 23.AUG.2022 08:53:36

n71_5MHz_15kHz_665.5MHz_DFT-s-OFDM QPSK_RB25@0




Date: 22.AUG.2022 22:04:31

n71_5MHz_15kHz_695.5MHz_DFT-s-OFDM QPSK_RB1@24




Date: 23.AUG.2022 08:56:07

n71_5MHz_15kHz_695.5MHz_DFT-s-OFDM QPSK_RB25@0




Date: 23.AUG.2022 08:56:20

n71_10MHz_15kHz_668MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 22:10:07

n71_10MHz_15kHz_668MHz_DFT-s-OFDM QPSK_RB50@0




Date: 22.AUG.2022 22:10:20

n71_10MHz_15kHz_693MHz_DFT-s-OFDM QPSK_RB1@51




Date: 23.AUG.2022 08:57:59

n71_10MHz_15kHz_693MHz_DFT-s-OFDM QPSK_RB50@0




Date: 22.AUG.2022 22:13:16

n71_15MHz_15kHz_670.5MHz_DFT-s-OFDM QPSK_RB1@0




Date: 23.AUG.2022 08:58:56

n71_15MHz_15kHz_670.5MHz_DFT-s-OFDM QPSK_RB75@0




Date: 22.AUG.2022 22:16:10

n71_15MHz_15kHz_690.5MHz_DFT-s-OFDM QPSK_RB1@78




Date: 23.AUG.2022 08:59:53

n71_15MHz_15kHz_690.5MHz_DFT-s-OFDM QPSK_RB75@0




Date: 22.AUG.2022 22:19:06

n71_20MHz_15kHz_673MHz_DFT-s-OFDM QPSK_RB1@0




Date: 22.AUG.2022 22:19:41

n71_20MHz_15kHz_673MHz_DFT-s-OFDM QPSK_RB100@0




Date: 22.AUG.2022 22:19:54

n71_20MHz_15kHz_688MHz_DFT-s-OFDM QPSK_RB1@105



Date: 23.AUG.2022 09:02:52

n71_20MHz_15kHz_688MHz_DFT-s-OFDM QPSK_RB100@0



Date: 23.AUG.2022 09:03:06