



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 28.JUN.2022 15:21:44

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 28.JUN.2022 15:22:02

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 28.JUN.2022 15:22:20

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 28.JUN.2022 15:22:38

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 28.JUN.2022 15:22:58

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 28.JUN.2022 15:23:13

Band 2_3 MHz_High_QPSK_RB15#0




Date: 28.JUN.2022 15:23:32

Band 2_3 MHz_High_16QAM_RB15#0




Date: 28.JUN.2022 15:23:49

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 6.JUL.2022 16:59:18

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 6.JUL.2022 17:01:00

Band 2_5 MHz_High_QPSK_RB25#0




Date: 6.JUL.2022 17:07:10

Band 2_5 MHz_High_16QAM_RB25#0




Date: 6.JUL.2022 17:05:34

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 28.JUN.2022 15:25:17

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 28.JUN.2022 15:25:33

Band 2_10 MHz_High_QPSK_RB50#0




Date: 28.JUN.2022 15:25:50

Band 2_10 MHz_High_16QAM_RB50#0




Date: 28.JUN.2022 15:26:09

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 28.JUN.2022 15:26:29

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 28.JUN.2022 15:26:50

Band 2_15 MHz_High_QPSK_RB75#0




Date: 28.JUN.2022 15:27:09

Band 2_15 MHz_High_16QAM_RB75#0




Date: 28.JUN.2022 15:27:27

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 28.JUN.2022 15:27:49

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 28.JUN.2022 15:28:07

Band 2_20 MHz_High_QPSK_RB100#0




Date: 28.JUN.2022 15:28:26

Band 2_20 MHz_High_16QAM_RB100#0




Date: 28.JUN.2022 15:28:44

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 28.JUN.2022 16:25:01

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 28.JUN.2022 16:25:22

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 28.JUN.2022 16:25:37

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 28.JUN.2022 16:25:52

Band 4_3 MHz_Low_QPSK_RB15#0



Date: 28.JUN.2022 16:26:10

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 28.JUN.2022 16:26:24

Band 4_3 MHz_High_QPSK_RB15#0




Date: 28.JUN.2022 16:26:40

Band 4_3 MHz_High_16QAM_RB15#0




Date: 28.JUN.2022 16:26:54

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 6.JUL.2022 17:13:06

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 6.JUL.2022 17:13:44

Band 4_5 MHz_High_QPSK_RB25#0




Date: 6.JUL.2022 17:15:23

Band 4_5 MHz_High_16QAM_RB25#0




Date: 6.JUL.2022 17:16:19

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 28.JUN.2022 16:28:20

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 28.JUN.2022 16:28:36

Band 4_10 MHz_High_QPSK_RB50#0




Date: 28.JUN.2022 16:28:52

Band 4_10 MHz_High_16QAM_RB50#0




Date: 28.JUN.2022 16:29:08

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 28.JUN.2022 16:29:30

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 28.JUN.2022 16:29:52

Band 4_15 MHz_High_QPSK_RB75#0




Date: 28.JUN.2022 16:30:10

Band 4_15 MHz_High_16QAM_RB75#0




Date: 28.JUN.2022 16:30:28

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 28.JUN.2022 16:30:49

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 28.JUN.2022 16:31:11

Band 4_20 MHz_High_QPSK_RB100#0




Date: 28.JUN.2022 16:31:33

Band 4_20 MHz_High_16QAM_RB100#0




Date: 28.JUN.2022 16:31:51

Band 5& Band 26(Part 22H)_1.4 MHz_Low_QPSK_RB6#0




Date: 28.JUN.2022 18:34:02

Band 5& Band 26(Part 22H)_1.4 MHz_Low_16QAM_RB6#0




Date: 28.JUN.2022 18:34:20

Band 5& Band 26(Part 22H)_1.4 MHz_High_QPSK_RB6#0




Date: 28.JUN.2022 18:34:38

Band 5& Band 26(Part 22H)_1.4 MHz_High_16QAM_RB6#0




Date: 28.JUN.2022 18:34:56

Band 5& Band 26(Part 22H)_3 MHz_Low_QPSK_RB15#0




Date: 28.JUN.2022 18:35:13

Band 5& Band 26(Part 22H)_3 MHz_Low_16QAM_RB15#0




Date: 28.JUN.2022 18:35:28

Band 5& Band 26(Part 22H)_3 MHz_High_QPSK_RB15#0




Date: 28.JUN.2022 18:35:43

Band 5& Band 26(Part 22H)_3 MHz_High_16QAM_RB15#0




Date: 28.JUN.2022 18:36:01

Band 5& Band 26(Part 22H)_5 MHz_Low_QPSK_RB25#0




Date: 6.JUL.2022 17:19:27

Band 5& Band 26(Part 22H)_5 MHz_Low_16QAM_RB25#0




Date: 6.JUL.2022 17:21:06

Band 5& Band 26(Part 22H)_5 MHz_High_QPSK_RB25#0




Date: 6.JUL.2022 17:22:22

Band 5& Band 26(Part 22H)_5 MHz_High_16QAM_RB25#0




Date: 6.JUL.2022 17:23:09

Band 5& Band 26(Part 22H)_10 MHz_Low_QPSK_RB50#0




Date: 28.JUN.2022 18:37:26

Band 5& Band 26(Part 22H)_10 MHz_Low_16QAM_RB50#0




Date: 28.JUN.2022 18:37:45

Band 5& Band 26(Part 22H)_10 MHz_High_QPSK_RB50#0




Date: 28.JUN.2022 18:38:04

Band 5& Band 26(Part 22H)_10 MHz_High_16QAM_RB50#0




Date: 28.JUN.2022 18:38:20

Band 26(Part 22H)_15 MHz_Low_QPSK_RB75#0




Date: 7.JUL.2022 10:26:42

Band 26(Part 22H)_15 MHz_Low_16QAM_RB75#0




Date: 7.JUL.2022 10:27:03

Band 26(Part 22H)_15 MHz_High_QPSK_RB75#0




Date: 7.JUL.2022 10:27:21

Band 26(Part 22H)_15 MHz_High_16QAM_RB75#0




Date: 7.JUL.2022 10:27:39

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 6.JUL.2022 17:27:34

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 6.JUL.2022 17:28:10

Band 7_5 MHz_High_QPSK_RB25#0




Date: 6.JUL.2022 17:29:49

Band 7_5 MHz_High_16QAM_RB25#0




Date: 6.JUL.2022 17:30:30

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 28.JUN.2022 19:04:36

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 28.JUN.2022 19:04:51

Band 7_10 MHz_High_QPSK_RB50#0




Date: 28.JUN.2022 19:05:08

Band 7_10 MHz_High_16QAM_RB50#0




Date: 28.JUN.2022 19:05:27

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 28.JUN.2022 19:05:47

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 28.JUN.2022 19:06:09

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 28.JUN.2022 19:07:10

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 28.JUN.2022 19:07:28

Band 7_20 MHz_High_QPSK_RB100#0




Date: 28.JUN.2022 19:07:47

Band 7_20 MHz_High_16QAM_RB100#0




Date: 28.JUN.2022 19:08:08

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 28.JUN.2022 19:43:26

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 28.JUN.2022 19:43:43

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 28.JUN.2022 19:43:59

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 28.JUN.2022 19:44:17

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 28.JUN.2022 19:44:34

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 28.JUN.2022 19:44:48

Band 12_3 MHz_High_QPSK_RB15#0




Date: 28.JUN.2022 19:45:04

Band 12_3 MHz_High_16QAM_RB15#0




Date: 28.JUN.2022 19:45:18

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 6.JUL.2022 17:33:40

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 28.JUN.2022 19:45:57

Band 12_5 MHz_High_QPSK_RB25#0




Date: 6.JUL.2022 17:35:11

Band 12_5 MHz_High_16QAM_RB25#0




Date: 6.JUL.2022 17:35:54

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 28.JUN.2022 19:46:46

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 28.JUN.2022 19:47:04

Band 12_10 MHz_High_QPSK_RB50#0




Date: 28.JUN.2022 19:47:21

Band 12_10 MHz_High_16QAM_RB50#0




Date: 28.JUN.2022 19:47:37

Band 25_1.4 MHz_Low_QPSK_RB6#0




Date: 28.JUN.2022 20:42:32

Band 25_1.4 MHz_Low_16QAM_RB6#0




Date: 28.JUN.2022 20:42:50

Band 25_1.4 MHz_High_QPSK_RB6#0




Date: 28.JUN.2022 20:43:05

Band 25_1.4 MHz_High_16QAM_RB6#0




Date: 28.JUN.2022 20:43:23

Band 25_3 MHz_Low_QPSK_RB15#0




Date: 28.JUN.2022 20:43:41

Band 25_3 MHz_Low_16QAM_RB15#0




Date: 28.JUN.2022 20:43:56

Band 25_3 MHz_High_QPSK_RB15#0




Date: 28.JUN.2022 20:44:11

Band 25_3 MHz_High_16QAM_RB15#0




Date: 28.JUN.2022 20:44:25

Band 25_5 MHz_Low_QPSK_RB25#0




Date: 6.JUL.2022 17:39:25

Band 25_5 MHz_Low_16QAM_RB25#0




Date: 6.JUL.2022 17:39:59

Band 25_5 MHz_High_QPSK_RB25#0




Date: 6.JUL.2022 17:41:29

Band 25_5 MHz_High_16QAM_RB25#0




Date: 6.JUL.2022 17:42:13

Band 25_10 MHz_Low_QPSK_RB50#0




Date: 28.JUN.2022 20:45:54

Band 25_10 MHz_Low_16QAM_RB50#0




Date: 28.JUN.2022 20:46:10

Band 25_10 MHz_High_QPSK_RB50#0




Date: 28.JUN.2022 20:46:29

Band 25_10 MHz_High_16QAM_RB50#0




Date: 28.JUN.2022 20:46:48

Band 25_15 MHz_Low_QPSK_RB75#0




Date: 6.JUL.2022 17:51:06

Band 25_15 MHz_Low_16QAM_RB75#0




Date: 28.JUN.2022 20:47:27

Band 25_15 MHz_High_QPSK_RB75#0




Date: 28.JUN.2022 20:47:46

Band 25_15 MHz_High_16QAM_RB75#0




Date: 28.JUN.2022 20:48:04

Band 25_20 MHz_Low_QPSK_RB100#0




Date: 28.JUN.2022 20:48:29

Band 25_20 MHz_Low_16QAM_RB100#0




Date: 28.JUN.2022 20:48:47

Band 25_20 MHz_High_QPSK_RB100#0




Date: 28.JUN.2022 20:49:06

Band 25_20 MHz_High_16QAM_RB100#0




Date: 28.JUN.2022 20:49:24

Band 26(Part 90S)_1.4 MHz_Low_QPSK_RB6#0




Date: 7.JUL.2022 09:28:36

Band 26(Part 90S)_1.4 MHz_Low_16QAM_RB6#0




Date: 7.JUL.2022 09:29:02

Band 26(Part 90S)_1.4 MHz_High_QPSK_RB6#0




Date: 7.JUL.2022 09:30:49

Band 26(Part 90S)_1.4 MHz_High_16QAM_RB6#0




Date: 7.JUL.2022 09:31:28

Band 26(Part 90S)_3 MHz_Low_QPSK_RB15#0




Date: 7.JUL.2022 09:32:54

Band 26(Part 90S)_3 MHz_Low_16QAM_RB15#0




Date: 7.JUL.2022 09:33:30

Band 26(Part 90S)_3 MHz_High_QPSK_RB15#0




Date: 7.JUL.2022 09:35:25

Band 26(Part 90S)_3 MHz_High_16QAM_RB15#0




Date: 7.JUL.2022 09:34:10

Band 26(Part 90S)_5 MHz_Low_QPSK_RB25#0




Date: 7.JUL.2022 09:36:40

Band 26(Part 90S)_5 MHz_Low_16QAM_RB25#0




Date: 7.JUL.2022 09:37:07

Band 26(Part 90S)_5 MHz_High_QPSK_RB25#0




Date: 7.JUL.2022 09:38:17

Band 26(Part 90S)_5 MHz_High_16QAM_RB25#0




Date: 7.JUL.2022 09:38:54

Band 26(Part 90S)_10 MHz_Low_QPSK_RB50#0




Date: 7.JUL.2022 09:42:13

Band 26(Part 90S)_10 MHz_Low_16QAM_RB50#0




Date: 7.JUL.2022 09:42:37

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 2.JUL.2022 17:09:16

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 6.JUL.2022 17:57:09

Band 41_5 MHz_High_QPSK_RB25#0




Date: 6.JUL.2022 18:00:09

Band 41_5 MHz_High_16QAM_RB25#0




Date: 6.JUL.2022 18:01:04

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 2.JUL.2022 17:10:41

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 2.JUL.2022 17:11:00

Band 41_10 MHz_High_QPSK_RB50#0




Date: 2.JUL.2022 17:11:20

Band 41_10 MHz_High_16QAM_RB50#0




Date: 2.JUL.2022 17:11:41

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 2.JUL.2022 17:12:10

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 2.JUL.2022 17:12:40

Band 41_15 MHz_High_QPSK_RB75#0




Date: 6.JUL.2022 18:07:36

Band 41_15 MHz_High_16QAM_RB75#0




Date: 2.JUL.2022 17:13:26

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 2.JUL.2022 17:13:51

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 2.JUL.2022 17:14:12

Band 41_20 MHz_High_QPSK_RB100#0




Date: 2.JUL.2022 17:14:34

Band 41_20 MHz_High_16QAM_RB100#0




Date: 2.JUL.2022 17:14:58

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 29.JUN.2022 19:13:57

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 29.JUN.2022 19:14:15

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 29.JUN.2022 19:14:33

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 29.JUN.2022 19:14:51

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 29.JUN.2022 19:15:07

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 29.JUN.2022 19:15:22

Band 66_3 MHz_High_QPSK_RB15#0




Date: 29.JUN.2022 19:15:37

Band 66_3 MHz_High_16QAM_RB15#0




Date: 29.JUN.2022 19:15:51

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 6.JUL.2022 18:10:49

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 6.JUL.2022 18:11:20

Band 66_5 MHz_High_QPSK_RB25#0




Date: 6.JUL.2022 18:12:32

Band 66_5 MHz_High_16QAM_RB25#0




Date: 6.JUL.2022 18:13:24

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 29.JUN.2022 19:17:16

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 29.JUN.2022 19:17:31

Band 66_10 MHz_High_QPSK_RB50#0




Date: 29.JUN.2022 19:17:48

Band 66_10 MHz_High_16QAM_RB50#0




Date: 29.JUN.2022 19:18:03

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 29.JUN.2022 19:18:23

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 29.JUN.2022 19:18:41

Band 66_15 MHz_High_QPSK_RB75#0




Date: 6.JUL.2022 18:15:36

Band 66_15 MHz_High_16QAM_RB75#0




Date: 29.JUN.2022 19:19:18

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 29.JUN.2022 19:19:37

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 29.JUN.2022 19:19:58

Band 66_20 MHz_High_QPSK_RB100#0




Date: 29.JUN.2022 19:20:17

Band 66_20 MHz_High_16QAM_RB100#0




Date: 29.JUN.2022 19:20:38

Band 71_5 MHz_Low_QPSK_RB25#0




Date: 7.JUL.2022 08:59:33

Band 71_5 MHz_Low_16QAM_RB25#0




Date: 7.JUL.2022 09:00:12

Band 71_5 MHz_High_QPSK_RB25#0




Date: 7.JUL.2022 09:03:12

Band 71_5 MHz_High_16QAM_RB25#0




Date: 7.JUL.2022 09:01:44

Band 71_10 MHz_Low_QPSK_RB50#0




Date: 29.JUN.2022 16:56:48

Band 71_10 MHz_Low_16QAM_RB50#0




Date: 29.JUN.2022 16:57:06

Band 71_10 MHz_High_QPSK_RB50#0




Date: 29.JUN.2022 16:57:23

Band 71_10 MHz_High_16QAM_RB50#0




Date: 29.JUN.2022 16:57:38

Band 71_15 MHz_Low_QPSK_RB75#0




Date: 29.JUN.2022 16:58:00

Band 71_15 MHz_Low_16QAM_RB75#0




Date: 29.JUN.2022 16:58:17

Band 71_15 MHz_High_QPSK_RB75#0




Date: 29.JUN.2022 16:58:36

Band 71_15 MHz_High_16QAM_RB75#0




Date: 29.JUN.2022 16:58:54

Band 71_20 MHz_Low_QPSK_RB100#0




Date: 29.JUN.2022 16:59:15

Band 71_20 MHz_Low_16QAM_RB100#0




Date: 29.JUN.2022 16:59:33

Band 71_20 MHz_High_QPSK_RB100#0



Date: 29.JUN.2022 16:59:52

Band 71_20 MHz_High_16QAM_RB100#0



Date: 29.JUN.2022 17:00:13