

Report No.: TB-FCC142548

Page: 1 of 8

Appendix I FCC ID Label

FCC ID: 2ADVR3300

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- 1. This device may not cause harmful interference, and
- 2. This device must accept any interference received, including interference that may cause undesired operation.

Zhongshan Auto Electronics Technology Co., Ltd.

Model: 3300