Date: June 24, 2016

## **Declaration**

We, AcSiP Technology Corporation, declare that the device, FCC ID: 2ADWC-AI7688H, does not support any non-US channels in all the operational mode(s). All non-US frequencies and Country code selection are disabled through proprietary software and is not user changeable.

Should you have any question or comment regarding this matter, please do not hesitate to contact me.

Sincerely yours,

Sam Hus / Director

**AcSiP Technology Corporation** 

Tel: +886 3 286 8388 Fax: +886 3 347 5000

E-mail: DCC@acsip.com.tw