

Report No. : EED32N00009701 Page 36 of 48



View of Product-7














View of Product-10
















Report No. : EED32N00009701 Page 38 of 48



View of Product-11



View of Product-12






Report No. : EED32N00009701 Page 39 of 48



View of Product-13



View of Product-14
















View of Product-15



View of Product-16



















View of Product-17



View of Product-18



















View of Product-19



View of Product-20




















View of Product-21



View of Product-22






















View of Product-24





















View of Product-25



View of Product-26



















View of Product-27



View of Product-28




















View of Product-29



View of Product-30














Report No. : EED32N00009701 Page 48 of 48



View of Product-31

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

*** End of Report ***

