



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 19.NOV.2021 13:31:58

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 19.NOV.2021 13:32:16

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.NOV.2021 13:32:34

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.NOV.2021 13:32:52

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 19.NOV.2021 13:33:10

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 19.NOV.2021 13:33:30

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 19.NOV.2021 13:33:49

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 19.NOV.2021 13:34:07

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 19.NOV.2021 13:34:25

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 19.NOV.2021 13:34:39

Band 2_3 MHz_High_QPSK_RB15#0




Date: 19.NOV.2021 13:34:54

Band 2_3 MHz_High_16QAM_RB15#0




Date: 19.NOV.2021 13:35:11

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 19.NOV.2021 13:35:31

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 19.NOV.2021 13:35:45

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 9.DEC.2021 23:29:39

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 19.NOV.2021 13:36:27

Band 2_5 MHz_High_QPSK_RB25#0




Date: 19.NOV.2021 13:36:48

Band 2_5 MHz_High_16QAM_RB25#0




Date: 19.NOV.2021 13:37:12

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 19.NOV.2021 13:37:45

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 19.NOV.2021 13:38:03

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 19.NOV.2021 13:38:28

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 19.NOV.2021 13:38:57

Band 2_10 MHz_High_QPSK_RB50#0




Date: 19.NOV.2021 13:39:25

Band 2_10 MHz_High_16QAM_RB50#0




Date: 19.NOV.2021 13:39:50

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 19.NOV.2021 13:40:19

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 19.NOV.2021 13:40:46

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 19.NOV.2021 13:41:16

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 19.NOV.2021 13:41:44

Band 2_15 MHz_High_QPSK_RB75#0




Date: 19.NOV.2021 13:42:17

Band 2_15 MHz_High_16QAM_RB75#0




Date: 19.NOV.2021 13:42:45

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 19.NOV.2021 13:43:17

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 19.NOV.2021 13:43:40

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 19.NOV.2021 13:44:14

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 19.NOV.2021 13:44:45

Band 2_20 MHz_High_QPSK_RB100#0




Date: 19.NOV.2021 13:45:22

Band 2_20 MHz_High_16QAM_RB100#0




Date: 19.NOV.2021 13:45:49

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 19.NOV.2021 13:46:05

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 19.NOV.2021 13:46:22

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.NOV.2021 13:46:40

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.NOV.2021 13:46:55

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 19.NOV.2021 13:47:13

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 19.NOV.2021 13:47:27

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 19.NOV.2021 13:47:46

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 19.NOV.2021 13:48:04

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 19.NOV.2021 13:48:25

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 19.NOV.2021 13:48:43

Band 4_3 MHz_High_QPSK_RB15#0




Date: 19.NOV.2021 13:49:04

Band 4_3 MHz_High_16QAM_RB15#0




Date: 19.NOV.2021 13:49:24

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 19.NOV.2021 13:49:47

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 19.NOV.2021 13:50:04

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 19.NOV.2021 13:50:22

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 19.NOV.2021 13:50:36

Band 4_5 MHz_High_QPSK_RB25#0




Date: 19.NOV.2021 13:51:01

Band 4_5 MHz_High_16QAM_RB25#0




Date: 19.NOV.2021 13:51:18

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 19.NOV.2021 13:51:48

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 19.NOV.2021 13:52:13

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 19.NOV.2021 13:52:41

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 19.NOV.2021 13:53:09

Band 4_10 MHz_High_QPSK_RB50#0




Date: 19.NOV.2021 13:53:35

Band 4_10 MHz_High_16QAM_RB50#0




Date: 19.NOV.2021 13:54:01

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 19.NOV.2021 13:54:23

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 19.NOV.2021 13:54:57

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 19.NOV.2021 13:55:24

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 19.NOV.2021 13:55:54

Band 4_15 MHz_High_QPSK_RB75#0




Date: 19.NOV.2021 13:56:25

Band 4_15 MHz_High_16QAM_RB75#0




Date: 19.NOV.2021 13:56:49

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 19.NOV.2021 13:57:14

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 19.NOV.2021 13:57:48

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 19.NOV.2021 13:58:19

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 19.NOV.2021 13:58:52

Band 4_20 MHz_High_QPSK_RB100#0




Date: 19.NOV.2021 13:59:20

Band 4_20 MHz_High_16QAM_RB100#0




Date: 20.NOV.2021 11:42:44

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 19.NOV.2021 14:00:02

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 19.NOV.2021 14:00:17

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.NOV.2021 14:00:32

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.NOV.2021 14:00:49

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 19.NOV.2021 14:01:04

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 19.NOV.2021 14:01:19

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 19.NOV.2021 14:01:37

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 19.NOV.2021 14:01:55

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 19.NOV.2021 14:02:13

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 19.NOV.2021 14:02:27

Band 5_3 MHz_High_QPSK_RB15#0




Date: 19.NOV.2021 14:02:42

Band 5_3 MHz_High_16QAM_RB15#0




Date: 19.NOV.2021 14:02:57

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 19.NOV.2021 14:03:16

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 19.NOV.2021 14:03:33

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 19.NOV.2021 14:03:52

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 19.NOV.2021 14:04:09

Band 5_5 MHz_High_QPSK_RB25#0




Date: 19.NOV.2021 14:04:27

Band 5_5 MHz_High_16QAM_RB25#0




Date: 19.NOV.2021 14:04:45

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 19.NOV.2021 14:05:08

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 19.NOV.2021 14:05:33

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 19.NOV.2021 14:05:55

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 19.NOV.2021 14:06:20

Band 5_10 MHz_High_QPSK_RB50#0




Date: 19.NOV.2021 14:06:46

Band 5_10 MHz_High_16QAM_RB50#0




Date: 19.NOV.2021 14:07:10

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 19.NOV.2021 14:07:29

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 19.NOV.2021 14:07:47

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 19.NOV.2021 14:08:05

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 19.NOV.2021 14:08:32

Band 7_5 MHz_High_QPSK_RB25#0




Date: 19.NOV.2021 14:08:53

Band 7_5 MHz_High_16QAM_RB25#0




Date: 19.NOV.2021 14:09:11

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 19.NOV.2021 14:09:37

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 19.NOV.2021 14:10:02

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 19.NOV.2021 14:10:27

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 19.NOV.2021 14:10:52

Band 7_10 MHz_High_QPSK_RB50#0




Date: 19.NOV.2021 14:11:17

Band 7_10 MHz_High_16QAM_RB50#0




Date: 19.NOV.2021 14:11:39

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 20.NOV.2021 15:01:43

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 20.NOV.2021 15:02:13

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 20.NOV.2021 15:02:45

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 20.NOV.2021 15:03:09

Band 7_15 MHz_High_QPSK_RB75#0




Date: 20.NOV.2021 15:03:30

Band 7_15 MHz_High_16QAM_RB75#0




Date: 20.NOV.2021 15:04:04

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 20.NOV.2021 15:04:31

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 20.NOV.2021 15:04:58

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 20.NOV.2021 15:05:26

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 20.NOV.2021 15:05:46

Band 7_20 MHz_High_QPSK_RB100#0




Date: 20.NOV.2021 15:06:11

Band 7_20 MHz_High_16QAM_RB100#0




Date: 20.NOV.2021 15:06:45

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 19.NOV.2021 16:29:45

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 19.NOV.2021 16:30:05

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 19.NOV.2021 16:30:24

Band 38_5 MHz_Middle_16QAM_RB25#0




Date: 19.NOV.2021 16:30:44


Band 38_5 MHz_High_QPSK_RB25#0



Band 38_5 MHz_High_16QAM_RB25#0




Band 38_10 MHz_Low_QPSK_RB50#0




Date: 19.NOV.2021 16:31:41

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 19.NOV.2021 16:31:56

Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 19.NOV.2021 16:32:28

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 19.NOV.2021 16:32:53

Band 38_10 MHz_High_QPSK_RB50#0




Date: 19.NOV.2021 16:33:18

Band 38_10 MHz_High_16QAM_RB50#0




Date: 19.NOV.2021 16:33:46

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 19.NOV.2021 16:34:16

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 19.NOV.2021 16:34:43

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 19.NOV.2021 16:35:10

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 19.NOV.2021 16:35:47

Band 38_15 MHz_High_QPSK_RB75#0




Date: 19.NOV.2021 16:36:11

Band 38_15 MHz_High_16QAM_RB75#0




Date: 19.NOV.2021 16:36:42

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 19.NOV.2021 16:37:15

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 19.NOV.2021 16:37:42

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 19.NOV.2021 16:38:06

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 19.NOV.2021 16:38:43

Band 38_20 MHz_High_QPSK_RB100#0




Date: 19.NOV.2021 16:39:14

Band 38_20 MHz_High_16QAM_RB100#0




Date: 19.NOV.2021 16:39:44

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 19.NOV.2021 17:30:24

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 19.NOV.2021 17:30:44

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 19.NOV.2021 17:31:06

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 19.NOV.2021 17:31:26

Band 41_5 MHz_High_QPSK_RB25#0




Date: 19.NOV.2021 17:31:47

Band 41_5 MHz_High_16QAM_RB25#0




Date: 19.NOV.2021 17:32:08

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 19.NOV.2021 17:32:38

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 19.NOV.2021 17:33:00

Band 41_10 MHz_Middle_QPSK_RB50#0




Date: 19.NOV.2021 17:33:25

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 19.NOV.2021 17:33:50

Band 41_10 MHz_High_QPSK_RB50#0




Date: 19.NOV.2021 17:34:16

Band 41_10 MHz_High_16QAM_RB50#0




Date: 19.NOV.2021 17:34:37

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 19.NOV.2021 17:35:07

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 19.NOV.2021 17:35:31

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 19.NOV.2021 17:35:59

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 19.NOV.2021 17:36:26

Band 41_15 MHz_High_QPSK_RB75#0




Date: 19.NOV.2021 17:36:57

Band 41_15 MHz_High_16QAM_RB75#0




Date: 19.NOV.2021 17:37:30


Band 41_20 MHz_Low_QPSK_RB100#0



Band 41_20 MHz_Low_16QAM_RB100#0




Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 19.NOV.2021 17:38:51

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 19.NOV.2021 17:39:21

Band 41_20 MHz_High_QPSK_RB100#0



Date: 19.NOV.2021 17:39:46

Band 41_20 MHz_High_16QAM_RB100#0



Date: 19.NOV.2021 17:40:19