



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:10:07

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.DEC.2021 14:56:42

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:11:03

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.DEC.2021 14:57:11

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:12:04

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.DEC.2021 14:57:37

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:13:06

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.DEC.2021 14:54:46

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:13:51

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.DEC.2021 14:52:49

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:14:43

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.DEC.2021 14:51:42

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:15:39

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:16:07

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:16:37

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:17:02

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:17:25

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:17:45

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:18:22

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:18:50

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:19:21

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:19:43

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:20:11

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:20:33

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:21:13

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:21:38

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:22:10

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:22:38

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:23:11

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:23:43

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:24:24

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:24:49

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:25:19

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:25:45

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:26:17

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:26:41

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:27:10

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.DEC.2021 14:59:47

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:28:08

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.DEC.2021 14:58:50

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:29:00

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 10.DEC.2021 15:00:25

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:29:57

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.DEC.2021 15:03:17

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:30:55

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.DEC.2021 15:05:22

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:31:57

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 10.DEC.2021 15:08:23

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:33:00

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:33:22

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:33:48

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:34:17

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:34:47

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:35:12

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:35:48

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:36:10

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:36:41

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:37:04

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:37:34

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:38:00

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:38:38

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:38:57

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:39:30

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:39:55

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:40:22

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:40:38

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:41:16

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:41:45

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:42:21

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:42:43

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:43:25

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 10.DEC.2021 00:43:54

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:44:20

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:44:39


Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)



Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:46:04

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:46:26

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:47:04

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:47:29

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:47:52

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:48:18

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:48:50

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:49:16

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:49:48

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:50:13

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:50:39

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:51:02

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:51:28

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:51:50

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:52:26

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:52:49

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:53:19

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:53:45

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:54:15

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 10.DEC.2021 00:54:44

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:55:19

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 00:55:47

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:56:11

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 00:56:33

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:57:06

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 00:57:31

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:58:01

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 00:58:23

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:58:51

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 00:59:19

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 10.DEC.2021 00:59:50

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 01:00:12

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.DEC.2021 01:00:47

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 01:01:07

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.DEC.2021 01:01:39

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 01:02:05

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 10.DEC.2021 01:02:38

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 01:03:03

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.DEC.2021 01:03:38

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 01:04:04

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.DEC.2021 01:04:33

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 01:04:53

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 10.DEC.2021 01:05:26

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 10.DEC.2021 01:05:54

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.NOV.2021 16:51:39

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 16:52:04

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.NOV.2021 16:52:34

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 16:52:56

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.NOV.2021 16:53:22

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 16:53:48

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.NOV.2021 16:54:27

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 16:54:50

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.NOV.2021 16:55:20

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 16:55:49

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.NOV.2021 16:56:19

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 16:56:42

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.NOV.2021 16:57:13

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 16:57:39

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.NOV.2021 16:58:05

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 16:58:28

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.NOV.2021 16:59:04

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 16:59:32

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.NOV.2021 17:00:07

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 17:00:33

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.NOV.2021 17:01:05

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 17:01:31

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.NOV.2021 17:02:04

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 17:02:23

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:00:56

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:01:18

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:01:53

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:02:18

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:02:48

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:03:10

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:03:49

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:04:11

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:04:42

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:05:04

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:05:38

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:05:57

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:06:35

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:06:55

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:07:27

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:07:56

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:08:25

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:08:51

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:09:23

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:09:45

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 19.NOV.2021 18:10:21

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 19.NOV.2021 18:10:47

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 19.NOV.2021 18:11:19

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 19.NOV.2021 18:11:42