



Please refer to following plots:

Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 19.NOV.2021 14:26:46

Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 19.NOV.2021 14:27:01

Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 19.NOV.2021 14:27:16

Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 19.NOV.2021 14:27:30

Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 19.NOV.2021 14:27:53

Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 19.NOV.2021 14:28:10

Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 19.NOV.2021 14:28:28

Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 19.NOV.2021 14:28:42

Band 2\_5 MHz\_Low\_QPSK\_RB25#0



Date: 20.NOV.2021 11:51:03


Band 2\_5 MHz\_Low\_16QAM\_RB25#0



Date: 20.NOV.2021 11:51:57




Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 19.NOV.2021 14:29:36

Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 19.NOV.2021 14:29:50

Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 19.NOV.2021 14:30:11

Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 19.NOV.2021 14:30:32

Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 19.NOV.2021 14:30:58


Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 19.NOV.2021 14:31:28




Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 19.NOV.2021 14:31:58

Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 19.NOV.2021 14:32:28

Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 19.NOV.2021 14:32:55

Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 19.NOV.2021 14:33:22

Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 19.NOV.2021 14:33:54

Band 2\_20 MHz\_Low\_16QAM\_RB100#0



Date: 19.NOV.2021 14:34:18

### Band 2\_20 MHz\_High\_QPSK\_RB100#0



Date: 19.NOV.2021 14:34:52


### Band 2\_20 MHz\_High\_16QAM\_RB100#0



Date: 19.NOV.2021 14:35:22




Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 19.NOV.2021 14:35:41

Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 19.NOV.2021 14:36:01

Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 19.NOV.2021 14:36:23

Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 19.NOV.2021 14:36:40

Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 19.NOV.2021 14:36:57

Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 19.NOV.2021 14:37:14

Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 19.NOV.2021 14:37:28


Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 19.NOV.2021 14:37:45




Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 19.NOV.2021 14:38:02

Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 19.NOV.2021 14:38:19

Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 19.NOV.2021 14:38:40

Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 20.NOV.2021 11:54:11

Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 19.NOV.2021 14:39:18

Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 19.NOV.2021 14:39:46

Band 4\_10 MHz\_High\_QPSK\_RB50#0



Date: 19.NOV.2021 14:40:05


Band 4\_10 MHz\_High\_16QAM\_RB50#0



Date: 19.NOV.2021 14:40:29




Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 19.NOV.2021 14:40:59

Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 19.NOV.2021 14:41:23

Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 19.NOV.2021 14:41:53

Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 19.NOV.2021 14:42:23

Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 19.NOV.2021 14:42:46

Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 19.NOV.2021 14:43:16

Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 19.NOV.2021 14:43:50


Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 19.NOV.2021 14:44:17




Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 9.DEC.2021 23:52:14

Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 9.DEC.2021 23:52:37

Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 9.DEC.2021 23:53:01

Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 9.DEC.2021 23:53:18

Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 9.DEC.2021 23:53:42

Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 9.DEC.2021 23:54:02

Band 5\_3 MHz\_High\_QPSK\_RB15#0



Date: 9.DEC.2021 23:54:23


Band 5\_3 MHz\_High\_16QAM\_RB15#0



Date: 9.DEC.2021 23:54:47




Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 10.DEC.2021 01:09:18

Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 9.DEC.2021 23:55:58

Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 9.DEC.2021 23:56:22

Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 10.DEC.2021 01:10:04


Band 5\_10 MHz\_Low\_QPSK\_RB50#0



Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 9.DEC.2021 23:58:30


Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 9.DEC.2021 23:59:10




Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 19.NOV.2021 14:49:52

Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 19.NOV.2021 14:50:09

Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 19.NOV.2021 14:50:27

Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 19.NOV.2021 14:50:41

Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 19.NOV.2021 14:51:05

Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 19.NOV.2021 14:51:20

Band 7\_10 MHz\_High\_QPSK\_RB50#0



Date: 19.NOV.2021 14:51:45


Band 7\_10 MHz\_High\_16QAM\_RB50#0



Date: 19.NOV.2021 14:52:10




Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 19.NOV.2021 14:52:39

Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 19.NOV.2021 14:53:06

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 19.NOV.2021 14:53:24

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 19.NOV.2021 14:53:53

Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 19.NOV.2021 14:54:30

Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 19.NOV.2021 14:54:53

Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 19.NOV.2021 14:55:17


Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 19.NOV.2021 14:55:47




Band 38\_5 MHz\_Low\_QPSK\_RB25#0




Date: 19.NOV.2021 16:43:50

Band 38\_5 MHz\_Low\_16QAM\_RB25#0




Date: 19.NOV.2021 16:44:07

Band 38\_5 MHz\_High\_QPSK\_RB25#0




Date: 20.NOV.2021 11:28:50

Band 38\_5 MHz\_High\_16QAM\_RB25#0




Date: 19.NOV.2021 16:44:41

Band 38\_10 MHz\_Low\_QPSK\_RB50#0




Date: 19.NOV.2021 16:45:08

Band 38\_10 MHz\_Low\_16QAM\_RB50#0




Date: 19.NOV.2021 16:45:42

Band 38\_10 MHz\_High\_QPSK\_RB50#0



Date: 19.NOV.2021 16:46:04


Band 38\_10 MHz\_High\_16QAM\_RB50#0



Date: 19.NOV.2021 16:46:25




Band 38\_15 MHz\_Low\_QPSK\_RB75#0




Date: 19.NOV.2021 16:46:55

Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 19.NOV.2021 16:47:15

Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 19.NOV.2021 16:47:45

Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 19.NOV.2021 16:48:09

Band 38\_20 MHz\_Low\_QPSK\_RB100#0




Date: 19.NOV.2021 16:48:38

Band 38\_20 MHz\_Low\_16QAM\_RB100#0




Date: 19.NOV.2021 16:49:08

Band 38\_20 MHz\_High\_QPSK\_RB100#0



Date: 19.NOV.2021 16:49:41


Band 38\_20 MHz\_High\_16QAM\_RB100#0



Date: 19.NOV.2021 16:50:08




Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 19.NOV.2021 17:53:10

Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 19.NOV.2021 17:53:24

Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 19.NOV.2021 17:53:44

Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 19.NOV.2021 17:54:05

Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 19.NOV.2021 17:54:35

Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 19.NOV.2021 17:54:56

Band 41\_10 MHz\_High\_QPSK\_RB50#0



Date: 19.NOV.2021 17:55:18


Band 41\_10 MHz\_High\_16QAM\_RB50#0



Date: 19.NOV.2021 17:55:42




Band 41\_15 MHz\_Low\_QPSK\_RB75#0




Date: 19.NOV.2021 17:56:12

Band 41\_15 MHz\_Low\_16QAM\_RB75#0




Date: 19.NOV.2021 17:56:32

Band 41\_15 MHz\_High\_QPSK\_RB75#0




Date: 19.NOV.2021 17:57:06

Band 41\_15 MHz\_High\_16QAM\_RB75#0




Date: 19.NOV.2021 17:57:36

Band 41\_20 MHz\_Low\_QPSK\_RB100#0




Date: 19.NOV.2021 17:58:05

Band 41\_20 MHz\_Low\_16QAM\_RB100#0




Date: 19.NOV.2021 17:58:35

Band 41\_20 MHz\_High\_QPSK\_RB100#0



Date: 19.NOV.2021 17:59:12

Band 41\_20 MHz\_High\_16QAM\_RB100#0



Date: 19.NOV.2021 17:59:48