



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 3.MAR.2022 13:14:33

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 2.MAR.2022 15:02:07

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 2.MAR.2022 15:02:28

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 2.MAR.2022 15:02:51

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 2.MAR.2022 15:03:09

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 2.MAR.2022 15:03:26

Band 2_3 MHz_High_QPSK_RB15#0




Date: 2.MAR.2022 15:03:47

Band 2_3 MHz_High_16QAM_RB15#0




Date: 2.MAR.2022 15:04:10

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 3.MAR.2022 13:16:00

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 3.MAR.2022 13:16:46

Band 2_5 MHz_High_QPSK_RB25#0




Date: 3.MAR.2022 13:17:59

Band 2_5 MHz_High_16QAM_RB25#0




Date: 3.MAR.2022 13:40:58

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 2.MAR.2022 15:05:46

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 2.MAR.2022 15:06:05

Band 2_10 MHz_High_QPSK_RB50#0




Date: 2.MAR.2022 15:06:25

Band 2_10 MHz_High_16QAM_RB50#0




Date: 2.MAR.2022 15:06:44

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 2.MAR.2022 15:07:08

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 2.MAR.2022 15:07:32

Band 2_15 MHz_High_QPSK_RB75#0




Date: 2.MAR.2022 15:07:56

Band 2_15 MHz_High_16QAM_RB75#0




Date: 2.MAR.2022 15:08:20

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 2.MAR.2022 15:08:45

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 2.MAR.2022 15:09:08

Band 2_20 MHz_High_QPSK_RB100#0




Date: 2.MAR.2022 15:09:32

Band 2_20 MHz_High_16QAM_RB100#0




Date: 2.MAR.2022 15:09:59

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 2.MAR.2022 15:10:17

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 2.MAR.2022 15:10:34

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 2.MAR.2022 15:10:54

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 2.MAR.2022 15:11:14

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 2.MAR.2022 15:11:33

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 2.MAR.2022 15:11:53

Band 4_3 MHz_High_QPSK_RB15#0




Date: 2.MAR.2022 15:12:10

Band 4_3 MHz_High_16QAM_RB15#0




Date: 2.MAR.2022 15:12:27

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 3.MAR.2022 13:18:58

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 3.MAR.2022 13:19:34

Band 4_5 MHz_High_QPSK_RB25#0




Date: 3.MAR.2022 13:21:05

Band 4_5 MHz_High_16QAM_RB25#0




Date: 3.MAR.2022 13:20:31

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 2.MAR.2022 15:13:59

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 2.MAR.2022 15:14:18

Band 4_10 MHz_High_QPSK_RB50#0




Date: 2.MAR.2022 15:14:38

Band 4_10 MHz_High_16QAM_RB50#0




Date: 2.MAR.2022 15:14:57

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 2.MAR.2022 15:15:26

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 2.MAR.2022 15:15:50

Band 4_15 MHz_High_QPSK_RB75#0




Date: 2.MAR.2022 15:16:14

Band 4_15 MHz_High_16QAM_RB75#0




Date: 2.MAR.2022 15:16:40

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 2.MAR.2022 15:17:05

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 2.MAR.2022 15:17:32

Band 4_20 MHz_High_QPSK_RB100#0




Date: 2.MAR.2022 15:17:56

Band 4_20 MHz_High_16QAM_RB100#0




Date: 2.MAR.2022 15:18:20

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 2.MAR.2022 15:18:44

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 2.MAR.2022 15:19:04

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 2.MAR.2022 15:19:25

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 2.MAR.2022 15:19:45

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 2.MAR.2022 15:20:03

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 2.MAR.2022 15:20:20

Band 5_3 MHz_High_QPSK_RB15#0




Date: 2.MAR.2022 15:20:37

Band 5_3 MHz_High_16QAM_RB15#0




Date: 2.MAR.2022 15:20:54

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 3.MAR.2022 13:22:55

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 3.MAR.2022 13:23:37

Band 5_5 MHz_High_QPSK_RB25#0




Date: 3.MAR.2022 13:24:41

Band 5_5 MHz_High_16QAM_RB25#0




Date: 3.MAR.2022 13:24:13

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 2.MAR.2022 15:22:36

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 2.MAR.2022 15:22:55

Band 5_10 MHz_High_QPSK_RB50#0




Date: 2.MAR.2022 15:23:15

Band 5_10 MHz_High_16QAM_RB50#0




Date: 2.MAR.2022 15:23:37

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 3.MAR.2022 13:25:28

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 3.MAR.2022 13:26:17

Band 7_5 MHz_High_QPSK_RB25#0




Date: 3.MAR.2022 13:28:29

Band 7_5 MHz_High_16QAM_RB25#0




Date: 3.MAR.2022 13:27:24

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 2.MAR.2022 15:25:16

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 2.MAR.2022 15:25:35

Band 7_10 MHz_High_QPSK_RB50#0




Date: 2.MAR.2022 15:25:55

Band 7_10 MHz_High_16QAM_RB50#0




Date: 2.MAR.2022 15:26:11

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 2.MAR.2022 15:26:35

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 2.MAR.2022 15:26:59

Band 7_15 MHz_High_QPSK_RB75#0




Date: 2.MAR.2022 15:27:23

Band 7_15 MHz_High_16QAM_RB75#0




Date: 2.MAR.2022 15:27:46

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 2.MAR.2022 15:28:14

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 2.MAR.2022 15:28:41

Band 7_20 MHz_High_QPSK_RB100#0




Date: 2.MAR.2022 15:29:05

Band 7_20 MHz_High_16QAM_RB100#0




Date: 2.MAR.2022 15:29:32

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 2.MAR.2022 15:29:53

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 2.MAR.2022 15:30:16

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 2.MAR.2022 15:30:37

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 2.MAR.2022 15:30:56

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 2.MAR.2022 15:31:15

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 2.MAR.2022 15:31:32

Band 12_3 MHz_High_QPSK_RB15#0




Date: 2.MAR.2022 15:31:52

Band 12_3 MHz_High_16QAM_RB15#0




Date: 2.MAR.2022 15:32:12

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 3.MAR.2022 13:29:55

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 2.MAR.2022 15:32:53

Band 12_5 MHz_High_QPSK_RB25#0




Date: 3.MAR.2022 13:31:10

Band 12_5 MHz_High_16QAM_RB25#0




Date: 3.MAR.2022 13:31:44

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 2.MAR.2022 15:33:54

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 2.MAR.2022 15:34:13

Band 12_10 MHz_High_QPSK_RB50#0




Date: 2.MAR.2022 15:34:33

Band 12_10 MHz_High_16QAM_RB50#0




Date: 2.MAR.2022 15:34:52

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 3.MAR.2022 13:32:40

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 2.MAR.2022 15:35:34

Band 17_5 MHz_High_QPSK_RB25#0




Date: 3.MAR.2022 13:34:06

Band 17_5 MHz_High_16QAM_RB25#0




Date: 3.MAR.2022 13:33:19

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 2.MAR.2022 15:36:37

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 2.MAR.2022 15:36:56

Band 17_10 MHz_High_QPSK_RB50#0




Date: 2.MAR.2022 15:37:22

Band 17_10 MHz_High_16QAM_RB50#0




Date: 2.MAR.2022 15:37:41

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 2.MAR.2022 15:38:00

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 2.MAR.2022 15:38:19

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 2.MAR.2022 15:38:40

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 2.MAR.2022 15:39:00

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 2.MAR.2022 15:39:18

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 2.MAR.2022 15:39:38

Band 66_3 MHz_High_QPSK_RB15#0




Date: 2.MAR.2022 15:39:55

Band 66_3 MHz_High_16QAM_RB15#0




Date: 2.MAR.2022 15:40:15

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 2.MAR.2022 15:40:33

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 3.MAR.2022 13:36:28

Band 66_5 MHz_High_QPSK_RB25#0




Date: 3.MAR.2022 13:38:35

Band 66_5 MHz_High_16QAM_RB25#0




Date: 3.MAR.2022 13:39:33

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 2.MAR.2022 15:41:48

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 2.MAR.2022 15:42:07

Band 66_10 MHz_High_QPSK_RB50#0




Date: 2.MAR.2022 15:42:26

Band 66_10 MHz_High_16QAM_RB50#0




Date: 2.MAR.2022 15:42:45

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 2.MAR.2022 15:43:10

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 2.MAR.2022 15:43:34

Band 66_15 MHz_High_QPSK_RB75#0




Date: 2.MAR.2022 15:43:58

Band 66_15 MHz_High_16QAM_RB75#0




Date: 2.MAR.2022 15:44:21

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 2.MAR.2022 15:44:47

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 2.MAR.2022 15:45:14

Band 66_20 MHz_High_QPSK_RB100#0




Date: 2.MAR.2022 15:45:38

Band 66_20 MHz_High_16QAM_RB100#0




Date: 2.MAR.2022 15:46:01

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 2.MAR.2022 17:40:45

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 2.MAR.2022 17:41:17

Band 38_5 MHz_High_QPSK_RB25#0




Date: 3.MAR.2022 11:38:58

Band 38_5 MHz_High_16QAM_RB25#0




Date: 2.MAR.2022 17:42:10

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 2.MAR.2022 17:42:37

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 2.MAR.2022 17:43:05

Band 38_10 MHz_High_QPSK_RB50#0




Date: 2.MAR.2022 17:43:34

Band 38_10 MHz_High_16QAM_RB50#0




Date: 2.MAR.2022 17:43:59

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 2.MAR.2022 17:44:30

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 2.MAR.2022 17:45:00

Band 38_15 MHz_High_QPSK_RB75#0




Date: 2.MAR.2022 17:45:33

Band 38_15 MHz_High_16QAM_RB75#0




Date: 2.MAR.2022 17:46:03

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 2.MAR.2022 17:46:38

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 2.MAR.2022 17:47:04

Band 38_20 MHz_High_QPSK_RB100#0




Date: 2.MAR.2022 17:47:34

Band 38_20 MHz_High_16QAM_RB100#0




Date: 2.MAR.2022 17:48:07

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 2.MAR.2022 18:13:31

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 2.MAR.2022 18:13:57

Band 41_5 MHz_High_QPSK_RB25#0




Date: 3.MAR.2022 11:43:23

Band 41_5 MHz_High_16QAM_RB25#0




Date: 3.MAR.2022 11:45:07

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 2.MAR.2022 18:15:17

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 2.MAR.2022 18:15:42

Band 41_10 MHz_High_QPSK_RB50#0




Date: 2.MAR.2022 18:16:08

Band 41_10 MHz_High_16QAM_RB50#0




Date: 2.MAR.2022 18:16:30

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 2.MAR.2022 18:17:01

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 2.MAR.2022 18:17:31

Band 41_15 MHz_High_QPSK_RB75#0




Date: 2.MAR.2022 18:17:58

Band 41_15 MHz_High_16QAM_RB75#0




Date: 2.MAR.2022 18:18:27

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 2.MAR.2022 18:18:59

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 2.MAR.2022 18:19:25

Band 41_20 MHz_High_QPSK_RB100#0



Date: 2.MAR.2022 18:19:59

Band 41_20 MHz_High_16QAM_RB100#0



Date: 2.MAR.2022 18:20:25