



Please refer to following plots:




Date: 24.NOV.2022 11:41:05




Date: 24.NOV.2022 11:41:12

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 24.NOV.2022 11:41:43

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 24.NOV.2022 11:41:51

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 24.NOV.2022 11:41:59

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 24.NOV.2022 11:42:06

Band 2_3 MHz_High_QPSK_RB15#0




Date: 24.NOV.2022 11:42:15

Band 2_3 MHz_High_16QAM_RB15#0




Date: 24.NOV.2022 11:42:23

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 24.NOV.2022 11:42:32

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 24.NOV.2022 11:42:39

Band 2_5 MHz_High_QPSK_RB25#0




Date: 24.NOV.2022 11:42:48

Band 2_5 MHz_High_16QAM_RB25#0




Date: 24.NOV.2022 11:42:56

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 24.NOV.2022 11:43:06

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 24.NOV.2022 11:43:15

Band 2_10 MHz_High_QPSK_RB50#0




Date: 24.NOV.2022 11:43:24

Band 2_10 MHz_High_16QAM_RB50#0




Date: 24.NOV.2022 11:43:33

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 24.NOV.2022 11:43:42

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 24.NOV.2022 11:43:50

Band 2_15 MHz_High_QPSK_RB75#0




Date: 24.NOV.2022 11:43:58

Band 2_15 MHz_High_16QAM_RB75#0




Date: 24.NOV.2022 11:44:06

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 24.NOV.2022 11:44:16

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 24.NOV.2022 11:44:24

Band 2_20 MHz_High_QPSK_RB100#0




Date: 24.NOV.2022 11:44:32

Band 2_20 MHz_High_16QAM_RB100#0




Date: 24.NOV.2022 11:44:40

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 24.NOV.2022 11:50:11

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 24.NOV.2022 11:50:19

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 24.NOV.2022 11:51:52

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 24.NOV.2022 11:51:59

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 24.NOV.2022 11:52:09

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 24.NOV.2022 11:52:17

Band 4_3 MHz_High_QPSK_RB15#0




Date: 24.NOV.2022 11:52:24

Band 4_3 MHz_High_16QAM_RB15#0




Date: 24.NOV.2022 11:52:31

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 24.NOV.2022 11:52:41

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 24.NOV.2022 11:52:49

Band 4_5 MHz_High_QPSK_RB25#0




Date: 24.NOV.2022 11:52:57

Band 4_5 MHz_High_16QAM_RB25#0




Date: 24.NOV.2022 11:53:05

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 24.NOV.2022 11:53:16

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 24.NOV.2022 11:53:25

Band 4_10 MHz_High_QPSK_RB50#0




Date: 24.NOV.2022 11:53:34

Band 4_10 MHz_High_16QAM_RB50#0




Date: 24.NOV.2022 11:53:42

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 24.NOV.2022 11:53:52

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 24.NOV.2022 11:54:00

Band 4_15 MHz_High_QPSK_RB75#0




Date: 24.NOV.2022 11:54:08

Band 4_15 MHz_High_16QAM_RB75#0




Date: 24.NOV.2022 11:54:16

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 24.NOV.2022 11:54:26

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 24.NOV.2022 11:54:34

Band 4_20 MHz_High_QPSK_RB100#0




Date: 24.NOV.2022 11:54:42

Band 4_20 MHz_High_16QAM_RB100#0




Date: 24.NOV.2022 11:54:50

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 7.DEC.2022 14:34:14

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 7.DEC.2022 14:34:40

Band 7_5 MHz_High_QPSK_RB25#0




Date: 7.DEC.2022 14:35:22

Band 7_5 MHz_High_16QAM_RB25#0




Date: 7.DEC.2022 14:35:45

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 7.DEC.2022 14:37:52

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 7.DEC.2022 14:38:17

Band 7_10 MHz_High_QPSK_RB50#0




Date: 7.DEC.2022 14:38:58

Band 7_10 MHz_High_16QAM_RB50#0




Date: 7.DEC.2022 14:39:24

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 16.DEC.2022 14:06:45

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 16.DEC.2022 14:07:08

Band 7_15 MHz_High_QPSK_RB75#0




Date: 16.DEC.2022 14:07:47

Band 7_15 MHz_High_16QAM_RB75#0




Date: 16.DEC.2022 14:09:15

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 7.DEC.2022 14:42:28

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 7.DEC.2022 14:42:51

Band 7_20 MHz_High_QPSK_RB100#0




Date: 7.DEC.2022 14:43:21

Band 7_20 MHz_High_16QAM_RB100#0




Date: 7.DEC.2022 14:43:38

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 24.NOV.2022 11:58:05

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 24.NOV.2022 11:58:13

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 24.NOV.2022 11:58:51

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 24.NOV.2022 11:58:58

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 24.NOV.2022 11:59:07

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 24.NOV.2022 11:59:15

Band 66_3 MHz_High_QPSK_RB15#0




Date: 24.NOV.2022 11:59:23

Band 66_3 MHz_High_16QAM_RB15#0




Date: 24.NOV.2022 11:59:31

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 24.NOV.2022 11:59:41

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 24.NOV.2022 11:59:49

Band 66_5 MHz_High_QPSK_RB25#0




Date: 24.NOV.2022 11:59:58

Band 66_5 MHz_High_16QAM_RB25#0




Date: 24.NOV.2022 12:00:06

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 24.NOV.2022 12:00:17

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 24.NOV.2022 12:00:26

Band 66_10 MHz_High_QPSK_RB50#0




Date: 24.NOV.2022 12:00:36

Band 66_10 MHz_High_16QAM_RB50#0




Date: 24.NOV.2022 12:00:45

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 24.NOV.2022 12:00:54

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 24.NOV.2022 12:01:02

Band 66_15 MHz_High_QPSK_RB75#0




Date: 24.NOV.2022 12:01:10

Band 66_15 MHz_High_16QAM_RB75#0




Date: 24.NOV.2022 12:01:18

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 24.NOV.2022 12:01:28

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 24.NOV.2022 12:01:36

Band 66_20 MHz_High_QPSK_RB100#0




Date: 24.NOV.2022 12:01:44

Band 66_20 MHz_High_16QAM_RB100#0




Date: 24.NOV.2022 12:01:52

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 25.NOV.2022 09:14:25

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 25.NOV.2022 09:14:32

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 25.NOV.2022 09:15:42

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 25.NOV.2022 09:15:50

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 25.NOV.2022 09:16:00

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 25.NOV.2022 09:16:07

Band 5_3 MHz_High_QPSK_RB15#0




Date: 25.NOV.2022 09:17:19

Band 5_3 MHz_High_16QAM_RB15#0




Date: 25.NOV.2022 09:17:26

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 25.NOV.2022 09:17:36

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 25.NOV.2022 09:17:43

Band 5_5 MHz_High_QPSK_RB25#0




Date: 25.NOV.2022 09:17:52

Band 5_5 MHz_High_16QAM_RB25#0




Date: 25.NOV.2022 09:17:59

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 25.NOV.2022 09:18:10

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 25.NOV.2022 09:18:18

Band 5_10 MHz_High_QPSK_RB50#0




Date: 25.NOV.2022 09:18:28

Band 5_10 MHz_High_16QAM_RB50#0




Date: 25.NOV.2022 09:18:37

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 25.NOV.2022 09:19:22

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 25.NOV.2022 09:19:29

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 25.NOV.2022 09:20:40

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 25.NOV.2022 09:20:47

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 25.NOV.2022 09:20:58

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 25.NOV.2022 09:21:05

Band 12_3 MHz_High_QPSK_RB15#0




Date: 25.NOV.2022 09:24:42

Band 12_3 MHz_High_16QAM_RB15#0




Date: 25.NOV.2022 09:24:49

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 25.NOV.2022 09:25:00

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 25.NOV.2022 09:25:09

Band 12_5 MHz_High_QPSK_RB25#0




Date: 25.NOV.2022 09:25:17

Band 12_5 MHz_High_16QAM_RB25#0




Date: 25.NOV.2022 09:25:24

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 25.NOV.2022 09:25:36

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 25.NOV.2022 09:25:45

Band 12_10 MHz_High_QPSK_RB50#0




Date: 25.NOV.2022 09:25:54

Band 12_10 MHz_High_16QAM_RB50#0




Date: 25.NOV.2022 09:26:02

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 25.NOV.2022 09:26:13

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 25.NOV.2022 09:26:21

Band 17_5 MHz_High_QPSK_RB25#0




Date: 25.NOV.2022 09:27:29

Band 17_5 MHz_High_16QAM_RB25#0




Date: 25.NOV.2022 09:27:36

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 25.NOV.2022 09:27:47

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 25.NOV.2022 09:27:56

Band 17_10 MHz_High_QPSK_RB50#0




Date: 25.NOV.2022 09:28:05

Band 17_10 MHz_High_16QAM_RB50#0




Date: 25.NOV.2022 09:28:13

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 7.DEC.2022 14:14:00

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 7.DEC.2022 14:14:28

Band 38_5 MHz_High_QPSK_RB25#0




Date: 7.DEC.2022 14:15:11

Band 38_5 MHz_High_16QAM_RB25#0




Date: 7.DEC.2022 14:15:31

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 7.DEC.2022 14:21:25

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 7.DEC.2022 14:21:49

Band 38_10 MHz_High_QPSK_RB50#0




Date: 7.DEC.2022 14:23:09

Band 38_10 MHz_High_16QAM_RB50#0




Date: 7.DEC.2022 14:23:25

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 16.DEC.2022 09:57:19

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 16.DEC.2022 09:57:47

Band 38_15 MHz_High_QPSK_RB75#0




Date: 16.DEC.2022 09:58:10

Band 38_15 MHz_High_16QAM_RB75#0




Date: 16.DEC.2022 09:58:39

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 7.DEC.2022 14:25:59

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 7.DEC.2022 14:26:28

Band 38_20 MHz_High_QPSK_RB100#0




Date: 7.DEC.2022 14:27:22

Band 38_20 MHz_High_16QAM_RB100#0




Date: 7.DEC.2022 14:27:41

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 7.DEC.2022 13:57:49

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 7.DEC.2022 13:58:15

Band 41_5 MHz_High_QPSK_RB25#0




Date: 7.DEC.2022 13:58:56

Band 41_5 MHz_High_16QAM_RB25#0




Date: 7.DEC.2022 13:59:14

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 7.DEC.2022 14:00:30

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 7.DEC.2022 14:00:52

Band 41_10 MHz_High_QPSK_RB50#0




Date: 7.DEC.2022 14:01:40

Band 41_10 MHz_High_16QAM_RB50#0




Date: 7.DEC.2022 14:02:04

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 16.DEC.2022 10:02:51

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 16.DEC.2022 10:03:14

Band 41_15 MHz_High_QPSK_RB75#0




Date: 16.DEC.2022 10:03:46

Band 41_15 MHz_High_16QAM_RB75#0




Date: 16.DEC.2022 10:04:06

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 7.DEC.2022 14:06:07

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 7.DEC.2022 14:06:39

Band 41_20 MHz_High_QPSK_RB100#0



Date: 7.DEC.2022 14:07:05

Band 41_20 MHz_High_16QAM_RB100#0



Date: 7.DEC.2022 14:07:28