



Please refer to following plots:




Date: 9.MAR.2021 00:11:06




Date: 9.MAR.2021 00:11:26

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 9.MAR.2021 00:12:00

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 9.MAR.2021 00:12:31

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 9.MAR.2021 00:13:03

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 9.MAR.2021 00:13:26

Band 2_3 MHz_High_QPSK_RB15#0




Date: 9.MAR.2021 00:14:07

Band 2_3 MHz_High_16QAM_RB15#0




Date: 9.MAR.2021 00:14:31

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 9.MAR.2021 00:15:06

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 9.MAR.2021 00:15:33

Band 2_5 MHz_High_QPSK_RB25#0




Date: 9.MAR.2021 00:16:14

Band 2_5 MHz_High_16QAM_RB25#0




Date: 9.MAR.2021 00:16:48

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 9.MAR.2021 00:17:25

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 9.MAR.2021 00:17:50

Band 2_10 MHz_High_QPSK_RB50#0




Date: 9.MAR.2021 00:18:30

Band 2_10 MHz_High_16QAM_RB50#0




Date: 9.MAR.2021 00:18:56

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 9.MAR.2021 00:19:36

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 9.MAR.2021 00:20:10

Band 2_15 MHz_High_QPSK_RB75#0




Date: 9.MAR.2021 00:20:54

Band 2_15 MHz_High_16QAM_RB75#0




Date: 9.MAR.2021 00:21:26

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 9.MAR.2021 00:22:05

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 9.MAR.2021 00:22:34

Band 2_20 MHz_High_QPSK_RB100#0




Date: 9.MAR.2021 00:23:16

Band 2_20 MHz_High_16QAM_RB100#0




Date: 9.MAR.2021 00:23:50

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 9.MAR.2021 00:24:23

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 9.MAR.2021 00:24:49

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 9.MAR.2021 00:25:22

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 9.MAR.2021 00:25:50

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 9.MAR.2021 00:26:26

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 9.MAR.2021 00:26:53

Band 4_3 MHz_High_QPSK_RB15#0




Date: 9.MAR.2021 00:27:23

Band 4_3 MHz_High_16QAM_RB15#0




Date: 9.MAR.2021 00:27:51

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 9.MAR.2021 00:28:24

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 9.MAR.2021 00:28:52

Band 4_5 MHz_High_QPSK_RB25#0




Date: 9.MAR.2021 00:29:28

Band 4_5 MHz_High_16QAM_RB25#0




Date: 9.MAR.2021 00:29:53

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 9.MAR.2021 00:30:27

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 9.MAR.2021 00:30:55

Band 4_10 MHz_High_QPSK_RB50#0




Date: 9.MAR.2021 00:31:27

Band 4_10 MHz_High_16QAM_RB50#0




Date: 9.MAR.2021 00:31:52

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 9.MAR.2021 00:32:31

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 9.MAR.2021 00:33:01

Band 4_15 MHz_High_QPSK_RB75#0




Date: 9.MAR.2021 00:33:40

Band 4_15 MHz_High_16QAM_RB75#0




Date: 9.MAR.2021 00:34:10

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 9.MAR.2021 00:34:49

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 9.MAR.2021 00:35:23

Band 4_20 MHz_High_QPSK_RB100#0




Date: 9.MAR.2021 00:36:05

Band 4_20 MHz_High_16QAM_RB100#0




Date: 9.MAR.2021 00:36:35

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 9.MAR.2021 00:37:08

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 9.MAR.2021 00:37:34

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 9.MAR.2021 00:38:07

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 9.MAR.2021 00:38:33

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 9.MAR.2021 00:39:03

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 9.MAR.2021 00:39:32

Band 5_3 MHz_High_QPSK_RB15#0




Date: 9.MAR.2021 00:40:05

Band 5_3 MHz_High_16QAM_RB15#0




Date: 9.MAR.2021 00:40:30

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 9.MAR.2021 00:41:06

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 9.MAR.2021 00:41:34

Band 5_5 MHz_High_QPSK_RB25#0




Date: 9.MAR.2021 00:42:09

Band 5_5 MHz_High_16QAM_RB25#0




Date: 9.MAR.2021 00:42:37

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 9.MAR.2021 00:43:11

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 9.MAR.2021 00:43:38

Band 5_10 MHz_High_QPSK_RB50#0




Date: 9.MAR.2021 00:44:12

Band 5_10 MHz_High_16QAM_RB50#0




Date: 9.MAR.2021 00:44:36

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 9.MAR.2021 00:45:09

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 9.MAR.2021 00:45:34

Band 7_5 MHz_High_QPSK_RB25#0




Date: 9.MAR.2021 00:46:08

Band 7_5 MHz_High_16QAM_RB25#0




Date: 9.MAR.2021 00:46:33

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 9.MAR.2021 00:47:07

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 9.MAR.2021 00:47:32

Band 7_10 MHz_High_QPSK_RB50#0




Date: 9.MAR.2021 00:48:09

Band 7_10 MHz_High_16QAM_RB50#0




Date: 9.MAR.2021 00:48:38

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 9.MAR.2021 00:49:17

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 9.MAR.2021 00:49:47

Band 7_15 MHz_High_QPSK_RB75#0




Date: 9.MAR.2021 00:50:26

Band 7_15 MHz_High_16QAM_RB75#0




Date: 9.MAR.2021 00:50:58

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 9.MAR.2021 00:51:37

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 9.MAR.2021 00:52:04

Band 7_20 MHz_High_QPSK_RB100#0




Date: 9.MAR.2021 00:52:37

Band 7_20 MHz_High_16QAM_RB100#0




Date: 9.MAR.2021 00:53:09

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 9.MAR.2021 00:53:42

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 9.MAR.2021 00:54:06

Band 17_5 MHz_High_QPSK_RB25#0




Date: 9.MAR.2021 00:54:42

Band 17_5 MHz_High_16QAM_RB25#0




Date: 14.APR.2021 20:14:20

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 9.MAR.2021 00:55:46

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 9.MAR.2021 00:56:10

Band 17_10 MHz_High_QPSK_RB50#0




Date: 9.MAR.2021 00:56:35

Band 17_10 MHz_High_16QAM_RB50#0




Date: 9.MAR.2021 00:56:59

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 9.MAR.2021 20:09:38

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 9.MAR.2021 20:10:18

Band 38_5 MHz_High_QPSK_RB25#0




Date: 11.MAR.2021 22:55:49

Band 38_5 MHz_High_16QAM_RB25#0




Date: 9.MAR.2021 20:11:34

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 9.MAR.2021 20:12:05

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 9.MAR.2021 20:12:36

Band 38_10 MHz_High_QPSK_RB50#0




Date: 9.MAR.2021 20:13:16

Band 38_10 MHz_High_16QAM_RB50#0




Date: 9.MAR.2021 20:13:45

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 9.MAR.2021 20:14:21

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 9.MAR.2021 20:15:00

Band 38_15 MHz_High_QPSK_RB75#0




Date: 9.MAR.2021 20:15:42

Band 38_15 MHz_High_16QAM_RB75#0




Date: 9.MAR.2021 20:16:11

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 9.MAR.2021 20:16:47

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 9.MAR.2021 20:17:22

Band 38_20 MHz_High_QPSK_RB100#0




Date: 9.MAR.2021 20:18:06

Band 38_20 MHz_High_16QAM_RB100#0




Date: 9.MAR.2021 20:18:35

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 9.MAR.2021 23:15:18

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 9.MAR.2021 23:15:49

Band 41_5 MHz_High_QPSK_RB25#0




Date: 9.MAR.2021 23:16:25

Band 41_5 MHz_High_16QAM_RB25#0




Date: 9.MAR.2021 23:16:52

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 9.MAR.2021 23:17:17

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 9.MAR.2021 23:17:49

Band 41_10 MHz_High_QPSK_RB50#0




Date: 9.MAR.2021 23:18:26

Band 41_10 MHz_High_16QAM_RB50#0




Date: 9.MAR.2021 23:18:48

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 9.MAR.2021 23:19:20

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 9.MAR.2021 23:19:57

Band 41_15 MHz_High_QPSK_RB75#0




Date: 11.MAR.2021 22:59:08

Band 41_15 MHz_High_16QAM_RB75#0




Date: 9.MAR.2021 23:21:11

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 9.MAR.2021 23:21:41

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 9.MAR.2021 23:22:14

Band 41_20 MHz_High_QPSK_RB100#0




Date: 9.MAR.2021 23:22:47

Band 41_20 MHz_High_16QAM_RB100#0




Date: 9.MAR.2021 23:23:19

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 9.MAR.2021 22:07:37

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 9.MAR.2021 22:08:02

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 9.MAR.2021 22:08:26

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 9.MAR.2021 22:08:52

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 9.MAR.2021 22:09:16

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 9.MAR.2021 22:09:41

Band 66_3 MHz_High_QPSK_RB15#0




Date: 9.MAR.2021 22:10:07

Band 66_3 MHz_High_16QAM_RB15#0




Date: 9.MAR.2021 22:10:31

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 9.MAR.2021 22:10:55

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 9.MAR.2021 22:11:20

Band 66_5 MHz_High_QPSK_RB25#0




Date: 9.MAR.2021 22:11:46

Band 66_5 MHz_High_16QAM_RB25#0




Date: 9.MAR.2021 22:12:14

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 9.MAR.2021 22:12:43

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 9.MAR.2021 22:13:09

Band 66_10 MHz_High_QPSK_RB50#0




Date: 9.MAR.2021 22:13:39

Band 66_10 MHz_High_16QAM_RB50#0




Date: 9.MAR.2021 22:14:05

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 9.MAR.2021 22:14:36

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 9.MAR.2021 22:15:05

Band 66_15 MHz_High_QPSK_RB75#0




Date: 9.MAR.2021 22:15:34

Band 66_15 MHz_High_16QAM_RB75#0




Date: 9.MAR.2021 22:16:04

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 9.MAR.2021 22:16:31

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 9.MAR.2021 22:17:05

Band 66_20 MHz_High_QPSK_RB100#0



Date: 9.MAR.2021 22:17:36

Band 66_20 MHz_High_16QAM_RB100#0



Date: 9.MAR.2021 22:18:05