



Please refer to following plots:




Date: 3.AUG.2021 11:33:02




Date: 3.AUG.2021 11:33:20

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 3.AUG.2021 11:33:42

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 3.AUG.2021 11:34:03

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 3.AUG.2021 11:34:24

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 3.AUG.2021 11:34:42

Band 2_3 MHz_High_QPSK_RB15#0




Date: 3.AUG.2021 11:35:00

Band 2_3 MHz_High_16QAM_RB15#0




Date: 3.AUG.2021 11:35:18

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 3.AUG.2021 11:35:41

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 3.AUG.2021 11:35:59

Band 2_5 MHz_High_QPSK_RB25#0




Date: 3.AUG.2021 11:36:21

Band 2_5 MHz_High_16QAM_RB25#0




Date: 3.AUG.2021 11:36:42

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 3.AUG.2021 11:37:16

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 3.AUG.2021 11:37:36

Band 2_10 MHz_High_QPSK_RB50#0




Date: 3.AUG.2021 11:37:57

Band 2_10 MHz_High_16QAM_RB50#0




Date: 3.AUG.2021 11:38:17

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 3.AUG.2021 11:38:44

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 3.AUG.2021 11:39:08

Band 2_15 MHz_High_QPSK_RB75#0




Date: 3.AUG.2021 11:39:34

Band 2_15 MHz_High_16QAM_RB75#0




Date: 3.AUG.2021 11:39:58

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 3.AUG.2021 11:40:46

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 3.AUG.2021 11:41:10

Band 2_20 MHz_High_QPSK_RB100#0




Date: 3.AUG.2021 11:41:36

Band 2_20 MHz_High_16QAM_RB100#0




Date: 3.AUG.2021 11:42:00

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 4.AUG.2021 20:09:42

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 2.AUG.2021 16:44:22

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 2.AUG.2021 16:44:43

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 2.AUG.2021 16:45:04

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 2.AUG.2021 16:45:24

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 2.AUG.2021 16:45:42

Band 4_3 MHz_High_QPSK_RB15#0




Date: 2.AUG.2021 16:46:00

Band 4_3 MHz_High_16QAM_RB15#0




Date: 2.AUG.2021 16:46:18

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 2.AUG.2021 16:46:38

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 2.AUG.2021 16:46:59

Band 4_5 MHz_High_QPSK_RB25#0




Date: 2.AUG.2021 16:47:20

Band 4_5 MHz_High_16QAM_RB25#0




Date: 2.AUG.2021 16:47:38

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 2.AUG.2021 16:48:01

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 2.AUG.2021 16:48:20

Band 4_10 MHz_High_QPSK_RB50#0




Date: 2.AUG.2021 16:48:41

Band 4_10 MHz_High_16QAM_RB50#0




Date: 2.AUG.2021 16:49:04

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 2.AUG.2021 16:49:31

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 2.AUG.2021 16:49:56

Band 4_15 MHz_High_QPSK_RB75#0




Date: 2.AUG.2021 16:50:21

Band 4_15 MHz_High_16QAM_RB75#0




Date: 2.AUG.2021 16:50:45

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 2.AUG.2021 16:51:13

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 2.AUG.2021 16:51:37

Band 4_20 MHz_High_QPSK_RB100#0




Date: 2.AUG.2021 16:51:59

Band 4_20 MHz_High_16QAM_RB100#0




Date: 2.AUG.2021 16:52:27

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 3.AUG.2021 11:42:21

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 3.AUG.2021 11:42:39

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 3.AUG.2021 11:43:01

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 3.AUG.2021 11:43:21

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 3.AUG.2021 11:43:42

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 3.AUG.2021 11:43:59

Band 5_3 MHz_High_QPSK_RB15#0




Date: 3.AUG.2021 11:44:21

Band 5_3 MHz_High_16QAM_RB15#0




Date: 3.AUG.2021 11:44:39

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 3.AUG.2021 11:44:59

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 3.AUG.2021 11:45:17

Band 5_5 MHz_High_QPSK_RB25#0




Date: 3.AUG.2021 11:45:39

Band 5_5 MHz_High_16QAM_RB25#0




Date: 3.AUG.2021 11:46:03

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 3.AUG.2021 11:46:29

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 3.AUG.2021 11:46:49

Band 5_10 MHz_High_QPSK_RB50#0




Date: 3.AUG.2021 11:47:13

Band 5_10 MHz_High_16QAM_RB50#0




Date: 3.AUG.2021 12:33:55

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 2.AUG.2021 16:52:47

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 2.AUG.2021 16:53:05

Band 7_5 MHz_High_QPSK_RB25#0




Date: 2.AUG.2021 16:53:30

Band 7_5 MHz_High_16QAM_RB25#0




Date: 2.AUG.2021 16:53:51

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 2.AUG.2021 16:54:13

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 2.AUG.2021 16:54:33

Band 7_10 MHz_High_QPSK_RB50#0




Date: 2.AUG.2021 16:54:54

Band 7_10 MHz_High_16QAM_RB50#0




Date: 2.AUG.2021 16:55:14

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 2.AUG.2021 16:55:41

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 2.AUG.2021 16:56:05

Band 7_15 MHz_High_QPSK_RB75#0




Date: 2.AUG.2021 16:56:43

Band 7_15 MHz_High_16QAM_RB75#0




Date: 2.AUG.2021 16:57:08

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 2.AUG.2021 16:57:38

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 2.AUG.2021 16:58:06

Band 7_20 MHz_High_QPSK_RB100#0




Date: 2.AUG.2021 16:58:31

Band 7_20 MHz_High_16QAM_RB100#0




Date: 2.AUG.2021 16:58:55

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 2.AUG.2021 16:59:19

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 2.AUG.2021 16:59:37

Band 17_5 MHz_High_QPSK_RB25#0




Date: 4.AUG.2021 20:15:18

Band 17_5 MHz_High_16QAM_RB25#0




Date: 4.AUG.2021 20:16:08

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 2.AUG.2021 17:00:46

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 2.AUG.2021 17:01:06

Band 17_10 MHz_High_QPSK_RB50#0




Date: 2.AUG.2021 17:01:26

Band 17_10 MHz_High_16QAM_RB50#0




Date: 2.AUG.2021 17:01:46

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 11.AUG.2021 18:22:48

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 11.AUG.2021 18:23:05

Band 38_5 MHz_High_QPSK_RB25#0




Date: 11.AUG.2021 18:23:22

Band 38_5 MHz_High_16QAM_RB25#0




Date: 11.AUG.2021 18:23:42

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 11.AUG.2021 18:24:07

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 11.AUG.2021 18:24:26

Band 38_10 MHz_High_QPSK_RB50#0




Date: 11.AUG.2021 18:24:49

Band 38_10 MHz_High_16QAM_RB50#0




Date: 11.AUG.2021 18:25:11

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 11.AUG.2021 18:25:37

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 11.AUG.2021 18:26:01

Band 38_15 MHz_High_QPSK_RB75#0




Date: 11.AUG.2021 18:26:25

Band 38_15 MHz_High_16QAM_RB75#0




Date: 11.AUG.2021 18:26:52

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 11.AUG.2021 18:27:21

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 11.AUG.2021 18:27:48

Band 38_20 MHz_High_QPSK_RB100#0




Date: 11.AUG.2021 18:28:12

Band 38_20 MHz_High_16QAM_RB100#0




Date: 11.AUG.2021 18:28:35

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 11.AUG.2021 18:29:07

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 11.AUG.2021 18:29:30

Band 41_5 MHz_High_QPSK_RB25#0




Date: 11.AUG.2021 18:29:54

Band 41_5 MHz_High_16QAM_RB25#0




Date: 11.AUG.2021 18:30:17

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 11.AUG.2021 18:30:42

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 11.AUG.2021 18:31:04

Band 41_10 MHz_High_QPSK_RB50#0




Date: 11.AUG.2021 18:31:27

Band 41_10 MHz_High_16QAM_RB50#0




Date: 11.AUG.2021 18:31:49

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 11.AUG.2021 18:32:22

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 11.AUG.2021 18:32:49

Band 41_15 MHz_High_QPSK_RB75#0




Date: 11.AUG.2021 18:33:16

Band 41_15 MHz_High_16QAM_RB75#0




Date: 11.AUG.2021 18:33:39

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 11.AUG.2021 18:34:06

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 11.AUG.2021 18:34:33

Band 41_20 MHz_High_QPSK_RB100#0




Date: 11.AUG.2021 18:35:00

Band 41_20 MHz_High_16QAM_RB100#0




Date: 11.AUG.2021 18:35:26

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 2.AUG.2021 17:02:10

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 2.AUG.2021 17:02:31

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 2.AUG.2021 17:02:53

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 2.AUG.2021 17:03:14

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 2.AUG.2021 17:03:35

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 2.AUG.2021 17:03:52

Band 66_3 MHz_High_QPSK_RB15#0




Date: 2.AUG.2021 17:04:11

Band 66_3 MHz_High_16QAM_RB15#0




Date: 2.AUG.2021 17:04:29

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 2.AUG.2021 17:04:52

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 2.AUG.2021 17:05:13

Band 66_5 MHz_High_QPSK_RB25#0




Date: 2.AUG.2021 17:05:31

Band 66_5 MHz_High_16QAM_RB25#0




Date: 2.AUG.2021 17:05:52

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 2.AUG.2021 17:06:19

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 2.AUG.2021 17:06:39

Band 66_10 MHz_High_QPSK_RB50#0




Date: 2.AUG.2021 17:07:00

Band 66_10 MHz_High_16QAM_RB50#0




Date: 2.AUG.2021 17:07:20

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 2.AUG.2021 17:07:47

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 2.AUG.2021 17:08:12

Band 66_15 MHz_High_QPSK_RB75#0




Date: 2.AUG.2021 17:08:37

Band 66_15 MHz_High_16QAM_RB75#0




Date: 2.AUG.2021 17:09:01

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 2.AUG.2021 17:09:30

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 2.AUG.2021 17:09:58

Band 66_20 MHz_High_QPSK_RB100#0



Date: 2.AUG.2021 17:10:23

Band 66_20 MHz_High_16QAM_RB100#0



Date: 2.AUG.2021 17:10:51