



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 10.FEB.2022 19:42:16

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 10.FEB.2022 17:59:57

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 10.FEB.2022 18:00:18

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 10.FEB.2022 18:00:38

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 10.FEB.2022 18:00:57

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 10.FEB.2022 18:01:14

Band 2_3 MHz_High_QPSK_RB15#0




Date: 10.FEB.2022 18:01:34

Band 2_3 MHz_High_16QAM_RB15#0




Date: 10.FEB.2022 18:01:51

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 10.FEB.2022 18:02:13

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 10.FEB.2022 18:02:29

Band 2_5 MHz_High_QPSK_RB25#0




Date: 10.FEB.2022 18:02:50

Band 2_5 MHz_High_16QAM_RB25#0




Date: 10.FEB.2022 18:03:07

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 10.FEB.2022 18:03:27

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 10.FEB.2022 18:03:46

Band 2_10 MHz_High_QPSK_RB50#0




Date: 10.FEB.2022 18:04:06

Band 2_10 MHz_High_16QAM_RB50#0




Date: 10.FEB.2022 18:04:25

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 10.FEB.2022 18:04:53

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 10.FEB.2022 18:05:17

Band 2_15 MHz_High_QPSK_RB75#0




Date: 10.FEB.2022 18:05:41

Band 2_15 MHz_High_16QAM_RB75#0




Date: 10.FEB.2022 18:06:04

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 10.FEB.2022 18:06:29

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 10.FEB.2022 18:06:56

Band 2_20 MHz_High_QPSK_RB100#0




Date: 10.FEB.2022 18:07:20

Band 2_20 MHz_High_16QAM_RB100#0




Date: 10.FEB.2022 18:07:44

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 10.FEB.2022 18:08:05

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 10.FEB.2022 18:08:25

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 10.FEB.2022 18:08:46

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 10.FEB.2022 18:09:02

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 10.FEB.2022 18:09:24

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 10.FEB.2022 18:09:40

Band 4_3 MHz_High_QPSK_RB15#0




Date: 10.FEB.2022 18:09:58

Band 4_3 MHz_High_16QAM_RB15#0




Date: 10.FEB.2022 18:10:15

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 10.FEB.2022 18:10:36

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 10.FEB.2022 18:10:53

Band 4_5 MHz_High_QPSK_RB25#0




Date: 10.FEB.2022 18:11:16

Band 4_5 MHz_High_16QAM_RB25#0




Date: 10.FEB.2022 18:11:39

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 10.FEB.2022 18:12:00

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 10.FEB.2022 18:12:19

Band 4_10 MHz_High_QPSK_RB50#0




Date: 10.FEB.2022 18:12:39

Band 4_10 MHz_High_16QAM_RB50#0




Date: 10.FEB.2022 18:12:58

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 10.FEB.2022 18:13:23

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 10.FEB.2022 18:13:47

Band 4_15 MHz_High_QPSK_RB75#0




Date: 10.FEB.2022 18:14:11

Band 4_15 MHz_High_16QAM_RB75#0




Date: 10.FEB.2022 18:14:34

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 10.FEB.2022 18:15:07

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 10.FEB.2022 18:15:31

Band 4_20 MHz_High_QPSK_RB100#0




Date: 10.FEB.2022 18:15:55

Band 4_20 MHz_High_16QAM_RB100#0




Date: 10.FEB.2022 18:16:18

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 10.FEB.2022 18:16:39

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 10.FEB.2022 18:16:56

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 10.FEB.2022 18:17:13

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 10.FEB.2022 18:17:30

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 10.FEB.2022 18:17:48

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 10.FEB.2022 18:18:05

Band 5_3 MHz_High_QPSK_RB15#0




Date: 10.FEB.2022 18:18:22

Band 5_3 MHz_High_16QAM_RB15#0




Date: 10.FEB.2022 18:18:39

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 10.FEB.2022 19:31:44

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 10.FEB.2022 18:19:14

Band 5_5 MHz_High_QPSK_RB25#0




Date: 10.FEB.2022 18:19:32

Band 5_5 MHz_High_16QAM_RB25#0




Date: 10.FEB.2022 18:19:49

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 10.FEB.2022 18:20:09

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 10.FEB.2022 18:20:28

Band 5_10 MHz_High_QPSK_RB50#0




Date: 10.FEB.2022 18:20:48

Band 5_10 MHz_High_16QAM_RB50#0




Date: 10.FEB.2022 18:21:07

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 10.FEB.2022 18:21:29

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 10.FEB.2022 18:21:49

Band 7_5 MHz_High_QPSK_RB25#0




Date: 10.FEB.2022 18:22:06

Band 7_5 MHz_High_16QAM_RB25#0




Date: 10.FEB.2022 18:22:23

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 10.FEB.2022 18:22:43

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 10.FEB.2022 18:23:02

Band 7_10 MHz_High_QPSK_RB50#0




Date: 10.FEB.2022 18:23:22

Band 7_10 MHz_High_16QAM_RB50#0




Date: 10.FEB.2022 18:23:41

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 10.FEB.2022 18:24:06

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 10.FEB.2022 18:24:33

Band 7_15 MHz_High_QPSK_RB75#0




Date: 10.FEB.2022 19:33:09

Band 7_15 MHz_High_16QAM_RB75#0




Date: 10.FEB.2022 18:25:23

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 10.FEB.2022 18:25:48

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 10.FEB.2022 18:26:12

Band 7_20 MHz_High_QPSK_RB100#0




Date: 10.FEB.2022 18:26:36

Band 7_20 MHz_High_16QAM_RB100#0




Date: 10.FEB.2022 18:27:00

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 10.FEB.2022 19:34:53

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 10.FEB.2022 19:36:13

Band 17_5 MHz_High_QPSK_RB25#0




Date: 10.FEB.2022 19:38:02

Band 17_5 MHz_High_16QAM_RB25#0




Date: 10.FEB.2022 19:37:24

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 10.FEB.2022 18:28:39

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 10.FEB.2022 18:28:58

Band 17_10 MHz_High_QPSK_RB50#0




Date: 10.FEB.2022 18:29:21

Band 17_10 MHz_High_16QAM_RB50#0




Date: 10.FEB.2022 18:29:40

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 10.FEB.2022 18:30:12

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 10.FEB.2022 18:30:36

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 10.FEB.2022 18:30:56

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 10.FEB.2022 18:31:16

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 10.FEB.2022 18:31:37

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 10.FEB.2022 18:31:54

Band 66_3 MHz_High_QPSK_RB15#0




Date: 10.FEB.2022 18:32:12

Band 66_3 MHz_High_16QAM_RB15#0




Date: 10.FEB.2022 18:32:28

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 10.FEB.2022 19:39:04

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 10.FEB.2022 19:39:40

Band 66_5 MHz_High_QPSK_RB25#0




Date: 10.FEB.2022 19:40:37

Band 66_5 MHz_High_16QAM_RB25#0




Date: 10.FEB.2022 19:44:32

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 10.FEB.2022 18:34:11

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 10.FEB.2022 18:34:30

Band 66_10 MHz_High_QPSK_RB50#0




Date: 10.FEB.2022 18:34:50

Band 66_10 MHz_High_16QAM_RB50#0




Date: 10.FEB.2022 18:35:12

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 10.FEB.2022 18:35:37

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 10.FEB.2022 18:36:01

Band 66_15 MHz_High_QPSK_RB75#0




Date: 10.FEB.2022 19:45:48

Band 66_15 MHz_High_16QAM_RB75#0




Date: 10.FEB.2022 19:46:41

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 10.FEB.2022 18:37:14

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 10.FEB.2022 18:37:37

Band 66_20 MHz_High_QPSK_RB100#0




Date: 10.FEB.2022 18:38:01

Band 66_20 MHz_High_16QAM_RB100#0




Date: 10.FEB.2022 18:38:28

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 11.FEB.2022 09:21:39

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 11.FEB.2022 09:22:02

Band 38_5 MHz_High_QPSK_RB25#0




Date: 11.FEB.2022 09:22:22

Band 38_5 MHz_High_16QAM_RB25#0




Date: 11.FEB.2022 09:22:42

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 11.FEB.2022 09:23:06

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 11.FEB.2022 09:23:28

Band 38_10 MHz_High_QPSK_RB50#0




Date: 11.FEB.2022 09:23:51

Band 38_10 MHz_High_16QAM_RB50#0




Date: 11.FEB.2022 09:24:13

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 11.FEB.2022 10:54:20

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 11.FEB.2022 09:25:07

Band 38_15 MHz_High_QPSK_RB75#0




Date: 11.FEB.2022 09:25:31

Band 38_15 MHz_High_16QAM_RB75#0




Date: 11.FEB.2022 09:25:58

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 11.FEB.2022 09:26:29

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 11.FEB.2022 09:26:55

Band 38_20 MHz_High_QPSK_RB100#0




Date: 11.FEB.2022 09:27:19

Band 38_20 MHz_High_16QAM_RB100#0




Date: 11.FEB.2022 09:27:49

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 11.FEB.2022 11:09:39

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 11.FEB.2022 10:39:59

Band 41_5 MHz_High_QPSK_RB25#0




Date: 11.FEB.2022 10:40:17

Band 41_5 MHz_High_16QAM_RB25#0




Date: 11.FEB.2022 10:40:37

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 11.FEB.2022 10:41:03

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 11.FEB.2022 10:41:28

Band 41_10 MHz_High_QPSK_RB50#0




Date: 11.FEB.2022 10:41:51

Band 41_10 MHz_High_16QAM_RB50#0




Date: 11.FEB.2022 10:42:13

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 11.FEB.2022 10:42:47

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 11.FEB.2022 10:43:14

Band 41_15 MHz_High_QPSK_RB75#0




Date: 11.FEB.2022 10:43:38

Band 41_15 MHz_High_16QAM_RB75#0




Date: 11.FEB.2022 11:12:36

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 11.FEB.2022 10:44:36

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 11.FEB.2022 10:45:02

Band 41_20 MHz_High_QPSK_RB100#0



Date: 11.FEB.2022 10:45:30

Band 41_20 MHz_High_16QAM_RB100#0



Date: 11.FEB.2022 10:45:56