



10MHz_30kHz_2501.01MHz_DFT-s-OFDM QPSK_RB1@0 -46.48 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:14:59

10MHz_30kHz_2501.01MHz_DFT-s-OFDM QPSK_RB1@0 -37.14 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:15:58

10MHz_30kHz_2501.01MHz_DFT-s-OFDM QPSK_RB1@23 -47.04 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:16:54

10MHz_30kHz_2501.01MHz_DFT-s-OFDM QPSK_RB1@23 -36.69 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:17:50

10MHz_30kHz_2501.01MHz_DFT-s-OFDM QPSK_RB24@0 -46.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:18:43

10MHz_30kHz_2501.01MHz_DFT-s-OFDM QPSK_RB24@0 -36.50 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:19:40

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.13 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:21:36

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.77 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:20:40

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@23 -46.59 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:22:32

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@23 -36.55 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:23:28

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB24@0 -46.76 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:24:26

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB24@0 -37.03 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:25:22

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@0 -46.59 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:26:22

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@0 -37.08 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:27:20

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@23 -36.29 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:29:18

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@23 -46.67 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:28:21

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB24@0 -46.97 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:30:14

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB24@0 -36.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:31:11

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.62 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:00:10

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.15 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:01:03

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@78 -37.27 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:02:20

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@78 -45.89 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:01:33

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.30 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:02:51

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB75@0 -36.44 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:03:38

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -36.40 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:05:15

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -47.28 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:04:28

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@78 -47.63 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:05:45

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@78 -36.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:06:33

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB75@0 -36.27 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:07:50

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB75@0 -46.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:07:03

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB1@0 -36.78 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:09:30

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB1@0 -46.00 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:08:43

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB1@78 -36.87 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:10:49

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB1@78 -47.05 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:10:02

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB75@0 -36.83 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:12:09

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB75@0 -46.43 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:11:20

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.89 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:32:14

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.00 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:33:11

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@37 -46.58 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:34:08

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@37 -36.80 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:35:04

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.82 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:36:00

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB36@0 -36.97 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:36:59

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -36.55 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:39:00

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:38:03

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@37 -37.06 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:40:52

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@37 -45.87 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:39:55

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB36@0 -47.11 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:41:47

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB36@0 -36.90 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 13:42:43

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB1@0 -47.22 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:43:46

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB1@0 -36.80 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:44:38

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB1@37 -37.36 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:47:25

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB1@37 -46.44 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:46:27

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB36@0 -36.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:49:16

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB36@0 -47.46 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:48:16

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB1@0 -46.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:12:47

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB1@0 -36.67 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:13:35

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB1@105 -46.97 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:14:07

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB1@105 -35.93 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:14:56

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB100@0 -47.02 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:15:28

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB100@0 -36.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:16:16

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -46.44 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:16:51

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -36.43 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:17:40

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@105 -36.84 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:18:59

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@105 -46.07 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:18:11

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB100@0 -37.20 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:20:19

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB100@0 -46.79 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:19:31

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.11 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:21:44

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.27 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:20:54

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@105 -46.26 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:22:17

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@105 -36.96 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:23:06

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB100@0 -36.78 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:24:26

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB100@0 -47.13 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:23:38

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB1@0 -46.90 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:50:50

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB1@0 -37.04 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:51:50

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB1@50 -37.00 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:03:24

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB1@50 -47.06 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:02:24

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB50@0 -36.99 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:04:58

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB50@0 -47.51 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:04:08

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -36.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:06:21

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:05:33

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@50 -36.64 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:07:40

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@50 -46.97 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:06:52

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB50@0 -36.74 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:08:59

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB50@0 -46.89 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:08:11

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.06 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:10:19

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.36 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:09:31

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@50 -36.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:11:38

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@50 -46.76 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:10:50

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB50@0 -45.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:12:10

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB50@0 -35.49 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:12:57

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB1@0 -36.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:25:55

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB1@0 -47.04 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:25:06

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB1@159 -37.06 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:27:17

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB1@159 -47.19 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:26:27

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB160@0 -36.62 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:28:39

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB160@0 -46.51 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:27:50

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -47.01 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:29:14

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -36.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:30:04

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@159 -36.95 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:31:25

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@159 -47.46 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:30:37

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB160@0 -36.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:32:47

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB160@0 -46.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:31:59

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB1@0 -46.32 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:33:42

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB1@0 -36.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:34:31

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB1@159 -47.22 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:35:04

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB1@159 -36.56 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:35:53

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB160@0 -47.34 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:36:25

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB160@0 -36.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:37:13

30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB1@0 -47.32 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:13:36

30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB1@0 -37.12 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:14:23

30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB1@77 -47.07 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:14:54

30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB1@77 -36.83 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:15:43

30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB75@0 -37.02 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:16:58

30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB75@0 -46.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:16:12

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.07 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:17:52

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -36.89 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:18:40

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@77 -37.32 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:19:58

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@77 -45.74 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:19:10

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB75@0 -36.83 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:21:14

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB75@0 -46.88 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:20:28

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB1@0 -46.89 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:54:18

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB1@0 -36.45 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:55:16

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB1@77 -36.92 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:57:13

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB1@77 -47.02 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:56:15

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB75@0 -36.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:58:59

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB75@0 -46.41 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:58:05

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@0 -46.90 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 12:37:56

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@0 -36.74 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 12:38:44

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@215 -36.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 12:40:05

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@215 -46.59 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 12:39:16

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB216@0 -35.65 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 12:41:25

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB216@0 -46.32 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 16.MAR.2024 12:40:37

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -46.78 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:42:24

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -36.55 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:43:14

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@215 -35.90 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:45:07

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@215 -46.48 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:44:07

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB216@0 -47.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:45:59

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB216@0 -36.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:46:53

40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB1@0 -36.97 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:49:00

40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB1@0 -47.35 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:48:02

40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB1@215 -46.56 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:49:56

40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB1@215 -36.53 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:50:56

40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB216@0 -46.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:51:52

40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB216@0 -36.29 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:52:49

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@0 -37.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:00:54

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@0 -47.36 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 14:59:58

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@105 -46.87 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:01:44

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@105 -36.20 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:02:39

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB100@0 -36.38 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:04:22

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB100@0 -46.93 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:03:29

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.28 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:05:59

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.69 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:05:12

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@105 -37.06 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:07:23

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@105 -46.39 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:06:31

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB100@0 -36.82 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:08:51

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB100@0 -47.00 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:08:04

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB1@0 -47.03 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:09:26

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB1@0 -35.78 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:10:14

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB1@105 -46.70 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:10:44

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB1@105 -37.12 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:11:32

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB100@0 -36.79 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:12:53

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB100@0 -46.65 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:12:03

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB1@0 -36.79 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:54:49

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB1@0 -46.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:53:49

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB1@269 -36.53 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:56:50

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB1@269 -46.34 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:55:50

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB270@0 -47.07 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:57:46

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB270@0 -36.97 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 12:58:45

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -36.42 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:01:32

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -46.96 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:00:35

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@269 -37.00 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:03:32

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@269 -46.48 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:02:32

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB270@0 -46.88 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:04:30

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB270@0 -36.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:05:27

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.30 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:07:22

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.29 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:06:24

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@269 -36.86 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:09:29

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@269 -46.11 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:08:21

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB270@0 -46.99 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:10:26

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB270@0 -36.74 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 13:11:20

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB1@0 -46.84 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:13:50

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB1@0 -36.82 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:14:52

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB1@132 -46.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:15:36

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB1@132 -36.42 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:16:29

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB128@0 -46.68 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:18:20

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB128@0 -36.41 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:19:17

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.17 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:21:01

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.04 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:20:06

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@132 -36.79 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:22:42

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@132 -46.27 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:21:49

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB128@0 -47.18 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:23:30

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB128@0 -36.89 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:24:22

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@0 -36.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:26:53

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.53 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:26:02

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@132 -47.36 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:27:25

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@132 -36.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:28:14

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB128@0 -36.45 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:29:33

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB128@0 -45.68 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:28:46

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@0 -36.05 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:31:29

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@0 -47.24 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:30:41

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@161 -36.90 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:32:51

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@161 -46.94 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:32:01

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB162@0 -36.68 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:34:10

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB162@0 -47.42 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:33:22

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -36.94 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:35:34

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.11 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:34:46

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@161 -37.36 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:36:53

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@161 -46.65 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:36:06

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB162@0 -46.72 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:37:25

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB162@0 -37.25 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:38:13

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB1@0 -36.80 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:39:37

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB1@0 -47.34 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:38:49

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB1@161 -45.30 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:40:10

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB1@161 -37.11 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:40:59

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB162@0 -37.01 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:42:16

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB162@0 -46.69 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 16.MAR.2024 15:41:29