



15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.62 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:20:38

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -45.68 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:19:37

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@78 -37.51 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:22:20

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@78 -46.63 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:21:18

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 -36.89 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:24:01

15MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 -47.12 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:22:58

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.39 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:36:43

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:35:41

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@78 -46.68 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:37:19

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@78 -37.32 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:38:21

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.49 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:38:58

15MHz_15kHz_3792.5MHz_DFT-s-OFDM QPSK_RB75@0 -37.66 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:39:59

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.46 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:29:46

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:30:57

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -46.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:32:07

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.68 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:33:20

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -37.94 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:35:37

15MHz_30kHz_3707.5MHz_DFT-s-OFDM QPSK_RB36@0 -46.88 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:34:26

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.37 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:40:18

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.15 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:39:18

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@37 -37.06 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:42:23

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@37 -46.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:41:14

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB36@0 -46.83 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:43:23

15MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB36@0 -37.30 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:44:34

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.12 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:47:06

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.22 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:45:57

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@37 -46.27 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:48:03

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.35 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:49:03

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB36@0 -36.79 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:50:32

15MHz_30kHz_3792.5MHz_DFT-s-OFDM QPSK_RB36@0 -47.29 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:49:33

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.77 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:40:44

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.42 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:41:45

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@132 -46.55 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:42:21

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@132 -37.34 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:43:23

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB128@0 -46.15 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:43:59

25MHz_15kHz_3712.5MHz_DFT-s-OFDM QPSK_RB128@0 -37.50 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:45:00

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:46:43

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.14 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:45:42

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -46.68 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:47:20

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -36.66 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:48:21

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -46.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:48:58

25MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -37.13 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:50:00

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.19 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:50:42

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:51:44

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@132 -46.89 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:52:21

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@132 -37.30 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:53:22

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB128@0 -37.65 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:55:00

25MHz_15kHz_3787.5MHz_DFT-s-OFDM QPSK_RB128@0 -46.79 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:53:59

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.32 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:52:51

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@0 -36.80 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:53:50

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@64 -47.07 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:54:19

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB1@64 -37.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:55:18

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB64@0 -46.92 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:55:48

25MHz_30kHz_3712.5MHz_DFT-s-OFDM QPSK_RB64@0 -37.77 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:56:47

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.59 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:58:21

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.31 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:57:22

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@64 -46.87 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:58:50

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@64 -37.78 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 16:59:49

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB64@0 -37.37 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 17:01:19

25MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB64@0 -47.21 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 17:00:20

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.28 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 17:03:46

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@0 -45.82 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 17:02:44

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@64 -37.49 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 17:05:18

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB1@64 -43.67 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 17:04:19

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB64@0 -46.84 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:33:01

25MHz_30kHz_3787.5MHz_DFT-s-OFDM QPSK_RB64@0 -37.60 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:34:00

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -37.30 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:56:46

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -47.06 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:55:45

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@159 -45.45 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:57:24

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB1@159 -37.38 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:58:26

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -34.54 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:00:03

30MHz_15kHz_3715MHz_DFT-s-OFDM QPSK_RB160@0 -46.18 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 14:59:02

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.00 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:08:04

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.62 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:07:03

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@159 -46.53 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:08:40

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@159 -37.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:09:42

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB160@0 -37.40 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:11:21

30MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB160@0 -46.62 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:10:19

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -46.66 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:12:02

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -37.17 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:13:04

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@159 -46.29 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:13:42

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB1@159 -37.65 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:14:43

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB160@0 -46.57 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:15:20

30MHz_15kHz_3785MHz_DFT-s-OFDM QPSK_RB160@0 -37.60 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:16:22

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -46.92 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:34:38

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@0 -37.46 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:35:37

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@77 -37.45 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:37:08

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB1@77 -47.39 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:36:08

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB75@0 -46.90 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:37:38

30MHz_30kHz_3715MHz_DFT-s-OFDM QPSK_RB75@0 -37.20 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:38:37

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.59 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:40:09

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -47.25 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:39:11

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@77 -47.01 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:40:39

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@77 -37.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:41:39

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 -37.47 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:43:08

30MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB75@0 -47.16 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:42:09

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -35.03 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:44:42

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@0 -46.57 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:43:43

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@77 -46.96 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:45:12

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB1@77 -37.63 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:46:12

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB75@0 -46.52 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:46:42

30MHz_30kHz_3785MHz_DFT-s-OFDM QPSK_RB75@0 -37.67 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:47:41

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -37.53 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:18:11

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -46.45 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:17:08

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@215 -47.33 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:18:48

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB1@215 -37.17 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:19:50

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB216@0 -37.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:21:28

40MHz_15kHz_3720MHz_DFT-s-OFDM QPSK_RB216@0 -46.72 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:20:27

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.32 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:23:16

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.57 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:22:14

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@215 -37.68 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:24:56

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@215 -45.99 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:23:54

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB216@0 -37.36 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:26:35

40MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB216@0 -46.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:25:33

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0 -46.90 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:36:46

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0 -37.50 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:37:49

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB1@215 -36.62 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:39:28

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB1@215 -46.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:38:27

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB216@0 -37.08 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:41:07

40MHz_15kHz_3780MHz_DFT-s-OFDM QPSK_RB216@0 -46.80 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:40:06

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -47.09 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:48:17

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@0 -37.82 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:49:16

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@105 -47.01 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:49:47

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB1@105 -37.37 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:50:46

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -47.20 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:51:17

40MHz_30kHz_3720MHz_DFT-s-OFDM QPSK_RB100@0 -37.64 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:52:17

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.05 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:53:50

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -45.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:52:51

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@105 -46.51 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:54:21

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@105 -37.36 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:55:20

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB100@0 -47.20 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:55:54

40MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB100@0 -37.62 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:56:53

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0 -46.80 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:57:29

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@0 -37.16 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:58:28

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@105 -36.24 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:59:59

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB1@105 -46.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 13:58:59

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB100@0 -46.58 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:00:30

40MHz_30kHz_3780MHz_DFT-s-OFDM QPSK_RB100@0 -37.20 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:01:30

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -46.60 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:41:53

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -37.00 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:42:54

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@269 -37.43 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:44:34

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB1@269 -46.41 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:43:32

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -47.07 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:45:12

50MHz_15kHz_3725MHz_DFT-s-OFDM QPSK_RB270@0 -37.67 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:46:13

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.30 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:46:57

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -36.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:47:59

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@269 -46.93 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:48:35

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB1@269 -37.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:49:37

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -37.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:51:15

50MHz_15kHz_3750MHz_DFT-s-OFDM QPSK_RB270@0 -47.20 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 18.MAR.2024 15:50:14

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -37.51 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:52:59

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -45.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:51:57

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@269 -47.26 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:53:36

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB1@269 -37.48 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:54:38

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB270@0 -37.21 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:56:21

50MHz_15kHz_3775MHz_DFT-s-OFDM QPSK_RB270@0 -46.88 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 18.MAR.2024 15:55:17

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -46.75 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:02:07

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@0 -36.71 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:03:07

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@132 -47.20 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:03:39

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB1@132 -37.46 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:04:39

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -37.71 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:06:10

50MHz_30kHz_3725MHz_DFT-s-OFDM QPSK_RB128@0 -47.21 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:05:10

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:07:44

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.27 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:06:45

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -37.22 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:09:15

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@132 -46.88 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:08:15

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -37.10 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:10:45

50MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB128@0 -43.62 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:09:46

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -46.38 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:11:21

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@0 -37.72 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:12:20

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@132 -46.53 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:12:52

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB1@132 -37.26 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:13:52

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB128@0 -45.78 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:14:22

50MHz_30kHz_3775MHz_DFT-s-OFDM QPSK_RB128@0 -37.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:15:22

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -46.41 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:16:02

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@0 -37.42 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:17:01

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@161 -37.27 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:18:33

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB1@161 -46.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:17:33

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -46.63 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:19:03

60MHz_30kHz_3730MHz_DFT-s-OFDM QPSK_RB162@0 -37.83 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:20:03

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -45.85 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:20:37

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.50 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:21:36

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@161 -37.38 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:23:07

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@161 -47.02 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:22:07

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB162@0 -47.05 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:23:38

60MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB162@0 -37.35 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:24:38

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@0 -45.99 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 19.MAR.2024 14:25:14

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@0 -37.23 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 19.MAR.2024 14:26:14

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@161 -37.13 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 19.MAR.2024 14:27:46

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB1@161 -46.40 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 19.MAR.2024 14:26:45

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB162@0 -37.22 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 19.MAR.2024 14:29:18

60MHz_30kHz_3770MHz_DFT-s-OFDM QPSK_RB162@0 -46.67 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
 Date: 19.MAR.2024 14:28:18

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -37.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:30:57

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0 -47.15 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:29:56

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188 -44.65 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:31:30

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188 -37.18 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:32:31

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -37.61 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:34:03

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0 -45.88 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:33:03

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -46.73 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:34:39

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0 -37.00 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:35:39

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@188 -47.05 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:36:11

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@188 -37.50 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:37:11

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB180@0 -37.20 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:38:45

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB180@0 -46.91 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:37:44

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@0 -37.57 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:40:23

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@0 -47.05 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:39:22

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@188 -37.07 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:41:57

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@188 -46.81 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:40:56

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB180@0 -37.14 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:43:34

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB180@0 -46.50 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:42:33

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0 -37.33 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:45:19

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@0 -47.26 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:44:18

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@216 -46.96 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:45:53

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB1@216 -37.39 dBm




ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:46:54

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0 -36.95 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:48:30

80MHz_30kHz_3740MHz_DFT-s-OFDM QPSK_RB216@0 -47.04 dBm



ProjectNo.:SZ1240108-01736E Tester:Jim Cheng
Date: 19.MAR.2024 14:47:28