



15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@0
-28.83 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:14:58

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB1@37
-28.72 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:16:14

15MHz_30kHz_3457.5MHz_DFT-s-OFDM QPSK_RB36@0
-28.39 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:17:31

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-28.45 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:19:09

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@37
-28.80 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:20:24

15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB36@0
-28.36 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:21:39

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@0
-28.81 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:23:19

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB1@37
-28.40 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:24:33

15MHz_30kHz_3542.5MHz_DFT-s-OFDM QPSK_RB36@0
-28.50 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:25:49

25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB1@0
-28.43 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:27:28

25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB1@64
-28.46 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:28:43

25MHz_30kHz_3462.5MHz_DFT-s-OFDM QPSK_RB64@0
-28.70 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:30:00

25MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-28.53 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 15:29:55

25MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@64
-28.73 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 15:31:13

25MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB64@0
-28.60 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 15:32:30

25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB1@0
-28.56 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 15:34:11

25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB1@64
-28.61 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 15:35:26

25MHz_30kHz_3537.5MHz_DFT-s-OFDM QPSK_RB64@0
-28.44 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 15:36:42

30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@0
-28.82 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 15:38:23

30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@77
-28.35 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 15:39:40

30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB75@0
-28.74 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 15:40:56

30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-28.09 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:31:39

30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@77
-28.87 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:32:54

30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB75@0
-28.78 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:34:09

30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@0
-28.74 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 20:38:00

30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@77
-28.61 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 20:39:17

30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB75@0
-28.62 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 20:40:33

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0
-27.97 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:38:22

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@105
-28.40 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:39:38

40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB100@0
-28.42 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:40:54

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-28.22 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:42:35

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@105
-28.61 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:43:52

40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB100@0
-27.72 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:45:08

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0
-28.36 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:46:49

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@105
-28.51 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:48:05

40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB100@0
-28.75 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:49:23

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0
-28.61 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:51:01

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@132
-28.55 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:52:16

50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB128@0
-28.02 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:53:32

50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-28.20 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:55:14

50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@132
-28.50 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:56:28

50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB128@0
-27.97 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:57:44

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0
-27.97 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 17:59:23

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@132
-28.58 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:00:38

50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB128@0
-28.46 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:01:53

60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0
-28.04 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:03:32

60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@161
-28.61 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:04:47

60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB162@0
-28.41 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:06:05

60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-28.51 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:07:45

60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@161
-28.40 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:09:03

60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB162@0
-28.43 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:10:19

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@0
-28.50 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:11:57

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@161
-28.56 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:13:13

60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB162@0
-28.17 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:14:29

70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0
-28.80 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:16:08

70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@188
-28.45 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:17:23

70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB180@0
-28.36 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:18:39

70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-28.43 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:20:19

70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@188
-28.52 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:21:35

70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB180@0
-28.38 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:22:52

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@0
-28.55 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:24:33

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@188
-28.39 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:25:57

70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB180@0
-28.21 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:27:13

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@0
-28.62 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:28:52

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@216
-29.11 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:30:09

80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB216@0
-28.26 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:31:26

80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-28.14 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:33:07

80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@216
-28.86 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:34:24

80MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB216@0
-28.32 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:35:40

80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@0
-28.10 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:37:19

80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB1@216
-28.51 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:38:35

80MHz_30kHz_3510MHz_DFT-s-OFDM QPSK_RB216@0
-28.25 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:39:51

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@0
-28.46 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:41:31

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB1@244
-28.58 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 18:42:47

90MHz_30kHz_3495MHz_DFT-s-OFDM QPSK_RB243@0
-28.32 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 20:42:13

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-28.30 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 20:43:52

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@244
-28.63 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 20:45:09

90MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB243@0
-28.20 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 20:46:26

90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@0
-28.43 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 20:48:07

90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB1@244
-27.90 dBm



ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 20:49:24


90MHz_30kHz_3505MHz_DFT-s-OFDM QPSK_RB243@0
-28.49 dBm



ProjectNo.:CR231165634-RF Tester:One Luo
Date: 27.DEC.2023 20:50:41


n78_2

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@0
-25.62 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 28.DEC.2023 04:34:04

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB1@188
-25.21 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 28.DEC.2023 04:35:28

70MHz_30kHz_3735MHz_DFT-s-OFDM QPSK_RB180@0
-25.28 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 28.DEC.2023 04:36:52

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@0
-25.09 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 28.DEC.2023 19:01:38

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@188
-25.56 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 28.DEC.2023 19:02:56

70MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB180@0
-25.79 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 28.DEC.2023 19:04:14

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@0
-25.14 dBm




ProjectNo.:CR231165634-RF Tester:One Luo
Date: 28.DEC.2023 04:42:02

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB1@188
-25.53 dBm



ProjectNo.:CR231165634-RF Tester:One Luo
Date: 28.DEC.2023 04:43:26

70MHz_30kHz_3765MHz_DFT-s-OFDM QPSK_RB180@0
-25.73 dBm



ProjectNo.:CR231165634-RF Tester:One Luo
Date: 28.DEC.2023 04:44:50