



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 17.MAR.2021 20:49:20

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 17.MAR.2021 20:49:42

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 17.MAR.2021 20:50:08

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 17.MAR.2021 20:50:33

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 17.MAR.2021 20:50:58

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 17.MAR.2021 20:51:25

Band 2_3 MHz_High_QPSK_RB15#0




Date: 17.MAR.2021 20:51:50

Band 2_3 MHz_High_16QAM_RB15#0




Date: 17.MAR.2021 20:52:16

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 17.MAR.2021 20:52:47

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 17.MAR.2021 20:53:16

Band 2_5 MHz_High_QPSK_RB25#0




Date: 17.MAR.2021 20:53:50

Band 2_5 MHz_High_16QAM_RB25#0




Date: 17.MAR.2021 20:54:19

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 17.MAR.2021 20:54:56

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 17.MAR.2021 20:55:29

Band 2_10 MHz_High_QPSK_RB50#0




Date: 17.MAR.2021 20:56:00

Band 2_10 MHz_High_16QAM_RB50#0




Date: 17.MAR.2021 20:56:40

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 17.MAR.2021 20:57:18

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 17.MAR.2021 20:58:11

Band 2_15 MHz_High_QPSK_RB75#0




Date: 17.MAR.2021 20:58:46

Band 2_15 MHz_High_16QAM_RB75#0




Date: 17.MAR.2021 20:59:38

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 17.MAR.2021 21:00:23

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 17.MAR.2021 21:01:03

Band 2_20 MHz_High_QPSK_RB100#0




Date: 17.MAR.2021 21:01:47

Band 2_20 MHz_High_16QAM_RB100#0




Date: 17.MAR.2021 21:02:27

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 17.MAR.2021 21:02:55

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 17.MAR.2021 21:03:35

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 17.MAR.2021 21:04:52

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 17.MAR.2021 21:05:17

Band 4_3 MHz_High_QPSK_RB15#0




Date: 17.MAR.2021 21:05:45

Band 4_3 MHz_High_16QAM_RB15#0




Date: 17.MAR.2021 21:06:13

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 17.MAR.2021 21:06:44

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 17.MAR.2021 21:07:18

Band 4_5 MHz_High_QPSK_RB25#0




Date: 17.MAR.2021 21:07:44

Band 4_5 MHz_High_16QAM_RB25#0




Date: 17.MAR.2021 21:08:20

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 17.MAR.2021 21:09:01

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 17.MAR.2021 21:09:46

Band 4_10 MHz_High_QPSK_RB50#0




Date: 17.MAR.2021 21:10:23

Band 4_10 MHz_High_16QAM_RB50#0




Date: 17.MAR.2021 21:11:00

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 17.MAR.2021 21:11:33

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 17.MAR.2021 21:12:13

Band 4_15 MHz_High_QPSK_RB75#0




Date: 17.MAR.2021 21:12:51

Band 4_15 MHz_High_16QAM_RB75#0




Date: 17.MAR.2021 21:13:46

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 17.MAR.2021 21:14:33

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 17.MAR.2021 21:15:14

Band 4_20 MHz_High_QPSK_RB100#0




Date: 17.MAR.2021 21:15:57

Band 4_20 MHz_High_16QAM_RB100#0




Date: 17.MAR.2021 21:16:40

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 22.MAR.2021 20:02:47

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 22.MAR.2021 20:03:09

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 5.FEB.2021 18:00:18

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 5.FEB.2021 18:00:45

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 5.FEB.2021 18:01:12

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 5.FEB.2021 18:01:34

Band 5_3 MHz_High_QPSK_RB15#0




Date: 5.FEB.2021 18:01:58

Band 5_3 MHz_High_16QAM_RB15#0




Date: 5.FEB.2021 18:02:21

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 5.FEB.2021 18:02:52

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 5.FEB.2021 18:03:17

Band 5_5 MHz_High_QPSK_RB25#0




Date: 5.FEB.2021 18:03:48

Band 5_5 MHz_High_16QAM_RB25#0




Date: 5.FEB.2021 18:04:13

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 5.FEB.2021 18:04:47

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 5.FEB.2021 18:05:21

Band 5_10 MHz_High_QPSK_RB50#0




Date: 5.FEB.2021 18:05:56

Band 5_10 MHz_High_16QAM_RB50#0




Date: 5.FEB.2021 18:06:33

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 17.MAR.2021 21:17:04

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 17.MAR.2021 21:17:38

Band 7_5 MHz_High_QPSK_RB25#0




Date: 17.MAR.2021 21:18:09

Band 7_5 MHz_High_16QAM_RB25#0




Date: 17.MAR.2021 21:18:37

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 17.MAR.2021 21:19:13

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 17.MAR.2021 21:19:43

Band 7_10 MHz_High_QPSK_RB50#0




Date: 17.MAR.2021 21:20:17

Band 7_10 MHz_High_16QAM_RB50#0




Date: 17.MAR.2021 21:20:56

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 17.MAR.2021 21:21:34

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 17.MAR.2021 21:22:15

Band 7_15 MHz_High_QPSK_RB75#0




Date: 17.MAR.2021 21:23:06

Band 7_15 MHz_High_16QAM_RB75#0




Date: 17.MAR.2021 21:23:47

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 17.MAR.2021 21:24:32

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 17.MAR.2021 21:25:13

Band 7_20 MHz_High_QPSK_RB100#0




Date: 17.MAR.2021 21:25:58

Band 7_20 MHz_High_16QAM_RB100#0




Date: 17.MAR.2021 21:26:42

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 22.MAR.2021 17:24:34

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 22.MAR.2021 17:25:54

Band 17_5 MHz_High_QPSK_RB25#0




Date: 22.MAR.2021 17:27:04

Band 17_5 MHz_High_16QAM_RB25#0




Date: 22.MAR.2021 17:29:03

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 22.MAR.2021 17:18:10

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 22.MAR.2021 17:18:47

Band 17_10 MHz_High_QPSK_RB50#0




Date: 22.MAR.2021 17:19:20

Band 17_10 MHz_High_16QAM_RB50#0




Date: 22.MAR.2021 17:19:57

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 22.MAR.2021 20:05:52

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 22.MAR.2021 20:06:19

Band 38_5 MHz_High_QPSK_RB25#0




Date: 22.MAR.2021 20:07:42

Band 38_5 MHz_High_16QAM_RB25#0




Date: 5.FEB.2021 18:16:35

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 22.MAR.2021 20:09:30

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 5.FEB.2021 18:17:37

Band 38_10 MHz_High_QPSK_RB50#0




Date: 5.FEB.2021 18:18:15

Band 38_10 MHz_High_16QAM_RB50#0




Date: 5.FEB.2021 18:18:40

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 22.MAR.2021 20:11:07

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 5.FEB.2021 18:20:02

Band 38_15 MHz_High_QPSK_RB75#0




Date: 22.MAR.2021 20:12:09

Band 38_15 MHz_High_16QAM_RB75#0




Date: 5.FEB.2021 18:21:18

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 22.MAR.2021 20:13:44

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 22.MAR.2021 20:15:22

Band 38_20 MHz_High_QPSK_RB100#0




Date: 5.FEB.2021 18:23:16

Band 38_20 MHz_High_16QAM_RB100#0




Date: 5.FEB.2021 18:23:49

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 22.MAR.2021 19:44:34

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 22.MAR.2021 19:45:15

Band 41_5 MHz_High_QPSK_RB25#0




Date: 22.MAR.2021 19:45:58

Band 41_5 MHz_High_16QAM_RB25#0




Date: 5.FEB.2021 20:08:16

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 5.FEB.2021 20:08:55

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 5.FEB.2021 20:09:25

Band 41_10 MHz_High_QPSK_RB50#0




Date: 5.FEB.2021 20:10:03

Band 41_10 MHz_High_16QAM_RB50#0




Date: 5.FEB.2021 20:10:40

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 5.FEB.2021 20:11:24

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 5.FEB.2021 20:12:01

Band 41_15 MHz_High_QPSK_RB75#0




Date: 5.FEB.2021 20:12:40

Band 41_15 MHz_High_16QAM_RB75#0




Date: 5.FEB.2021 20:13:22

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 5.FEB.2021 20:14:09

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 5.FEB.2021 20:14:39

Band 41_20 MHz_High_QPSK_RB100#0




Date: 5.FEB.2021 20:15:22

Band 41_20 MHz_High_16QAM_RB100#0




Date: 5.FEB.2021 20:16:08

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 17.MAR.2021 21:27:01

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 17.MAR.2021 21:27:22

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 17.MAR.2021 21:27:47

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 17.MAR.2021 21:28:11

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 17.MAR.2021 21:28:36

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 17.MAR.2021 21:29:04

Band 66_3 MHz_High_QPSK_RB15#0




Date: 17.MAR.2021 21:29:33

Band 66_3 MHz_High_16QAM_RB15#0




Date: 17.MAR.2021 21:30:00

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 17.MAR.2021 21:30:34

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 17.MAR.2021 21:31:04

Band 66_5 MHz_High_QPSK_RB25#0




Date: 17.MAR.2021 21:31:32

Band 66_5 MHz_High_16QAM_RB25#0




Date: 17.MAR.2021 21:32:07

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 17.MAR.2021 21:32:48

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 17.MAR.2021 21:33:20

Band 66_10 MHz_High_QPSK_RB50#0




Date: 17.MAR.2021 21:33:57

Band 66_10 MHz_High_16QAM_RB50#0




Date: 17.MAR.2021 21:34:34

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 17.MAR.2021 21:35:23

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 17.MAR.2021 21:36:12

Band 66_15 MHz_High_QPSK_RB75#0




Date: 17.MAR.2021 21:36:47

Band 66_15 MHz_High_16QAM_RB75#0




Date: 17.MAR.2021 21:37:25

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 17.MAR.2021 21:37:58

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 17.MAR.2021 21:38:46

Band 66_20 MHz_High_QPSK_RB100#0



Date: 17.MAR.2021 21:39:29

Band 66_20 MHz_High_16QAM_RB100#0



Date: 17.MAR.2021 21:40:13