



Please refer to following plots:




Date: 9.SEP.2021 09:37:14




Date: 8.SEP.2021 16:36:38

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 8.SEP.2021 16:36:58

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 8.SEP.2021 16:37:15

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 8.SEP.2021 16:37:38

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 8.SEP.2021 16:37:54

Band 2_3 MHz_High_QPSK_RB15#0




Date: 8.SEP.2021 16:38:15

Band 2_3 MHz_High_16QAM_RB15#0




Date: 8.SEP.2021 16:38:32

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 8.SEP.2021 16:38:54

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 8.SEP.2021 16:39:14

Band 2_5 MHz_High_QPSK_RB25#0




Date: 8.SEP.2021 16:39:35

Band 2_5 MHz_High_16QAM_RB25#0




Date: 8.SEP.2021 16:39:55

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 8.SEP.2021 16:40:17

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 8.SEP.2021 16:40:36

Band 2_10 MHz_High_QPSK_RB50#0




Date: 8.SEP.2021 16:40:56

Band 2_10 MHz_High_16QAM_RB50#0




Date: 8.SEP.2021 16:41:15

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 8.SEP.2021 16:41:42

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 8.SEP.2021 16:42:05

Band 2_15 MHz_High_QPSK_RB75#0




Date: 8.SEP.2021 16:42:30

Band 2_15 MHz_High_16QAM_RB75#0




Date: 8.SEP.2021 16:42:53

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 8.SEP.2021 16:43:26

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 8.SEP.2021 16:43:53

Band 2_20 MHz_High_QPSK_RB100#0




Date: 8.SEP.2021 16:44:17

Band 2_20 MHz_High_16QAM_RB100#0




Date: 8.SEP.2021 16:44:46

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 8.SEP.2021 16:45:10

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 8.SEP.2021 16:45:30

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 8.SEP.2021 16:45:48

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 8.SEP.2021 16:46:05

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 8.SEP.2021 16:46:25

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 8.SEP.2021 16:46:45

Band 4_3 MHz_High_QPSK_RB15#0




Date: 8.SEP.2021 16:47:02

Band 4_3 MHz_High_16QAM_RB15#0




Date: 8.SEP.2021 16:47:19

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 8.SEP.2021 16:47:39

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 8.SEP.2021 16:47:59

Band 4_5 MHz_High_QPSK_RB25#0




Date: 8.SEP.2021 16:48:20

Band 4_5 MHz_High_16QAM_RB25#0




Date: 8.SEP.2021 16:48:40

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 8.SEP.2021 16:49:02

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 8.SEP.2021 16:49:21

Band 4_10 MHz_High_QPSK_RB50#0




Date: 8.SEP.2021 16:49:41

Band 4_10 MHz_High_16QAM_RB50#0




Date: 8.SEP.2021 16:50:00

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 8.SEP.2021 16:50:26

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 8.SEP.2021 16:50:53

Band 4_15 MHz_High_QPSK_RB75#0




Date: 8.SEP.2021 16:51:17

Band 4_15 MHz_High_16QAM_RB75#0




Date: 8.SEP.2021 16:51:41

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 8.SEP.2021 16:52:07

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 8.SEP.2021 16:52:34

Band 4_20 MHz_High_QPSK_RB100#0




Date: 8.SEP.2021 16:53:02

Band 4_20 MHz_High_16QAM_RB100#0




Date: 8.SEP.2021 16:53:28

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 9.SEP.2021 09:40:46

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 8.SEP.2021 16:54:11

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 8.SEP.2021 16:54:32

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 8.SEP.2021 16:54:52

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 8.SEP.2021 16:55:17

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 8.SEP.2021 16:55:34

Band 5_3 MHz_High_QPSK_RB15#0




Date: 8.SEP.2021 16:55:55

Band 5_3 MHz_High_16QAM_RB15#0




Date: 8.SEP.2021 16:56:12

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 8.SEP.2021 16:56:31

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 8.SEP.2021 16:56:48

Band 5_5 MHz_High_QPSK_RB25#0




Date: 8.SEP.2021 16:57:09

Band 5_5 MHz_High_16QAM_RB25#0




Date: 8.SEP.2021 16:57:29

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 8.SEP.2021 16:57:50

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 8.SEP.2021 16:58:09

Band 5_10 MHz_High_QPSK_RB50#0




Date: 8.SEP.2021 16:58:32

Band 5_10 MHz_High_16QAM_RB50#0




Date: 8.SEP.2021 16:58:51

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 8.SEP.2021 16:59:11

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 8.SEP.2021 16:59:28

Band 7_5 MHz_High_QPSK_RB25#0




Date: 8.SEP.2021 16:59:49

Band 7_5 MHz_High_16QAM_RB25#0




Date: 8.SEP.2021 17:00:09

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 8.SEP.2021 17:00:30

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 8.SEP.2021 17:00:49

Band 7_10 MHz_High_QPSK_RB50#0




Date: 8.SEP.2021 17:01:12

Band 7_10 MHz_High_16QAM_RB50#0




Date: 8.SEP.2021 17:01:31

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 8.SEP.2021 17:01:58

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 8.SEP.2021 17:02:21

Band 7_15 MHz_High_QPSK_RB75#0




Date: 8.SEP.2021 17:02:46

Band 7_15 MHz_High_16QAM_RB75#0




Date: 8.SEP.2021 17:03:15

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 8.SEP.2021 17:03:42

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 8.SEP.2021 17:04:06

Band 7_20 MHz_High_QPSK_RB100#0




Date: 8.SEP.2021 17:04:30

Band 7_20 MHz_High_16QAM_RB100#0




Date: 8.SEP.2021 17:04:57

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 9.SEP.2021 09:45:06

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 9.SEP.2021 10:07:08

Band 17_5 MHz_High_QPSK_RB25#0




Date: 9.SEP.2021 10:09:21

Band 17_5 MHz_High_16QAM_RB25#0




Date: 9.SEP.2021 10:11:22

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 8.SEP.2021 17:06:36

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 8.SEP.2021 17:06:55

Band 17_10 MHz_High_QPSK_RB50#0




Date: 8.SEP.2021 17:07:15

Band 17_10 MHz_High_16QAM_RB50#0




Date: 8.SEP.2021 17:07:34

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 8.SEP.2021 09:50:29

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 8.NOV.2021 09:52:07

Band 38_5 MHz_High_QPSK_RB25#0




Date: 8.SEP.2021 09:51:22

Band 38_5 MHz_High_16QAM_RB25#0




Date: 8.SEP.2021 09:51:48

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 8.SEP.2021 09:52:17

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 8.SEP.2021 09:52:45

Band 38_10 MHz_High_QPSK_RB50#0




Date: 8.SEP.2021 09:53:08

Band 38_10 MHz_High_16QAM_RB50#0




Date: 8.SEP.2021 09:53:30

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 9.SEP.2021 11:30:31

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 8.SEP.2021 09:54:41

Band 38_15 MHz_High_QPSK_RB75#0




Date: 9.SEP.2021 11:26:55

Band 38_15 MHz_High_16QAM_RB75#0




Date: 8.SEP.2021 09:55:42

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 8.SEP.2021 09:56:17

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 8.SEP.2021 09:56:44

Band 38_20 MHz_High_QPSK_RB100#0




Date: 8.SEP.2021 09:57:18

Band 38_20 MHz_High_16QAM_RB100#0




Date: 8.SEP.2021 09:57:53

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 9.SEP.2021 13:34:27

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 9.SEP.2021 14:02:26

Band 41_5 MHz_High_QPSK_RB25#0




Date: 9.SEP.2021 14:04:22

Band 41_5 MHz_High_16QAM_RB25#0




Date: 9.SEP.2021 13:35:53

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 9.SEP.2021 13:36:24

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 9.SEP.2021 13:36:49

Band 41_10 MHz_High_QPSK_RB50#0




Date: 9.SEP.2021 13:37:15

Band 41_10 MHz_High_16QAM_RB50#0




Date: 9.SEP.2021 13:37:40

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 9.SEP.2021 14:07:24

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 9.SEP.2021 13:38:45

Band 41_15 MHz_High_QPSK_RB75#0




Date: 8.NOV.2021 09:55:47

Band 41_15 MHz_High_16QAM_RB75#0




Date: 9.SEP.2021 13:39:48

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 9.SEP.2021 13:40:24

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 9.SEP.2021 13:40:54

Band 41_20 MHz_High_QPSK_RB100#0




Date: 9.SEP.2021 13:41:27

Band 41_20 MHz_High_16QAM_RB100#0




Date: 9.SEP.2021 13:42:00

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 8.SEP.2021 17:08:04

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 8.SEP.2021 17:08:27

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 8.SEP.2021 17:08:48

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 8.SEP.2021 17:09:11

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 8.SEP.2021 17:09:35

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 8.SEP.2021 17:09:52

Band 66_3 MHz_High_QPSK_RB15#0




Date: 8.SEP.2021 17:10:12

Band 66_3 MHz_High_16QAM_RB15#0




Date: 8.SEP.2021 17:10:32

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 9.SEP.2021 10:15:43

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 9.SEP.2021 10:13:45

Band 66_5 MHz_High_QPSK_RB25#0




Date: 9.SEP.2021 10:17:58

Band 66_5 MHz_High_16QAM_RB25#0




Date: 9.SEP.2021 10:20:05

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 8.SEP.2021 17:12:26

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 8.SEP.2021 17:12:45

Band 66_10 MHz_High_QPSK_RB50#0




Date: 8.SEP.2021 17:13:05

Band 66_10 MHz_High_16QAM_RB50#0




Date: 8.SEP.2021 17:13:24

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 9.SEP.2021 10:24:25

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 9.SEP.2021 10:26:09

Band 66_15 MHz_High_QPSK_RB75#0




Date: 9.SEP.2021 10:28:06

Band 66_15 MHz_High_16QAM_RB75#0




Date: 9.SEP.2021 10:30:06

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 8.SEP.2021 17:15:35

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 8.SEP.2021 17:15:59

Band 66_20 MHz_High_QPSK_RB100#0



Date: 8.SEP.2021 17:16:26

Band 66_20 MHz_High_16QAM_RB100#0



Date: 8.SEP.2021 17:16:50