



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 7.NOV.2021 18:45:33

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 7.NOV.2021 18:45:54

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 7.NOV.2021 18:46:16

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 7.NOV.2021 18:46:37

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 7.NOV.2021 18:46:58

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 7.NOV.2021 18:47:15

Band 2_3 MHz_High_QPSK_RB15#0




Date: 7.NOV.2021 18:47:37

Band 2_3 MHz_High_16QAM_RB15#0




Date: 7.NOV.2021 18:47:54

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 7.NOV.2021 18:48:15

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 7.NOV.2021 18:48:33

Band 2_5 MHz_High_QPSK_RB25#0




Date: 7.NOV.2021 18:48:51

Band 2_5 MHz_High_16QAM_RB25#0




Date: 7.NOV.2021 18:49:12

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 7.NOV.2021 18:49:35

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 7.NOV.2021 18:49:55

Band 2_10 MHz_High_QPSK_RB50#0




Date: 7.NOV.2021 18:50:16

Band 2_10 MHz_High_16QAM_RB50#0




Date: 7.NOV.2021 18:50:36

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 7.NOV.2021 18:51:03

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 7.NOV.2021 18:51:28

Band 2_15 MHz_High_QPSK_RB75#0




Date: 7.NOV.2021 18:51:53

Band 2_15 MHz_High_16QAM_RB75#0




Date: 7.NOV.2021 18:52:17

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 7.NOV.2021 18:52:45

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 7.NOV.2021 18:53:09

Band 2_20 MHz_High_QPSK_RB100#0




Date: 8.NOV.2021 19:38:23

Band 2_20 MHz_High_16QAM_RB100#0




Date: 7.NOV.2021 18:54:02

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 7.NOV.2021 18:54:29

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 7.NOV.2021 18:54:53

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 7.NOV.2021 18:55:12

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 7.NOV.2021 18:55:32

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 7.NOV.2021 18:55:54

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 7.NOV.2021 18:56:14

Band 4_3 MHz_High_QPSK_RB15#0




Date: 7.NOV.2021 18:56:33

Band 4_3 MHz_High_16QAM_RB15#0




Date: 7.NOV.2021 18:56:50

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 7.NOV.2021 18:57:11

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 7.NOV.2021 18:57:32

Band 4_5 MHz_High_QPSK_RB25#0




Date: 7.NOV.2021 18:57:54

Band 4_5 MHz_High_16QAM_RB25#0




Date: 7.NOV.2021 18:58:11

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 7.NOV.2021 18:58:35

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 7.NOV.2021 18:58:55

Band 4_10 MHz_High_QPSK_RB50#0




Date: 7.NOV.2021 18:59:15

Band 4_10 MHz_High_16QAM_RB50#0




Date: 7.NOV.2021 18:59:35

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 7.NOV.2021 19:00:03

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 8.NOV.2021 19:39:42

Band 4_15 MHz_High_QPSK_RB75#0




Date: 7.NOV.2021 19:00:53

Band 4_15 MHz_High_16QAM_RB75#0




Date: 7.NOV.2021 19:01:17

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 7.NOV.2021 19:01:45

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 7.NOV.2021 19:02:09

Band 4_20 MHz_High_QPSK_RB100#0




Date: 7.NOV.2021 19:02:34

Band 4_20 MHz_High_16QAM_RB100#0




Date: 7.NOV.2021 19:02:59

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 7.NOV.2021 19:03:23

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 7.NOV.2021 19:03:40

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 7.NOV.2021 19:04:02

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 7.NOV.2021 19:04:20

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 7.NOV.2021 19:04:41

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 7.NOV.2021 19:04:58

Band 5_3 MHz_High_QPSK_RB15#0




Date: 7.NOV.2021 19:05:17

Band 5_3 MHz_High_16QAM_RB15#0




Date: 7.NOV.2021 19:05:34

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 7.NOV.2021 19:05:59

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 8.NOV.2021 19:41:03

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 7.NOV.2021 19:07:18

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 7.NOV.2021 19:07:41

Band 5_10 MHz_High_QPSK_RB50#0




Date: 7.NOV.2021 19:08:02

Band 5_10 MHz_High_16QAM_RB50#0




Date: 7.NOV.2021 19:08:22

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 7.NOV.2021 19:08:46

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 7.NOV.2021 19:09:04

Band 7_5 MHz_High_QPSK_RB25#0




Date: 7.NOV.2021 19:09:22

Band 7_5 MHz_High_16QAM_RB25#0




Date: 7.NOV.2021 19:09:40

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 7.NOV.2021 19:10:04

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 7.NOV.2021 19:10:24

Band 7_10 MHz_High_QPSK_RB50#0




Date: 8.NOV.2021 19:44:17

Band 7_10 MHz_High_16QAM_RB50#0




Date: 7.NOV.2021 19:11:04

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 7.NOV.2021 19:11:33

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 7.NOV.2021 19:11:57

Band 7_15 MHz_High_QPSK_RB75#0




Date: 7.NOV.2021 19:12:22

Band 7_15 MHz_High_16QAM_RB75#0




Date: 7.NOV.2021 19:12:46

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 7.NOV.2021 19:13:15

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 8.NOV.2021 19:45:38

Band 7_20 MHz_High_QPSK_RB100#0




Date: 7.NOV.2021 19:14:05

Band 7_20 MHz_High_16QAM_RB100#0




Date: 7.NOV.2021 19:14:29

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 7.NOV.2021 19:14:50

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 7.NOV.2021 19:15:08

Band 17_5 MHz_High_QPSK_RB25#0




Date: 7.NOV.2021 19:15:30

Band 17_5 MHz_High_16QAM_RB25#0




Date: 7.NOV.2021 19:15:50

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 7.NOV.2021 19:16:14

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 7.NOV.2021 19:16:37

Band 17_10 MHz_High_QPSK_RB50#0




Date: 7.NOV.2021 19:16:58

Band 17_10 MHz_High_16QAM_RB50#0




Date: 7.NOV.2021 19:17:17

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 7.NOV.2021 21:06:38

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 7.NOV.2021 21:07:05

Band 38_5 MHz_High_QPSK_RB25#0




Date: 8.NOV.2021 19:52:56

Band 38_5 MHz_High_16QAM_RB25#0




Date: 7.NOV.2021 21:07:59

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 7.NOV.2021 21:08:22

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 7.NOV.2021 21:08:45

Band 38_10 MHz_High_QPSK_RB50#0




Date: 7.NOV.2021 21:09:09

Band 38_10 MHz_High_16QAM_RB50#0




Date: 7.NOV.2021 21:09:35

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 7.NOV.2021 21:10:05

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 7.NOV.2021 21:10:39

Band 38_15 MHz_High_QPSK_RB75#0




Date: 7.NOV.2021 21:11:17

Band 38_15 MHz_High_16QAM_RB75#0




Date: 7.NOV.2021 21:11:54

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 7.NOV.2021 21:12:28

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 7.NOV.2021 21:12:58

Band 38_20 MHz_High_QPSK_RB100#0




Date: 7.NOV.2021 21:13:36


Band 38_20 MHz_High_16QAM_RB100#0



Date: 7.NOV.2021 21:14:10




Date: 7.NOV.2021 21:14:37




Date: 7.NOV.2021 21:15:01

Band 41_5 MHz_High_QPSK_RB25#0




Date: 7.NOV.2021 21:15:29

Band 41_5 MHz_High_16QAM_RB25#0




Date: 7.NOV.2021 21:15:56

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 7.NOV.2021 21:16:21

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 7.NOV.2021 21:16:44

Band 41_10 MHz_High_QPSK_RB50#0




Date: 7.NOV.2021 21:17:08

Band 41_10 MHz_High_16QAM_RB50#0




Date: 7.NOV.2021 21:17:34

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 7.NOV.2021 21:18:08

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 7.NOV.2021 21:18:38

Band 41_15 MHz_High_QPSK_RB75#0




Date: 7.NOV.2021 21:19:16

Band 41_15 MHz_High_16QAM_RB75#0




Date: 7.NOV.2021 21:19:53

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 7.NOV.2021 21:20:24

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 7.NOV.2021 21:20:51

Band 41_20 MHz_High_QPSK_RB100#0




Date: 7.NOV.2021 21:21:26

Band 41_20 MHz_High_16QAM_RB100#0




Date: 8.NOV.2021 19:56:29

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 8.NOV.2021 19:47:34

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 8.NOV.2021 19:48:53

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 7.NOV.2021 20:14:47

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 7.NOV.2021 20:15:08

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 7.NOV.2021 20:15:28

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 7.NOV.2021 20:15:45

Band 66_3 MHz_High_QPSK_RB15#0




Date: 7.NOV.2021 20:16:03

Band 66_3 MHz_High_16QAM_RB15#0




Date: 7.NOV.2021 20:16:21

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 7.NOV.2021 20:16:42

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 7.NOV.2021 20:16:59

Band 66_5 MHz_High_QPSK_RB25#0




Date: 8.NOV.2021 19:50:02

Band 66_5 MHz_High_16QAM_RB25#0




Date: 7.NOV.2021 20:17:35

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 7.NOV.2021 20:17:58

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 7.NOV.2021 20:18:21

Band 66_10 MHz_High_QPSK_RB50#0




Date: 7.NOV.2021 20:18:41

Band 66_10 MHz_High_16QAM_RB50#0




Date: 7.NOV.2021 20:19:01

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 8.NOV.2021 19:50:57

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 7.NOV.2021 20:19:52

Band 66_15 MHz_High_QPSK_RB75#0




Date: 7.NOV.2021 20:20:17

Band 66_15 MHz_High_16QAM_RB75#0




Date: 7.NOV.2021 20:20:42

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 7.NOV.2021 20:21:09

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 7.NOV.2021 20:21:34

Band 66_20 MHz_High_QPSK_RB100#0



Date: 7.NOV.2021 20:21:59

Band 66_20 MHz_High_16QAM_RB100#0



Date: 7.NOV.2021 20:22:23