



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 30.JUL.2021 20:35:55

### Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 30.JUL.2021 20:36:12

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 30.JUL.2021 20:36:30

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 30.JUL.2021 20:36:50

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 30.JUL.2021 20:37:09

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 30.JUL.2021 20:37:26

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 30.JUL.2021 20:37:43

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 30.JUL.2021 20:38:00

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 30.JUL.2021 20:38:19

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 30.JUL.2021 20:38:36

### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 30.JUL.2021 20:39:00

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 30.JUL.2021 20:39:17

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 30.JUL.2021 20:39:39

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 30.JUL.2021 20:39:58

### Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 30.JUL.2021 20:40:17


### Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 30.JUL.2021 20:40:39




### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 30.JUL.2021 20:41:06

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 30.JUL.2021 20:41:29

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 30.JUL.2021 20:41:54

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 30.JUL.2021 20:42:17

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 30.JUL.2021 20:42:43

### Band 2\_20 MHz\_Low\_16QAM\_RB100#0




Date: 30.JUL.2021 20:43:07

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 30.JUL.2021 20:43:31

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 30.JUL.2021 20:43:55

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 30.JUL.2021 20:44:14

### Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 30.JUL.2021 20:44:31

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 30.JUL.2021 20:44:58

### Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 30.JUL.2021 20:45:21

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 30.JUL.2021 20:45:43

### Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 30.JUL.2021 20:46:00

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 30.JUL.2021 20:46:18


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 30.JUL.2021 20:46:35




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 30.JUL.2021 20:46:54

### Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 30.JUL.2021 20:47:11

### Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 30.JUL.2021 20:47:28

### Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 30.JUL.2021 20:47:45

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 30.JUL.2021 20:48:07

### Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 30.JUL.2021 20:48:29

### Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 30.JUL.2021 20:48:49

### Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 30.JUL.2021 20:49:08

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 30.JUL.2021 20:49:34

### Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 30.JUL.2021 20:49:58

### Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 30.JUL.2021 20:50:22

### Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 30.JUL.2021 20:50:46

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 30.JUL.2021 20:51:12

### Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 30.JUL.2021 20:51:36

### Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 30.JUL.2021 20:52:00


### Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 30.JUL.2021 20:52:24




### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 30.JUL.2021 20:52:49

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 30.JUL.2021 20:53:09

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 30.JUL.2021 20:53:30

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 30.JUL.2021 20:53:46

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 30.JUL.2021 20:54:06

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 30.JUL.2021 20:54:26

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 30.JUL.2021 20:54:47

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 30.JUL.2021 20:55:03

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 30.JUL.2021 20:55:29

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 30.JUL.2021 20:55:49

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 30.JUL.2021 20:56:10

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 30.JUL.2021 20:56:30

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 30.JUL.2021 20:56:51

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 30.JUL.2021 20:57:11

### Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 30.JUL.2021 20:57:33


### Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 30.JUL.2021 20:57:56




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 30.JUL.2021 20:58:15

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 30.JUL.2021 20:58:35

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 30.JUL.2021 20:58:52

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 30.JUL.2021 20:59:12

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 30.JUL.2021 20:59:34

### Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 30.JUL.2021 20:59:53

### Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 30.JUL.2021 21:00:13

### Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 30.JUL.2021 21:00:32

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 30.JUL.2021 21:00:58

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 30.JUL.2021 21:01:22

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 30.JUL.2021 21:01:46

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 30.JUL.2021 21:02:09

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 30.JUL.2021 21:02:36

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 30.JUL.2021 21:02:59

### Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 30.JUL.2021 21:03:24


### Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 30.JUL.2021 21:03:50




### Band 17\_5 MHz\_Low\_QPSK\_RB25#0




Date: 1.AUG.2021 18:03:14

### Band 17\_5 MHz\_Low\_16QAM\_RB25#0




Date: 1.AUG.2021 18:04:09

### Band 17\_5 MHz\_High\_QPSK\_RB25#0




Date: 1.AUG.2021 18:04:50

### Band 17\_5 MHz\_High\_16QAM\_RB25#0




Date: 1.AUG.2021 18:05:14

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0




Date: 30.JUL.2021 21:05:35

### Band 17\_10 MHz\_Low\_16QAM\_RB50#0




Date: 30.JUL.2021 21:05:54

### Band 17\_10 MHz\_High\_QPSK\_RB50#0




Date: 30.JUL.2021 21:06:14

### Band 17\_10 MHz\_High\_16QAM\_RB50#0




Date: 30.JUL.2021 21:06:33

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0




Date: 30.JUL.2021 23:27:16

### Band 38\_5 MHz\_Low\_16QAM\_RB25#0




Date: 30.JUL.2021 23:27:36

### Band 38\_5 MHz\_High\_QPSK\_RB25#0




Date: 30.JUL.2021 23:27:57

### Band 38\_5 MHz\_High\_16QAM\_RB25#0




Date: 30.JUL.2021 23:28:20

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0




Date: 30.JUL.2021 23:28:51

### Band 38\_10 MHz\_Low\_16QAM\_RB50#0




Date: 30.JUL.2021 23:29:13

### Band 38\_10 MHz\_High\_QPSK\_RB50#0



Date: 30.JUL.2021 23:29:36


### Band 38\_10 MHz\_High\_16QAM\_RB50#0



Date: 30.JUL.2021 23:29:58




### Band 38\_15 MHz\_Low\_QPSK\_RB75#0




Date: 30.JUL.2021 23:30:33

### Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 30.JUL.2021 23:31:03

### Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 30.JUL.2021 23:31:30

### Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 30.JUL.2021 23:31:57

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0




Date: 30.JUL.2021 23:32:26

### Band 38\_20 MHz\_Low\_16QAM\_RB100#0




Date: 30.JUL.2021 23:32:53

### Band 38\_20 MHz\_High\_QPSK\_RB100#0




Date: 30.JUL.2021 23:33:20

### Band 38\_20 MHz\_High\_16QAM\_RB100#0




Date: 30.JUL.2021 23:33:49

### Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 30.JUL.2021 23:34:15

### Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 30.JUL.2021 23:34:41

### Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 30.JUL.2021 23:35:02

### Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 30.JUL.2021 23:35:25

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 30.JUL.2021 23:35:49

### Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 30.JUL.2021 23:36:12

### Band 41\_10 MHz\_High\_QPSK\_RB50#0



Date: 30.JUL.2021 23:36:34


### Band 41\_10 MHz\_High\_16QAM\_RB50#0



Date: 30.JUL.2021 23:36:56




### Band 41\_15 MHz\_Low\_QPSK\_RB75#0




Date: 30.JUL.2021 23:37:29

### Band 41\_15 MHz\_Low\_16QAM\_RB75#0




Date: 30.JUL.2021 23:37:59

### Band 41\_15 MHz\_High\_QPSK\_RB75#0




Date: 30.JUL.2021 23:38:32

### Band 41\_15 MHz\_High\_16QAM\_RB75#0




Date: 30.JUL.2021 23:38:59

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0




Date: 30.JUL.2021 23:39:31

### Band 41\_20 MHz\_Low\_16QAM\_RB100#0




Date: 30.JUL.2021 23:39:58

### Band 41\_20 MHz\_High\_QPSK\_RB100#0




Date: 30.JUL.2021 23:40:25

### Band 41\_20 MHz\_High\_16QAM\_RB100#0




Date: 30.JUL.2021 23:40:55

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 31.JUL.2021 00:53:16

### Band 66\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 31.JUL.2021 00:17:23

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 31.JUL.2021 00:17:40

### Band 66\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 31.JUL.2021 00:18:00

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0




Date: 31.JUL.2021 00:18:19

### Band 66\_3 MHz\_Low\_16QAM\_RB15#0




Date: 31.JUL.2021 00:18:36

### Band 66\_3 MHz\_High\_QPSK\_RB15#0



Date: 31.JUL.2021 00:18:57


### Band 66\_3 MHz\_High\_16QAM\_RB15#0



Date: 31.JUL.2021 00:19:14




### Band 66\_5 MHz\_Low\_QPSK\_RB25#0




Date: 31.JUL.2021 00:19:33

### Band 66\_5 MHz\_Low\_16QAM\_RB25#0




Date: 31.JUL.2021 00:19:50

### Band 66\_5 MHz\_High\_QPSK\_RB25#0




Date: 31.JUL.2021 00:20:08

### Band 66\_5 MHz\_High\_16QAM\_RB25#0




Date: 31.JUL.2021 00:20:25

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0




Date: 31.JUL.2021 00:20:48

### Band 66\_10 MHz\_Low\_16QAM\_RB50#0




Date: 31.JUL.2021 00:21:07

### Band 66\_10 MHz\_High\_QPSK\_RB50#0




Date: 31.JUL.2021 00:21:30

### Band 66\_10 MHz\_High\_16QAM\_RB50#0




Date: 31.JUL.2021 00:21:49

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0




Date: 31.JUL.2021 00:22:16

### Band 66\_15 MHz\_Low\_16QAM\_RB75#0




Date: 31.JUL.2021 00:22:39

### Band 66\_15 MHz\_High\_QPSK\_RB75#0




Date: 31.JUL.2021 00:23:03

### Band 66\_15 MHz\_High\_16QAM\_RB75#0




Date: 31.JUL.2021 00:23:27

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0




Date: 31.JUL.2021 00:23:53

### Band 66\_20 MHz\_Low\_16QAM\_RB100#0




Date: 31.JUL.2021 00:24:17

### Band 66\_20 MHz\_High\_QPSK\_RB100#0



Date: 31.JUL.2021 00:24:41

### Band 66\_20 MHz\_High\_16QAM\_RB100#0



Date: 31.JUL.2021 00:25:05