



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 21.DEC.2022 10:06:30

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 21.DEC.2022 10:06:49

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 21.DEC.2022 10:07:07

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 21.DEC.2022 10:07:22

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 21.DEC.2022 10:07:40

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 21.DEC.2022 10:07:58

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 21.DEC.2022 10:08:57

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 21.DEC.2022 10:09:12

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 21.DEC.2022 10:09:30

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 21.DEC.2022 10:09:49

Band 2_3 MHz_High_QPSK_RB15#0




Date: 21.DEC.2022 10:10:07

Band 2_3 MHz_High_16QAM_RB15#0




Date: 21.DEC.2022 10:10:25

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 21.DEC.2022 10:11:27

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 21.DEC.2022 10:11:46

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 21.DEC.2022 10:12:02

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 21.DEC.2022 10:12:21

Band 2_5 MHz_High_QPSK_RB25#0




Date: 21.DEC.2022 10:12:40

Band 2_5 MHz_High_16QAM_RB25#0




Date: 21.DEC.2022 10:12:58

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 21.DEC.2022 10:16:07

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 21.DEC.2022 10:16:27

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 21.DEC.2022 10:16:43

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 21.DEC.2022 10:17:03

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 21.DEC.2022 10:19:05

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 21.DEC.2022 10:19:27

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 21.DEC.2022 10:19:49

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 21.DEC.2022 10:20:08

Band 2_15 MHz_High_QPSK_RB75#0




Date: 21.DEC.2022 10:20:27

Band 2_15 MHz_High_16QAM_RB75#0




Date: 21.DEC.2022 10:20:49

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 21.DEC.2022 10:22:07

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 21.DEC.2022 10:22:29

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 21.DEC.2022 10:22:52

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 21.DEC.2022 10:23:11

Band 2_20 MHz_High_QPSK_RB100#0




Date: 21.DEC.2022 10:23:34

Band 2_20 MHz_High_16QAM_RB100#0




Date: 21.DEC.2022 10:23:56

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 21.DEC.2022 10:24:17

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 21.DEC.2022 10:24:32

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 21.DEC.2022 10:24:47

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 21.DEC.2022 10:25:05

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 21.DEC.2022 10:25:24

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 21.DEC.2022 10:25:42

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 21.DEC.2022 10:26:39

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 21.DEC.2022 10:26:57

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 21.DEC.2022 10:27:12

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 21.DEC.2022 10:27:27

Band 4_3 MHz_High_QPSK_RB15#0




Date: 21.DEC.2022 10:27:46

Band 4_3 MHz_High_16QAM_RB15#0




Date: 21.DEC.2022 10:28:01

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 21.DEC.2022 10:29:07

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 21.DEC.2022 10:29:25

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 21.DEC.2022 10:29:48

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 21.DEC.2022 10:30:03

Band 4_5 MHz_High_QPSK_RB25#0




Date: 21.DEC.2022 10:30:22

Band 4_5 MHz_High_16QAM_RB25#0




Date: 21.DEC.2022 10:30:38

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 21.DEC.2022 10:32:22

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 21.DEC.2022 10:32:41

Band 4_10 MHz_High_QPSK_RB50#0




Date: 21.DEC.2022 10:33:01

Band 4_10 MHz_High_16QAM_RB50#0




Date: 21.DEC.2022 10:33:20

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 21.DEC.2022 10:34:47

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 21.DEC.2022 10:35:09

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 21.DEC.2022 10:35:31

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 21.DEC.2022 10:35:53

Band 4_15 MHz_High_QPSK_RB75#0




Date: 21.DEC.2022 10:36:16

Band 4_15 MHz_High_16QAM_RB75#0




Date: 21.DEC.2022 10:36:37

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 21.DEC.2022 10:37:35

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 21.DEC.2022 10:37:54

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 21.DEC.2022 10:38:17

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 21.DEC.2022 10:38:39

Band 4_20 MHz_High_QPSK_RB100#0




Date: 21.DEC.2022 10:39:02

Band 4_20 MHz_High_16QAM_RB100#0




Date: 21.DEC.2022 10:39:25

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 21.DEC.2022 10:39:49

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 21.DEC.2022 10:40:11

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 21.DEC.2022 10:40:30

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 21.DEC.2022 10:40:52

Band 7_5 MHz_High_QPSK_RB25#0




Date: 21.DEC.2022 10:41:11

Band 7_5 MHz_High_16QAM_RB25#0




Date: 21.DEC.2022 10:41:30

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 21.DEC.2022 10:42:57

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 21.DEC.2022 10:43:14

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 21.DEC.2022 10:43:34

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 21.DEC.2022 10:43:53

Band 7_10 MHz_High_QPSK_RB50#0




Date: 21.DEC.2022 10:44:13

Band 7_10 MHz_High_16QAM_RB50#0




Date: 21.DEC.2022 10:44:32

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 21.DEC.2022 10:45:34

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 21.DEC.2022 10:45:55

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 21.DEC.2022 10:46:18

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 21.DEC.2022 10:46:40

Band 7_15 MHz_High_QPSK_RB75#0




Date: 21.DEC.2022 10:47:02

Band 7_15 MHz_High_16QAM_RB75#0




Date: 21.DEC.2022 10:47:24

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 21.DEC.2022 10:49:15

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 21.DEC.2022 10:49:38

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 21.DEC.2022 10:50:04

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 21.DEC.2022 10:50:26

Band 7_20 MHz_High_QPSK_RB100#0




Date: 21.DEC.2022 10:50:49

Band 7_20 MHz_High_16QAM_RB100#0




Date: 21.DEC.2022 10:51:15

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 21.DEC.2022 10:51:36

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 21.DEC.2022 10:51:54

Band 66_1.4 MHz_Middle_QPSK_RB6#0




Date: 21.DEC.2022 10:52:09

Band 66_1.4 MHz_Middle_16QAM_RB6#0




Date: 21.DEC.2022 10:52:27

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 21.DEC.2022 10:52:42

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 21.DEC.2022 10:52:57

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 21.DEC.2022 10:53:40

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 21.DEC.2022 10:53:58

Band 66_3 MHz_Middle_QPSK_RB15#0




Date: 21.DEC.2022 10:54:14

Band 66_3 MHz_Middle_16QAM_RB15#0




Date: 21.DEC.2022 10:54:29

Band 66_3 MHz_High_QPSK_RB15#0




Date: 21.DEC.2022 10:54:48

Band 66_3 MHz_High_16QAM_RB15#0




Date: 21.DEC.2022 10:55:06

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 21.DEC.2022 10:55:50

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 21.DEC.2022 10:56:05

Band 66_5 MHz_Middle_QPSK_RB25#0




Date: 21.DEC.2022 10:56:24

Band 66_5 MHz_Middle_16QAM_RB25#0




Date: 21.DEC.2022 10:56:43

Band 66_5 MHz_High_QPSK_RB25#0




Date: 21.DEC.2022 10:57:02

Band 66_5 MHz_High_16QAM_RB25#0




Date: 21.DEC.2022 10:57:20

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 21.DEC.2022 10:58:05

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 21.DEC.2022 10:58:24

Band 66_10 MHz_Middle_QPSK_RB50#0




Date: 21.DEC.2022 10:58:44

Band 66_10 MHz_Middle_16QAM_RB50#0




Date: 21.DEC.2022 10:59:00

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 21.DEC.2022 11:00:26

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 21.DEC.2022 11:00:48

Band 66_15 MHz_Middle_QPSK_RB75#0




Date: 21.DEC.2022 11:01:11

Band 66_15 MHz_Middle_16QAM_RB75#0




Date: 21.DEC.2022 11:01:33

Band 66_15 MHz_High_QPSK_RB75#0




Date: 21.DEC.2022 11:01:55

Band 66_15 MHz_High_16QAM_RB75#0




Date: 21.DEC.2022 11:02:14

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 21.DEC.2022 11:02:58

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 21.DEC.2022 11:03:21

Band 66_20 MHz_Middle_QPSK_RB100#0




Date: 21.DEC.2022 11:03:41

Band 66_20 MHz_Middle_16QAM_RB100#0




Date: 21.DEC.2022 11:04:03

Band 66_20 MHz_High_QPSK_RB100#0




Date: 21.DEC.2022 11:04:26

Band 66_20 MHz_High_16QAM_RB100#0




Date: 21.DEC.2022 11:04:45

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 21.DEC.2022 14:45:39

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 21.DEC.2022 14:45:53

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 21.DEC.2022 14:46:12

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 21.DEC.2022 14:46:33

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 21.DEC.2022 14:46:48

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 21.DEC.2022 14:47:09

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 21.DEC.2022 14:47:59

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 21.DEC.2022 14:48:14

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 21.DEC.2022 14:48:32

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 21.DEC.2022 14:48:50

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 21.DEC.2022 14:50:10

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 21.DEC.2022 14:50:32

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 21.DEC.2022 14:50:57

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 21.DEC.2022 14:51:15

Band 5_5 MHz_High_QPSK_RB25#0




Date: 21.DEC.2022 14:51:38

Band 5_5 MHz_High_16QAM_RB25#0




Date: 21.DEC.2022 14:51:59

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 21.DEC.2022 14:53:01

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 21.DEC.2022 14:53:20

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 21.DEC.2022 14:53:40

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 21.DEC.2022 14:53:56

Band 5_10 MHz_High_QPSK_RB50#0




Date: 21.DEC.2022 14:54:18

Band 5_10 MHz_High_16QAM_RB50#0




Date: 21.DEC.2022 14:54:40

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 21.DEC.2022 14:55:05

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 21.DEC.2022 14:55:23

Band 17_5 MHz_Middle_QPSK_RB25#0




Date: 21.DEC.2022 14:55:42

Band 17_5 MHz_Middle_16QAM_RB25#0




Date: 21.DEC.2022 14:56:01

Band 17_5 MHz_High_QPSK_RB25#0




Date: 21.DEC.2022 14:56:20

Band 17_5 MHz_High_16QAM_RB25#0




Date: 21.DEC.2022 14:56:42

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 21.DEC.2022 14:57:26

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 21.DEC.2022 14:57:45

Band 17_10 MHz_Middle_QPSK_RB50#0




Date: 21.DEC.2022 14:58:05

Band 17_10 MHz_Middle_16QAM_RB50#0




Date: 21.DEC.2022 14:58:24

Band 17_10 MHz_High_QPSK_RB50#0




Date: 21.DEC.2022 14:58:44

Band 17_10 MHz_High_16QAM_RB50#0




Date: 21.DEC.2022 14:59:06

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 28.DEC.2022 23:14:19

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 28.DEC.2022 23:14:38

Band 12_1.4 MHz_Middle_QPSK_RB6#0




Date: 28.DEC.2022 23:14:56

Band 12_1.4 MHz_Middle_16QAM_RB6#0




Date: 28.DEC.2022 23:15:11

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 28.DEC.2022 23:15:25

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 28.DEC.2022 23:15:40

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 28.DEC.2022 23:16:23

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 28.DEC.2022 23:16:44

Band 12_3 MHz_Middle_QPSK_RB15#0




Date: 28.DEC.2022 23:16:59

Band 12_3 MHz_Middle_16QAM_RB15#0




Date: 28.DEC.2022 23:17:13

Band 12_3 MHz_High_QPSK_RB15#0




Date: 28.DEC.2022 23:17:28

Band 12_3 MHz_High_16QAM_RB15#0




Date: 28.DEC.2022 23:17:55

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 28.DEC.2022 23:18:38

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 28.DEC.2022 23:18:59

Band 12_5 MHz_Middle_QPSK_RB25#0




Date: 28.DEC.2022 23:19:18

Band 12_5 MHz_Middle_16QAM_RB25#0




Date: 28.DEC.2022 23:19:35

Band 12_5 MHz_High_QPSK_RB25#0




Date: 28.DEC.2022 23:19:57

Band 12_5 MHz_High_16QAM_RB25#0




Date: 28.DEC.2022 23:20:15

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 28.DEC.2022 23:20:58

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 28.DEC.2022 23:21:16

Band 12_10 MHz_Middle_QPSK_RB50#0




Date: 28.DEC.2022 23:21:34

Band 12_10 MHz_Middle_16QAM_RB50#0




Date: 28.DEC.2022 23:21:49

Band 12_10 MHz_High_QPSK_RB50#0




Date: 28.DEC.2022 23:22:11

Band 12_10 MHz_High_16QAM_RB50#0




Date: 28.DEC.2022 23:22:25

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 26.DEC.2022 10:10:33

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 26.DEC.2022 10:10:58

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 26.DEC.2022 10:11:24

Band 38_5 MHz_Middle_16QAM_RB25#0




Date: 26.DEC.2022 10:11:58

Band 38_5 MHz_High_QPSK_RB25#0




Date: 26.DEC.2022 10:12:24

Band 38_5 MHz_High_16QAM_RB25#0




Date: 26.DEC.2022 10:12:49

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 26.DEC.2022 10:13:50

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 26.DEC.2022 10:14:09

Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 26.DEC.2022 10:14:29

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 26.DEC.2022 10:14:51

Band 38_10 MHz_High_QPSK_RB50#0




Date: 26.DEC.2022 10:15:14

Band 38_10 MHz_High_16QAM_RB50#0




Date: 26.DEC.2022 10:15:43

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 26.DEC.2022 10:16:51

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 26.DEC.2022 10:17:30

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 26.DEC.2022 10:17:59

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 26.DEC.2022 10:18:27

Band 38_15 MHz_High_QPSK_RB75#0




Date: 26.DEC.2022 10:18:53

Band 38_15 MHz_High_16QAM_RB75#0




Date: 26.DEC.2022 10:19:24

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 26.DEC.2022 10:20:23

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 26.DEC.2022 10:20:54

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 26.DEC.2022 10:21:17

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 26.DEC.2022 10:21:39

Band 38_20 MHz_High_QPSK_RB100#0




Date: 26.DEC.2022 10:22:05

Band 38_20 MHz_High_16QAM_RB100#0




Date: 26.DEC.2022 10:22:31

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 26.DEC.2022 09:46:17

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 3.JAN.2023 22:49:36

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 3.JAN.2023 22:54:59

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 3.JAN.2023 23:09:28

Band 41_5 MHz_High_QPSK_RB25#0




Date: 26.DEC.2022 09:47:56

Band 41_5 MHz_High_16QAM_RB25#0




Date: 26.DEC.2022 09:48:18

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 26.DEC.2022 09:48:42

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 26.DEC.2022 09:49:05

Band 41_10 MHz_High_QPSK_RB50#0




Date: 26.DEC.2022 09:50:13

Band 41_10 MHz_High_16QAM_RB50#0




Date: 26.DEC.2022 09:50:32

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 26.DEC.2022 09:50:56

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 26.DEC.2022 09:51:21

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 26.DEC.2022 09:51:44

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 26.DEC.2022 09:52:06

Band 41_15 MHz_High_QPSK_RB75#0




Date: 26.DEC.2022 09:52:38

Band 41_15 MHz_High_16QAM_RB75#0




Date: 3.JAN.2023 23:47:25

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 26.DEC.2022 09:53:37

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 26.DEC.2022 09:54:06

Band 41_20 MHz_High_QPSK_RB100#0



Date: 26.DEC.2022 09:55:27

Band 41_20 MHz_High_16QAM_RB100#0



Date: 26.DEC.2022 09:55:55