



2\_3MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 14:47:16

2\_3MHz\_Low\_16QAM\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 14:46:41

2\_3MHz\_High\_QPSK\_1@14




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 14:48:36

2\_3MHz\_High\_QPSK\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 14:48:01

2\_3MHz\_High\_16QAM\_1@14




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:21:04

2\_3MHz\_High\_16QAM\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:20:19

2\_5MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:24:52

2\_5MHz\_Low\_QPSK\_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:21:58

2\_5MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:26:10

2\_5MHz\_Low\_16QAM\_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:25:31

2\_5MHz\_High\_QPSK\_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:27:38

2\_5MHz\_High\_QPSK\_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:26:59

2\_5MHz\_High\_16QAM\_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:28:57

2\_5MHz\_High\_16QAM\_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:28:17

2\_10MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:30:49

2\_10MHz\_Low\_QPSK\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:29:59

2\_10MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:32:29

2\_10MHz\_Low\_16QAM\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:31:39

2\_10MHz\_High\_QPSK\_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:34:26

2\_10MHz\_High\_QPSK\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 4.JUL.2024 16:11:23

2\_10MHz\_High\_16QAM\_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:36:06

2\_10MHz\_High\_16QAM\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:35:15

2\_15MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:38:20

2\_15MHz\_Low\_QPSK\_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:37:120

2\_15MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:40:22

2\_15MHz\_Low\_16QAM\_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:39:21

2\_15MHz\_High\_QPSK\_1@74




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:45:03

2\_15MHz\_High\_QPSK\_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 4.JUL.2024 16:19:41

2\_15MHz\_High\_16QAM\_1@74



ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:47:07

2\_15MHz\_High\_16QAM\_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 16:46:05

FCC Part 24E


B2, Normal

1.4MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:45:14

1.4MHz\_Low\_QPSK\_6@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:45:10

1.4MHz\_Low\_16QAM\_1@0



ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:46:17

1.4MHz\_Low\_16QAM\_6@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:45:55

1.4MHz\_High\_QPSK\_1@5




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:47:13

1.4MHz\_High\_QPSK\_6@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:46:51

1.4MHz\_High\_16QAM\_1@5




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:47:55

1.4MHz\_High\_16QAM\_6@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:47:35

3MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:48:53

3MHz\_Low\_QPSK\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:48:32

3MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:49:37

3MHz\_Low\_16QAM\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:49:15

3MHz\_High\_QPSK\_1@14




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:50:31

3MHz\_High\_QPSK\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:50:10

3MHz\_High\_16QAM\_1@14




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:51:14

3MHz\_High\_16QAM\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:50:53

5MHz\_Low\_QPSK\_1@0



ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:52:16


5MHz\_Low\_QPSK\_25@0



ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:51:53




5MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:53:02

5MHz\_Low\_16QAM\_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:52:19

5MHz\_High\_QPSK\_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:54:00

5MHz\_High\_QPSK\_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:53:18

5MHz\_High\_16QAM\_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:54:47

5MHz\_High\_16QAM\_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:54:25

10MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:55:48

10MHz\_Low\_QPSK\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:55:25

10MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:56:34

10MHz\_Low\_16QAM\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:56:12

10MHz\_High\_QPSK\_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:57:32

10MHz\_High\_QPSK\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:57:10

10MHz\_High\_16QAM\_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:58:20

10MHz\_High\_16QAM\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:57:55

15MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:59:20

15MHz\_Low\_QPSK\_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:58:57

15MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:00:03

15MHz\_Low\_16QAM\_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 11:59:41

15MHz\_High\_QPSK\_1@74




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:01:01

15MHz\_High\_QPSK\_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:00:39

15MHz\_High\_16QAM\_1@74




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:01:48

15MHz\_High\_16QAM\_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:01:26

20MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:02:50

20MHz\_Low\_QPSK\_100@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:02:17

20MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:03:36

20MHz\_Low\_16QAM\_100@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:03:13

20MHz\_High\_QPSK\_1@99




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:04:36

20MHz\_High\_QPSK\_100@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:04:12

20MHz\_High\_16QAM\_1@99



ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:05:22

20MHz\_High\_16QAM\_100@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:05:00

FCC Part 27


B4, Normal

1.4MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28 JUN 2024 12:06:24

1.4MHz\_Low\_QPSK\_6@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28 JUN 2024 12:06:02

1.4MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28 JUN 2024 12:07:08

1.4MHz\_Low\_16QAM\_6@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28 JUN 2024 12:06:46

1.4MHz\_High\_QPSK\_1@5




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28 JUN 2024 12:08:04

1.4MHz\_High\_QPSK\_6@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28 JUN 2024 12:07:42

1.4MHz\_High\_16QAM\_1@5




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:09:48

1.4MHz\_High\_16QAM\_6@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:08:26

3MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:09:48

3MHz\_Low\_QPSK\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:09:26

3MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:10:31

3MHz\_Low\_16QAM\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:10:10

3MHz\_High\_QPSK\_1@14




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:11:28

3MHz\_High\_QPSK\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:11:06

3MHz\_High\_16QAM\_1@14




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:12:12

3MHz\_High\_16QAM\_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:11:49

5MHz\_Low\_QPSK\_1@0



ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:13:14


5MHz\_Low\_QPSK\_25@0



ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:12:50




5MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:14:02

5MHz\_Low\_16QAM\_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:13:38

5MHz\_High\_QPSK\_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:15:02

5MHz\_High\_QPSK\_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:14:38

5MHz\_High\_16QAM\_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:15:50

5MHz\_High\_16QAM\_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:15:25

10MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:16:55

10MHz\_Low\_QPSK\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:16:30

10MHz\_Low\_16QAM\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:17:44

10MHz\_Low\_16QAM\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:17:19

10MHz\_High\_QPSK\_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:23:22

10MHz\_High\_QPSK\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 30.JUN.2024 17:43:00

10MHz\_High\_16QAM\_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:24:08

10MHz\_High\_16QAM\_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:23:46

15MHz\_Low\_QPSK\_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:25:12

15MHz\_Low\_QPSK\_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:24:48

15MHz\_Low\_16QAM\_1@0



ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:26:00

15MHz\_Low\_16QAM\_75@0



ProjectNo.:2402U82788E-RF Tester:Karl Liang  
Date: 28.JUN.2024 12:25:36