




n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB38@0 13.577MHz




n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB38@0 13.574MHz




n41\_15MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB38@0 13.528MHz




n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 18.100MHz




n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB50@0 18.022MHz




n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 18.020MHz




n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 18.031MHz




n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 18.017MHz




n41\_20MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB51@0 18.174MHz




n41\_20MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB51@0 18.178MHz




n41\_20MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB51@0 18.180MHz




n41\_20MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB51@0 18.181MHz




n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 27.609MHz




n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB75@0 27.537MHz




n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 27.736MHz




n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 27.628MHz




n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 27.535MHz




n41\_30MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB78@0 27.859MHz




n41\_30MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB78@0 27.777MHz




n41\_30MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB78@0 27.749MHz



n41\_30MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB78@0 27.768MHz




n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM π/2  
BPSK\_RB100@0 37.647MHz




n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.604MHz




n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.286MHz




n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB100@0 37.169MHz




n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB100@0 37.318MHz




n41\_40MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB106@0 37.808MHz



n41\_40MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB106@0 37.815MHz



n41\_40MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB106@0 37.817MHz



n41\_40MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB106@0 37.786MHz

