




n66\_30MHz\_15kHz\_1745MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB160@0 28.565MHz




n66\_30MHz\_15kHz\_1745MHz\_DFT-s-OFDM  
QPSK\_RB160@0 28.497MHz




n66\_30MHz\_15kHz\_1745MHz\_DFT-s-OFDM 16  
QAM\_RB160@0 28.465MHz




n66\_30MHz\_15kHz\_1745MHz\_DFT-s-OFDM 64  
QAM\_RB160@0 28.565MHz




n66\_30MHz\_15kHz\_1745MHz\_DFT-s-OFDM 256  
QAM\_RB160@0 28.492MHz




n66\_30MHz\_15kHz\_1745MHz\_CP-OFDM  
QPSK\_RB160@0 28.567MHz




n66\_30MHz\_15kHz\_1745MHz\_CP-OFDM 16  
QAM\_RB160@0 28.469MHz




n66\_30MHz\_15kHz\_1745MHz\_CP-OFDM 64  
QAM\_RB160@0 28.473MHz




n66\_30MHz\_15kHz\_1745MHz\_CP-OFDM 256  
QAM\_RB160@0 28.484MHz




n66\_40MHz\_15kHz\_1745MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB216@0 38.594MHz




n66\_40MHz\_15kHz\_1745MHz\_DFT-s-OFDM  
QPSK\_RB216@0 38.460MHz




n66\_40MHz\_15kHz\_1745MHz\_DFT-s-OFDM 16  
QAM\_RB216@0 38.425MHz




n66\_40MHz\_15kHz\_1745MHz\_DFT-s-OFDM 64  
QAM\_RB216@0 38.476MHz




n66\_40MHz\_15kHz\_1745MHz\_DFT-s-OFDM 256  
QAM\_RB216@0 38.433MHz



n66\_40MHz\_15kHz\_1745MHz\_CP-OFDM  
QPSK\_RB216@0 38.446MHz



n66\_40MHz\_15kHz\_1745MHz\_CP-OFDM 16  
QAM\_RB216@0 38.408MHz



n66\_40MHz\_15kHz\_1745MHz\_CP-OFDM 64  
QAM\_RB216@0 38.463MHz




n66\_40MHz\_15kHz\_1745MHz\_CP-OFDM 256  
QAM\_RB216@0 38.442MHz




n77\_1


n77\_1\_10MHz\_30kHz\_3500MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB24@0 8.569MHz




n77\_1\_10MHz\_30kHz\_3500MHz\_DFT-s-OFDM  
QPSK\_RB24@0 8.561MHz




n77\_1\_10MHz\_30kHz\_3500MHz\_DFT-s-OFDM 16  
QAM\_RB24@0 8.573MHz




n77\_1\_10MHz\_30kHz\_3500MHz\_DFT-s-OFDM 64  
QAM\_RB24@0 8.536MHz




n77\_1\_10MHz\_30kHz\_3500MHz\_DFT-s-OFDM 256  
QAM\_RB24@0 8.567MHz




n77\_1\_10MHz\_30kHz\_3500MHz\_CP-OFDM  
QPSK\_RB24@0 8.574MHz




n77\_1\_10MHz\_30kHz\_3500MHz\_CP-OFDM 16  
QAM\_RB24@0 8.572MHz




n77\_1\_10MHz\_30kHz\_3500MHz\_CP-OFDM 64  
QAM\_RB24@0 8.570MHz




n77\_1\_10MHz\_30kHz\_3500MHz\_CP-OFDM 256  
QAM\_RB24@0 8.611MHz



n77\_1\_15MHz\_30kHz\_3500MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB36@0 13.447MHz



n77\_1\_15MHz\_30kHz\_3500MHz\_DFT-s-OFDM  
QPSK\_RB36@0 13.459MHz



n77\_1\_15MHz\_30kHz\_3500MHz\_DFT-s-OFDM 16  
QAM\_RB36@0 13.522MHz

