




n77\_1\_15MHz\_30kHz\_3500MHz\_DFT-s-OFDM 64  
QAM\_RB36@0 13.456MHz




n77\_1\_15MHz\_30kHz\_3500MHz\_DFT-s-OFDM 256  
QAM\_RB36@0 13.467MHz




n77\_1\_15MHz\_30kHz\_3500MHz\_CP-OFDM  
QPSK\_RB38@0 13.568MHz




n77\_1\_15MHz\_30kHz\_3500MHz\_CP-OFDM 16  
QAM\_RB38@0 13.577MHz




n77\_1\_15MHz\_30kHz\_3500MHz\_CP-OFDM 64  
QAM\_RB38@0 13.574MHz




n77\_1\_15MHz\_30kHz\_3500MHz\_CP-OFDM 256  
QAM\_RB38@0 13.527MHz




n77\_1\_20MHz\_30kHz\_3500MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 18.080MHz




n77\_1\_20MHz\_30kHz\_3500MHz\_DFT-s-OFDM  
QPSK\_RB50@0 18.100MHz




n77\_1\_20MHz\_30kHz\_3500MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 18.103MHz




n77\_1\_20MHz\_30kHz\_3500MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 18.032MHz




n77\_1\_20MHz\_30kHz\_3500MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 18.015MHz




n77\_1\_20MHz\_30kHz\_3500MHz\_CP-OFDM  
QPSK\_RB51@0 18.177MHz




n77\_1\_20MHz\_30kHz\_3500MHz\_CP-OFDM 16  
QAM\_RB51@0 18.172MHz




n77\_1\_20MHz\_30kHz\_3500MHz\_CP-OFDM 64  
QAM\_RB51@0 18.178MHz




n77\_1\_20MHz\_30kHz\_3500MHz\_CP-OFDM 256  
QAM\_RB51@0 18.186MHz




n77\_1\_30MHz\_30kHz\_3500MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 27.634MHz




n77\_1\_30MHz\_30kHz\_3500MHz\_DFT-s-OFDM  
QPSK\_RB75@0 27.600MHz




n77\_1\_30MHz\_30kHz\_3500MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 27.736MHz



n77\_1\_30MHz\_30kHz\_3500MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 27.722MHz




n77\_1\_30MHz\_30kHz\_3500MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 27.520MHz




n77\_1\_30MHz\_30kHz\_3500MHz\_CP-OFDM  
QPSK\_RB78@0 27.872MHz




n77\_1\_30MHz\_30kHz\_3500MHz\_CP-OFDM 16  
QAM\_RB78@0 27.770MHz




n77\_1\_30MHz\_30kHz\_3500MHz\_CP-OFDM 64  
QAM\_RB78@0 27.759MHz




n77\_1\_30MHz\_30kHz\_3500MHz\_CP-OFDM 256  
QAM\_RB78@0 27.763MHz




n77\_1\_40MHz\_30kHz\_3500MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB100@0 37.467MHz




n77\_1\_40MHz\_30kHz\_3500MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.601MHz




n77\_1\_40MHz\_30kHz\_3500MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.297MHz



n77\_1\_40MHz\_30kHz\_3500MHz\_DFT-s-OFDM 64  
QAM\_RB100@0 37.169MHz



n77\_1\_40MHz\_30kHz\_3500MHz\_DFT-s-OFDM 256  
QAM\_RB100@0 37.287MHz



n77\_1\_40MHz\_30kHz\_3500MHz\_CP-OFDM  
QPSK\_RB106@0 37.775MHz

