




n78\_2\_15MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB38@0 13.580MHz




n78\_2\_15MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB38@0 13.574MHz




n78\_2\_15MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB38@0 13.529MHz




n78\_2\_20MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 18.031MHz



n78\_2\_20MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB50@0 18.023MHz




n78\_2\_20MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 18.100MHz




n78\_2\_20MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 18.025MHz




n78\_2\_20MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 18.011MHz




n78\_2\_20MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB51@0 18.168MHz



n78\_2\_20MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB51@0 18.169MHz




n78\_2\_20MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB51@0 18.167MHz




n78\_2\_20MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB51@0 18.180MHz




n78\_2\_30MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 27.608MHz




n78\_2\_30MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB75@0 27.537MHz




n78\_2\_30MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 27.723MHz



n78\_2\_30MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 27.656MHz




n78\_2\_30MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 27.508MHz




n78\_2\_30MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB78@0 27.851MHz




n78\_2\_30MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB78@0 27.773MHz




n78\_2\_30MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB78@0 27.774MHz




n78\_2\_30MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB78@0 27.755MHz




n78\_2\_40MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB100@0 37.462MHz




n78\_2\_40MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.517MHz




n78\_2\_40MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.186MHz




n78\_2\_40MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB100@0 37.132MHz




n78\_2\_40MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB100@0 37.197MHz




n78\_2\_40MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB106@0 37.777MHz



n78\_2\_40MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB106@0 37.783MHz



n78\_2\_40MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB106@0 37.832MHz



n78\_2\_40MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB106@0 37.761MHz

