



n78\_2\_50MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB128@0 47.008MHz



n78\_2\_50MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB128@0 47.233MHz




n78\_2\_50MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB128@0 46.872MHz




n78\_2\_50MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB128@0 46.861MHz



n78\_2\_50MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB128@0 46.862MHz




n78\_2\_50MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB133@0 47.429MHz




n78\_2\_50MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB133@0 47.411MHz




n78\_2\_50MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB133@0 47.476MHz




n78\_2\_50MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB133@0 47.297MHz




n78\_2\_60MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB162@0 57.676MHz




n78\_2\_60MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB162@0 57.885MHz




n78\_2\_60MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB162@0 57.480MHz




n78\_2\_60MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB162@0 57.902MHz




n78\_2\_60MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB162@0 57.624MHz



n78\_2\_60MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB162@0 57.629MHz



n78\_2\_60MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB162@0 57.691MHz




n78\_2\_60MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB162@0 57.874MHz




n78\_2\_60MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB162@0 57.708MHz



n78\_2\_70MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB180@0 66.885MHz




n78\_2\_70MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB180@0 66.594MHz



n78\_2\_70MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB180@0 66.638MHz




n78\_2\_70MHz\_30kHz\_3625MHz\_DFT-s-OFDM 64  
QAM\_RB180@0 66.375MHz




n78\_2\_70MHz\_30kHz\_3625MHz\_DFT-s-OFDM 256  
QAM\_RB180@0 66.254MHz




n78\_2\_70MHz\_30kHz\_3625MHz\_CP-OFDM  
QPSK\_RB189@0 67.353MHz




n78\_2\_70MHz\_30kHz\_3625MHz\_CP-OFDM 16  
QAM\_RB189@0 67.526MHz




n78\_2\_70MHz\_30kHz\_3625MHz\_CP-OFDM 64  
QAM\_RB189@0 67.266MHz




n78\_2\_70MHz\_30kHz\_3625MHz\_CP-OFDM 256  
QAM\_RB189@0 67.335MHz



n78\_2\_80MHz\_30kHz\_3625MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB216@0 77.251MHz



n78\_2\_80MHz\_30kHz\_3625MHz\_DFT-s-OFDM  
QPSK\_RB216@0 76.855MHz



n78\_2\_80MHz\_30kHz\_3625MHz\_DFT-s-OFDM 16  
QAM\_RB216@0 76.837MHz

