




n77\_1\_90MHz\_30kHz\_3500MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB243@0 86.798MHz




n77\_1\_90MHz\_30kHz\_3500MHz\_DFT-s-OFDM  
QPSK\_RB243@0 86.832MHz




n77\_1\_90MHz\_30kHz\_3500MHz\_DFT-s-OFDM 16  
QAM\_RB243@0 86.505MHz




n77\_1\_90MHz\_30kHz\_3500MHz\_DFT-s-OFDM 64  
QAM\_RB243@0 86.773MHz




n77\_1\_90MHz\_30kHz\_3500MHz\_DFT-s-OFDM 256  
QAM\_RB243@0 86.492MHz




n77\_1\_90MHz\_30kHz\_3500MHz\_CP-OFDM  
QPSK\_RB245@0 87.190MHz




n77\_1\_90MHz\_30kHz\_3500MHz\_CP-OFDM 16  
QAM\_RB245@0 87.254MHz




n77\_1\_90MHz\_30kHz\_3500MHz\_CP-OFDM 64  
QAM\_RB245@0 87.229MHz




n77\_1\_90MHz\_30kHz\_3500MHz\_CP-OFDM 256  
QAM\_RB245@0 87.249MHz




n77\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB270@0 96.551MHz




n77\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM  
QPSK\_RB270@0 96.557MHz




n77\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM 16  
QAM\_RB270@0 96.158MHz




n77\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM 64  
QAM\_RB270@0 96.198MHz




n77\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM 256  
QAM\_RB270@0 96.138MHz




n77\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM  
QPSK\_RB273@0 97.375MHz




n77\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM 16  
QAM\_RB273@0 97.251MHz



n77\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM 64  
QAM\_RB273@0 97.266MHz




n77\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM 256  
QAM\_RB273@0 97.280MHz




n77\_3


n77\_3\_10MHz\_30kHz\_3840MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB24@0 8.564MHz




n77\_3\_10MHz\_30kHz\_3840MHz\_DFT-s-OFDM  
QPSK\_RB24@0 8.580MHz




n77\_3\_10MHz\_30kHz\_3840MHz\_DFT-s-OFDM 16  
QAM\_RB24@0 8.563MHz




n77\_3\_10MHz\_30kHz\_3840MHz\_DFT-s-OFDM 64  
QAM\_RB24@0 8.602MHz




n77\_3\_10MHz\_30kHz\_3840MHz\_DFT-s-OFDM 256  
QAM\_RB24@0 8.563MHz




n77\_3\_10MHz\_30kHz\_3840MHz\_CP-OFDM  
QPSK\_RB24@0 8.574MHz




n77\_3\_10MHz\_30kHz\_3840MHz\_CP-OFDM 16  
QAM\_RB24@0 8.575MHz




n77\_3\_10MHz\_30kHz\_3840MHz\_CP-OFDM 64  
QAM\_RB24@0 8.567MHz




n77\_3\_10MHz\_30kHz\_3840MHz\_CP-OFDM 256  
QAM\_RB24@0 8.608MHz



n77\_3\_15MHz\_30kHz\_3840MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB36@0 13.462MHz



n77\_3\_15MHz\_30kHz\_3840MHz\_DFT-s-OFDM  
QPSK\_RB36@0 13.441MHz



n77\_3\_15MHz\_30kHz\_3840MHz\_DFT-s-OFDM 16  
QAM\_RB36@0 13.518MHz

